MINERAL CREEK From Devil's Canyon		OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
to Gila River 15050100 – 012B	A&Ww – Impaired FBC – Inconclusive FC – Inconclusive AgL – Attaining	Category 5	Selenium, copper, and low dissolved oxygen	Adding low dissolved oxygen. Added selenium in 2004. Mine under a consent decree to mitigate copper pollution.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 01/10/2000 – 06/17/2005 NUMBER AND TYPES OF SAMPLES			
DATABASE #					
		Metals	Nutrients - Related	Other	
At Indian Gardens MGMIN008.81 103331	ASARCO Effectiveness monitoring	217-218 total and dissolved metals: Antimony, arsenic, beryllium, cadmium, chromium,	218 samples: Nitrite/nitrate, pH, dissolved oxygen	217 Fluoride 217 Total dissolved solids	
At tunnel inlet MGMIN006.99 103332	ASARCO Effectiveness monitoring	copper, lead, nickel, selenium silver, thallium, and zinc		217 Turbidity	
At tunnel outlet MGMIN003.69 103333	ASARCO Effectiveness monitoring				
At channel outlet MGMIN002.65 103334	ASARCO Effectiveness monitoring				
At Highway 177 bridge MGMIN001.38 100472	ASARCO Effectiveness monitoring				

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Only reviewed exceed	dances that occurred after extensive	e treatment initiated in 20	01.
Copper (dissolved)	8.0 µg/L at 58 mg/L hardness 6.7 µg/L at 48 mg/L hardness 9.1 µg/L at 66 mg/L hardness A&Ww acute	03/06/2003 – 12 μg/L 03/11/2004 – 17 μg/L 2/15/2005 – 20 μg/L	Remains Impaired – 3 exceedances during the last 3 years of monitoring. Copper exceedances occurred during high flows.
Dissolved oxygen	6.0 mg/L A&Ww	Too many to list here. Did not meet standards in 29 samples.	Impaired – Low dissolved oxygen in 29 of 218 samples (binomial). Cause of low dissolved oxygen is unknown, but may be due to natural conditions, such as groundwater upwelling.
Selenium	2.0 µg/L A&Ww chronic	35 sampling events – Too many to list here.	Remains Impaired – 35 exceedances during the assessment period. 28 were at or above 5 μ g/L.

DATA GAPS AND MC	DNITORING NEED	S	
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient <i>E. coli</i> and mercury to assess FBC and FC.		Lab detection limits for dissolved metals (cadmium, copper, lead, nickel, and silver) were higher than A&W chronic criteria in at least 7 samples.
MONITORING RECOMMEN	IDATIONS	High Priority -Collect selenium and dissolved oxygen samples to support TMDL development. Collect copper samples to determine effectiveness o treatment. Use lower detection limits for dissolved metals. Collect missing core parameters to represent at least 3 seasons during an assessment perior	

MINNEHAHA CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters Hassayampa Creek 15070103 029 12.7 Miles	A&Ww - Inconclusive FBC - Inconclusive FC - Inconclusive AgL - Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 03/05/2005				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
Near Hassayampa River MGMHA000.24 102955	ADEQ TMDL	1 total and dissolved metal sample: Antimony, arsenic, barium, beryllium, boron, cadmium, chromium, copper, manganese, mercury, silver, and zinc 1 total metals only: Lead and nickel	1 Dissolved oxygen and pH	1 Total dissolved solids		

EXCEEDANG	CL3		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

DATA GAPS AND MC	NITORING NEEDS			
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Insufficient core parameters	Insufficient monitoring events	Lab detection limits for selenium and dissolved metals (lead, mercury, nickel) were higher than A&Wc chronic criteria.	
MONITORING RECOMMENDATIONS		Low Priority -Collect additional core parameters to represent at least 3 seasons during an assessment period.		
		Use lower lab detection li	mits for selenium and dissolved metals.	

PAINTED ROCKS RESERVOIR	USE SUPPORT		OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
15070101 – 1020A 100 Acres (This is a flood retention basin)	ADEQ	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive AgI – Inconclusive AgL – Inconclusive	Category 3		
	E P A	FC – Impaired	Category 5	DDT, toxaphene, and chlordane in fish tissue.	DDT, toxaphene, and chlordane were listed by EPA in 2002.

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B and Appendix C).

MONITORING USED IN THIS ASSESSMENT						
No Current Data		Fish consumption advisory due to DDT, toxaphene, and chlordane in fish tissue				

DATA GAPS AND MONITORING NEEDS					
DISCUSSION OF PESTICIDE IMPAIRMENT	Evidence of potential pesticide impairment:				
MONITORING RECOMMENDATIONS	High Priority – Collect samples to support pesticide TMDL development.				

See also Painted Rock Lake assessment in the Colorado River - Lower Gila Watershed

PAPAGO PARK PONDS	USE SUPPORT	OVERALL ASSESSMENT	
15060106B - 1030 24 Acres	A&Ww – Inconclusive PBC – Inconclusive	Category 3	
	FC – Inconclusive	Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATES: 12/20/2002 and 04/17/2003				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
At dam MGPAP - A 101047	ADEQ Ambient	2 total and dissolved: Antimony, arsenic, barium, beryllium, boron, cadmium, copper, lead, mercury, manganese, nickel, selenium, silver, and zinc 2 total and 0-1 dissolved: Chromium	2 samples: Ammonia, total nitrogen, nitrite/nitrate, total phosphorus, total Kjeldahl nitrogen, dissolved oxygen, pH	2 <i>E. coli</i> bacteria 2 Fluoride 2 Turbidity		

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING	MISSING CORE	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
MORE SAMPLES TO ASSESS	PARAMETERS		
	Insufficient core	Insufficient sampling events	Lab detection limit for dissolved mercury was
	parameters.		higher than A&Ww chronic criterion.
MONITORING RECOMMENDATIONS		Low Priority -Collect missing during an assessment period.	core parameters to represent at least 3 seasons
		Use a lower lab detection lin	nit for dissolved mercury.

POTTS CANYON	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Queen Creek 15050100 – 1856 10.6 Miles	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 08/10/2005				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
Above Queen Creek MGPTC000.01 104438	ADEQ TMDL	1 total and dissolved: Cadmium, chromium, copper, mercury, and zinc	1 samples: Dissolved oxygen, and pH	1 Fluoride 1 Total dissolved solids 1 Suspended sediment concentration		
		1 total metals only: Arsenic, lead, manganese				

EXCEEDANCES	5		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Arsenic	50 μg/L FBC	08/10/2005 – 79 μg/L	Inconclusive – Only 1 sampling exceedance. (Binomial)
Copper (dissolved)	29.3 µg/L at >400 mg/L hardness A&Ww chronic	08/10/2005 – 49 μg/L	Inconclusive – Only 1 exceedance during the assessment period. Exceedance occurred during a summer storm and may not represent chronic (4-day average) conditions.
Lead	15 μg/L – FBC	08/10/2005 – 170 μg/L	Inconclusive – Only 1 exceedance. (Binomial)
Mercury	0.6 μg/L FC	08/10/2005 – 1.1 μg/L	Inconclusive – Only 1 exceedance (Binomial)
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Ww	08/10/2005 – 1859 mg/L	Inconclusive – Only 1 sampling date. Insufficient samples to assess, as need a minimum of 4 samples to calculate a geometric mean and compare to standard.

DATA GAPS AND MC	NITORING NEE	DS	
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Arsenic, copper, lead, mercury, and suspended sediment	Insufficient core parameters	Insufficient sampling events	Lab detection limits for selenium and dissolved mercury were higher that A&Ww chronic criteria.
MONITORING RECOMMENDATIONS		Recommend using biocriteria implementation procedures i	enic, copper, lead, mercury, and suspended oles due to exceedances. assessments and bottom deposits in this reach, when they are adopted. eters to represent at least 3 seasons during an relab detection limits for selenium and dissolved

QUEEN CREEK From headwaters to Superior	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
WWTP discharge 15050100 – 014A 8.8 Miles	A&We – Impaired PBC – Attaining AgL – Attaining	Category 5	Copper	Copper on list since 2002. TMDL being developed.

SITE NAMES ID #	AGENCY PURPOSE					
DATABASE #		Metals	Nutrients - Related	Other		
Headwaters MGQEN045.93 103091	ADEQ TMDL	11-26 total and dissolved: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, mercury, nickel, silver, thallium, and zinc 12 total and 4-5 dissolved: Barium, boron, selenium 26 total and 1 dissolved: Manganese	TMDL Antimony, arsenic, beryllium, Nitrite/nitrate	15-25 samples: Nitrite/nitrate, pH, dissolved oxygen	7 <i>E. coli</i> bacteria 13 Fluoride 15 Total dissolved solids	
Below Omya Pump Station Spring MGQEN044.42 103092	ADEQ TMDL and Resolution Cu Effectiveness			5 Suspended sediment concentration 13 Turbidity		
Above Oak Flat MGQEN041.74 103093	ADEQ TMDL					
Below Oak Flat MGQEN041.34 103094	ADEQ TMDL					
At boulder hole MGQEN040.17 103463	Resolution Copper Effectiveness					
Below Superior water tank MGQEN039.75 103564	ADEQ TMDL					
Magma Ave and Queen Creek MGQEN038.73 103095	ADEQ TMDL					
Below NPDES Permit discharge MGQEN037.09 103096	ADEQ TMDL					

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Copper (dissolved)	18.0 µg/L at 76 mg/L hardness 8.7 µg/L at 35 mg/L hardness A&We acute	12/29/2004 – 44 μg/L 08/10/2005 – 49 μg/L	Remains impaired – 2 exceedances during the last 3 years of monitoring. Exceedances are occurring at normal flows (0.6 cfs).		

DATA GAPS AND MC	NITORING NEEDS	5	
EXCEEDANCES NEEDING	MISSING CORE	MISSING SEASONAL	DETECTION LIMITS NOT LOW
MORE SAMPLES TO ASSESS	PARAMETERS	DISTRIBUTION	ENOUGH
	All core parameters were collected		
MONITORING RECOMMEN	DATIONS	High Priority -Collect copp	per samples to support TMDL development.

QUEEN CREEK From Superior WWTP discharge	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
to Potts Canyon	A&Wedw – Impaired PBC – Inconclusive	Category 5	Copper	Copper on 303(d) List since 2004. TMDL being developed

PURPOSE	SAMPLING DATE: 11/14/2003	2 – 08/30/2005	
	NUMBER AND TYPES OF SA	MPLES	
	Metals	Nutrients - Related	Other
ADEQ Ambient and TMDL	4-7 total and dissolved: Antimony, arsenic, beryllium cadmium, chromium, copper, and zinc	4-7 samples: Ammonia, total nitrogen, nitrite/nitrate, total phosphorus,	4 E. coli bacteria 6 Fluoride 4 Total dissolved solids 5 Suspended sediment
ADEQ TMDL	5-7 total and 0-2 dissolved: Boron, lead, manganese, and mercury	nitrite/nitrate, pH, dissolved oxygen	concentration 4 Turbidity 2 Chlorine
	Ambient and TMDL	Metals ADEQ Ambient and TMDL ADEQ Antimony, arsenic, beryllium cadmium, chromium, copper, and zinc ADEQ TMDL 5-7 total and 0-2 dissolved: Boron, lead, manganese, and	ADEQ Ambient and TMDL Antimony, arsenic, beryllium cadmium, chromium, copper, and zinc ADEQ TMDL 5-7 total and 0-2 dissolved: Boron, lead, manganese, and mercury 4-7 samples: Ammonia, total nitrogen, nitrite/nitrate, total phosphorus, nitrite/nitrate, pH, dissolved oxygen

POLLUTANT	STANDARD	DATES	DESIGNATED USE SUPPORT
	UNIT DESIGNATED USES	EXCEEDANCES	SUPPORTING EVIDENCE AND COMMENTS
Chlorine	11 μg/L A&Wedw acute	03/31/2003 – 90 μg/L	Inconclusive – Only 1 exceedance in 2 samples.
Copper (dissolved)	49.6 µg/L at >400 mg/L hardness A&Wedw acute	11/14/2002 – 50 μg/L	Remains impaired – 1 exceedance during the last 3 years of monitoring.
Copper (dissolved)	29.3 µg/L at >400 mg/L hardness 29.3 µg/L at >400 mg/L hardness 23.5 µg/L at 310 mg/L hardness A&Wedw chronic	11/14/2002 – 50 µg/L 01/13/2003 – 37 µg/L 08/10/2005 – 33 µg/L	Remains impaired – 1 of these 3 exceedances (33 μ g/L) was during an elevated flow (2.3 cfs), so may not represent chronic conditions (4 day exposure). Therefore, 2 exceedances in a 3-year period.
Dissolved oxygen	3.0 mg/L (daytime) A&Wedw	05/19/2003 – 1.6 mg/L	Inconclusive – Only 1 exceedance in 7 samples. (Binomial) (Note: sample was collected at 11 am.)
Selenium	2.0 µg/L A&Wedw chronic	11/14/2002 – 5.8 μg/L	Inconclusive – Only 1 exceedance in the last 3 years of monitoring. (See note below about lab detection limits)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Chlorine, dissolved oxygen, and selenium	Collected all core parameters		Lab detection limit for selenium and dissolved mercury were higher than A&Wedw chronic criteria in 1 or more samples.
MONITORING RECOMMEN	IDATIONS	High Priority -Collect copp	per samples to support TMDL development.
		Collect chlorine, dissolved exceedances.	oxygen, and selenium samples due to
		Use lower detection limit f	or selenium and dissolved mercury.

QUEEN CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From Potts Canyon to Whitlow Canyon 15050100 – 014C 8.0 Miles	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive AgL – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 08/10/2005	5	
DATABASE #		NUMBER AND TYPES OF SAM	APLES	
		Metals	Nutrients - Related	Other
Queens Station MGQEN030.06 103098	ADEQ TMDL	1 total and dissolved: Cadmium, chromium, copper, mercury, and zinc	1 samples: Dissolved oxygen, and pH	1 Fluoride 1 Total dissolved solid: 1 Suspended sediment concentration
		1 total metals only: Arsenic, lead, manganese		

POLLUTANT	STANDARD	DATES	DESIGNATED USE SUPPORT
	UNIT DESIGNATED USES	EXCEEDANCES	SUPPORTING EVIDENCE AND COMMENTS
Arsenic	50 μg/L FBC	08/10/2005 – 52 μg/L	Inconclusive – Only 1 sampling exceedance. (Binomial)
Copper (dissolved)	24.6 µg/L at 190 mg/L hardness A&Ww acute	08/10/2005 – 39 μg/L	Inconclusive – Only 1 exceedance in 3-year period.
Mercury	0.6 μg/L FC	08/10/2005 – 1.1 μg/L	Inconclusive – Only 1 exceedance. (Binomial)
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Ww	08/10/2005 – 88 mg/L	Inconclusive – Although sample was marginally above the 80 mg/L criterion, there were insufficient samples to assess, as need a minimum of 4 samples to calculate a geometric mean and compare to standard. Also, the sample was collected during a monsoon rain event, so would not be included in the geometric mean calculation.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Arsenic, copper, mercury, and suspended sediment	Insufficient core parameters	Insufficient sampling events	Lab detection limits for selenium and dissolved mercury were higher that A&Ww chronic criteria.
MONITORING RECOMMEN	IDATIONS	Recommend using biocriteria implementation procedures i	enic, copper, mercury, and suspended sediment o exceedances. a assessments and bottom deposits n this reach, when they are adopted. eters to represent at least 3 seasons during an r lab detection limits for selenium and dissolved

SALT RIVER	USE SUPPORT	OVERALL ASSESSMENT
From Granite Reef Dam for 2 kilometers 15060106B-001A 1.6 Miles	A&Ww - Inconclusive FBC - Inconclusive FC - Inconclusive DWS - Inconclusive Agl - Inconclusive AgL - Attaining	Category 2 Attaining some uses

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 07/19/2002	2 – 12/04/2003		
DATABASE #	100	NUMBER AND TYPES OF SAMP	APLES		
		Metals	Nutrients - Related	Other	
At Granite Reef diversion dam MGSLR041.57 102769	AGFD Ambient	3-4 total metals only: Arsenic, barium, cadmium, chromium, copper, lead, manganese, selenium, and zinc	5-7 samples: Ammonia, total nitrogen, nitrite/nitrate, total phosphorus, total Kjeldahl nitrogen, dissolved oxygen, pH	6 Total dissolved solids 2 Turbidity	

EXCEEDAN	STANDARD UNIT DESIGNATED USES 50 µg/L FBC, DWS 2000 µg/L DWS 100 µg/L FBC, DWS		
POLLUTANT	UNIT	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Arsenic		07/19/2002 – 148 μg/L*	Inconclusive — Only 1 exceedance in 4 samples. (Binomial requires a minimum of 5 exceedances and 20 samples to assess as impaired.) "This exceedance may be related to the Rodeo-Chediski fire (June 18th through July 7th) which led to increased flow in Salt River during the 2002 monsoon season.
Barium	. 0	07/19/2002 – 2780 μg/L*	Inconclusive – Only 1 exceedance in 4 samples. (Binomial) *See note above.
Chromium		07/19/2002 – 184 μg/L*	Inconclusive – Only 1 exceedance in 4 samples. (Binomial) *See note above.
Lead	15 μg/L FBC, DWS	07/19/2002 – 234 μg/L° 07/31/2002 – 44 μg/L°	Inconclusive – 2 exceedances in 4 samples. (Binomial) "See note above.
Manganese	980 μg/L DWS	07/19/2002 – 7640 μg/L* 07/31/2002 – 1960 μg/L*	Inconclusive – 2 exceedances in 5 samples. (Binomial) "See note above.
Nickel	140 μg/L DWS	07/19/2002 – 218 μg/L*	Inconclusive – Only 1 exceedance in 4 samples. (Binomial) *See note above.

DATA GAPS AND MC	DNITOKING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Chromium and lead	Insufficient dissolved metals (cadmium, copper, and zinc), E. coli bacteria, mercury, fluoride, and boron to assess A&WW, FBC, FC, DWS, AgI.		
MONITORING RECOMMEN	IDATIONS		nromium and lead due to exceedances. epresent at least 3 seasons during an

LT RIVER	USE SUPPORT	OVERALL ASSESSMENT	
om 2 kilometers below Granite ef Dam to Interstate 10 bridge 060106B-001B Miles	A&We - Inconclusive PBC - Inconclusive	Category 3 Inconclusive	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 01/12/2005 – 01/21/2005 NUMBER AND TYPES OF SAMPLES				
DATABASE #						
		Metals	Nutrients – Related	Other		
At Priest Drive USGS #09512165 MGSLR022.76 101493	AGFD Ambient	2 total metals only: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, mercury, and zinc 2 total metals only: Boron, manganese, and selenium	2 samples: Ammonia, total nitrogen, nitrite/nitrate, total phosphorus, total Kjeldahl nitrogen, dissolved oxygen, pH	2 <i>E. coli</i> bacteria 2 Fluoride 2 Total dissolved solids 2 Turbidity		

EXCEEDANG	CE3		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events.	
MONITORING RECOMMENDATIONS		Low Priority – Collect sufficient core parameters to represent at least seasons during an assessment period.	

SALT RIVER	USE SUPPORT	OVERALL ASSESSMENT	
From Interstate 10 bridge to 23 rd Avenue WWTP discharge 15050106B-001C 7.9 Miles	A&We – Inconclusive PBC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID # DATABASE #	AGENCY PURPOSE	SAMPLING PERIOD: 07/19/2002 – 12/04/2003 NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients – Related	Other		
At 19th Avenue bridge MCSLR013.36 102767	AGFD Ambient		1 sample: Ammonia, nitrite/nitrate, total phosphorus, total Kjeldahl nitrogen, dissolved oxygen, pH	1 Total dissolved solids		

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

DATA GAPS AND MC	MITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
MORE SAMILES TO POSESS	Insufficient core parameters	Insufficient sampling events	LING OCH
MONITORING RECOMMENDATIONS		Low Priority – Collect core parameters to represent at least 3 seasons during an assessment period.	

SALT RIVER From 23 rd Avenue WWTP	US	E SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
discharge to Gila River 15060106B-001D 14.1 Miles	ADEQ	A&Wedw - Attaining PBC - Attaining FC - Inconclusive Agl - Attaining AgL - Attaining	Category 2 Attaining Some Uses		
	E P A	FC – Impaired	Category 5	DDT, toxaphene, and chlordane in fish tissue.	DDT, toxaphene, and chlordane were listed by EPA in 2002.

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B and Appendix C).

MONITORING US	AGENCY PURPOSE	SAMPLING PERIOD: 11/20/200	1 – 08/09/2002			
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
Below Tres Rios discharge MGSLR003.33 101265	ADEQ Ambient	4 total and dissolved metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, mercury, and zinc 4 total metals only: Boron, lead, and manganese	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total phosphorus, total Kjeldahl nitrogen, dissolved oxygen, pH	4 E. coli bacteria 4 Fluoride 4 Total dissolved solids 4 Turbidity 3 Chlorine		

EXCEEDANCES			
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			Fish consumption advisory due to DDT, toxaphene, and chlordane in fish tissue

Pollutant: Assume "total" concentration, unless shown as dissolved.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Pesticides in fish tissue	Collected all core parameters		Lab detection limit for selenium was higher than A&W chronic criteria.	
DISCUSSION OF PESTICIDE I	MPAIRMENT	consumption ad	icide impairment: It completed in 2006 indicates that the fish Ivisory for these pesticides should remain in effect. ion advisory issued in 1991 remains in effect.	
MONITORING RECOMMENDATIONS		High Priority – Collect pesticides data to support TMDL development. Use a lower detection limit for selenium.		

SKUNK CREEK	USE SUPPORT	OVERALL ASSESSMENT	-
From headwaters to Agua Fria River 15070102 003 30.4 Miles	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 11/29/200	02 – 03/16/2003	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other
At 79th Avenue, north bank MGSKU001.43 101521	USGS Special study	3 total metals only: Cadmium, copper, lead, mercury, and zinc	3 samples: Ammonia, total nitrogen, nitrite/nitrate, total phosphorus, total Kjeldahl nitrogen, dissolved oxygen, pH	

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Lead	15 μg/L FBC	01/08/2003 – 18 μg/L	Inconclusive – 1 exceedance in 3 samples. (Binomial)		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Lead	Insufficient dissolved metals (cadmium, copper, and zinc), E. coli bacteria, and mercury to assess A&Ww, FBC, and FC		
MONITORING RECOMMEN	DATIONS	Medium Priority – Co exceedance.	llect additional lead data due to the
		Collect core paramete assessment period.	ers to represent at least 3 seasons during an

SYCAMORE CREEK	USE SUPPORT	OVERALL ASSESSMENT
From Tank Canyon to Agua Fria River 15070102 – 0248 17.6 Miles	A&Ww - Attaining FBC - Attaining FC - Attaining AgL - Attaining	Category 1 Attaining

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 12/21/2001 – 09/20/2002 NUMBER AND TYPES OF SAMPLES		
DATABASE #				
		Metals	Nutrients - Related	Other
Above Sycamore Ranger Station MGSYD009.13 100704	ADEQ Ambient	4 total and dissolved metals: Antimony, arsenic, beryllium, cadmium, copper, and zinc 4 total and 0-2 dissolved: Boron, chromium, lead, manganese, mercury	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total phosphorus, total Kjeldahl nitrogen, dissolved oxygen, pH	3 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solid: 4 Turbidity

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limit for selenium was higher than A&Ww chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority – Use a lower	lab detection limit for selenium.

TEMPE TOWN LAKE	USE SUPPORT	OVERALL ASSESSMENT	
15060106B- 1588 220 Acres	A&WW – Inconclusive FBC – Inconclusive FC – Attaining	Category 2 Attaining Some Uses	

SITE NAMES ID # DATABASE #	AGENCY PURPOSE	SAMPLING PERIOD: 03/27/2001 – 07/22/2004 Weekly sampling from 01/04/2001 – 03/27/2006 NUMBER AND TYPES OF SAMPLES			
DATABASE #		Metals	Nutrients – Related	Other	
At downstream dam MGTTL - A 101316	ADEQ and City of Tempe Ambient	72 total and 0-1 dissolved: Antimony, arsenic, barium, beryllium, boron, cadmium,	78 samples: Ammonia, total nitrogen, nitrite/nitrate, total	352 <i>E. coli</i> bacteria 6 Fluoride 11 Total dissolved solids	
Near upstream dam MGTTL - B 101315	ADEQ and city of Tempe Ambient	chromium, copper, lead, manganese, mercury, nickel, selenium, silver, and zinc	phosphorus, total Kjeldahl nitrogen.	1317 Turbidity	
Mid lake MGTTL - MID 102452	ADEQ and AGFD Ambient		280 Dissolved oxygen 1332 pH		
Mid depth MGTTL – MDEP (not in ADEQ's database)	City of Tempe Ambient (metals)				
Marina MCTTL – MAR (not in ADEQ's database)	City of Tempe Ambient (bacteria and metals)	٠			
50 feet off shore MCTTL – 50 (not in ADEQ's database)	City of Tempe Ambient (field)				

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	>6.0 mg/L A&Ww	After treatment in 2002: 07/15/2004 – 5.4 mg/L 07/22/2004 – 4.1 mg/L 07/29/2004 – 5.1 mg/L 08/05/2004 – 5.1 mg/L 10/22/2004 – 5.4 mg/L 08/29/2005 – 5.7 mg/L	Attaining – 6 low dissolved oxygen samples out of 280 samples (binomial). Dissolved oxygen was collected at only one of the City of Tempe sites (50 feet off shore). It was also collected when ADEQ and AGFD monitored. (Copper sulfate has been added to the lake since 2002 to control algal blooms.)
E. coli bacteria	235 CFU/100 ml FBC	02/14/2003 – 1700 CFU/100 ml 01/25/2005 – 240 CFU/100 ml 07/31/2003 – 900 CFU/100 ml 09/11/2003 – 240 CFU/100 ml	Inconclusive – Although there were four exceedances of standards during the last 3 years of monitoring, weight-of-evidence does not support listing the lake as impaired. See discussion below.
pH (high	<9.0 SU A&Ww, FBC	After treatment in 2002: 01/09/2006 – 9.3 SU (2 sites) 02/07/2006 – 9.3 SU	Attaining – Only 2 exceedances in 890 samples after treatment was begun in 2002. (Copper sulfate has been added to the lake since 2002 to control algal blooms.)
Mercury	0.6 μg/L FC	08/02/2001 – 0.7 µg/L 12/06/2001 – 0.7 µg/L 06/06/2002 – 0.7 µg/L	Attaining – 3 of 72 samples exceeded the criterion. (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient dissolved metals to assess A&W (cadmium, copper, and zinc)		Lab detection limit for dissolved mercury was higher than A&Ww chronic criteria.
DISCUSSION OF E. COLI BAC	CTERIA EXCEEDANCES	does not support listing thi 1. The exceedance flood flows topp USGS gage on In 625 cfs (normal contaminated by 2. The exceedances CFU. Both of the must be exceeded 3. Two of the exceeduring our colde sailing is uncommunity and the binor samples, only 4 cm. The City of Temrestrict swimming.	on 9/11/2003 and 1/25/2005 were both at 240 ase are below the 300 CFU screening value that d for listing decisions. edances (2/14/2003 and 1/25/2005) occurred st months when even incidental swimming while
MONITORING RECOMMENDATIONS		Collect missing core parame	e to collect <i>E. coli</i> bacteria samples. eters to represent at least 3 seasons during an ower lab detection limit for dissolved mercury.

TURKEY CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to unnamed tributary at 341928/1122128 15070102 – 036A 9.1 Miles	A&Ww – Attaining FBC – Inconclusive FC – Inconclusive AgI – Inconclusive AgL – Attaining	Category 2 Attaining some uses	•

MONITORING L	SED IN THI	S ASSESSMENT					
SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 03/14/2000 – 12/19/2003					
DATABASE #		NUMBER AND TYPES OF SAMI	NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients – Related	Other			
At Forest Road 261 MGTRK030.07 101523	ADEQ TMDL	3-9 total and dissolved metals: Arsenic, beryllium, cadmium, chromium, copper, lead, and zinc	7-9 samples: Dissolved oxygen and pH. 1 sample: total nitrogen,	1 Suspended sediment concentration			
At Forest Road 706 MCTRK029.80 101524	ADEQ TMDL	3 total and 0-2 dissolved: Boron 1-2 total and 0-2 dissolved: Antimony, manganese, mercury	nitrite/nitrate, total phosphorus, total Kjeldahl nitrogen				
At Goodwin, AZ MGTRK024.35 101626	ADEQ TMDL						
At Senator Weir MGTRK021.52 102519	ADEQ TMDL						
Upstream of 5000 MSL MGTRK021.44 102512	ADEQ TMDL						

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Dissolved oxygen	<90% A&Ww	12/19/2003 – 58.17%	Attaining – Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Flow 0.003 cfs.		

EXCEEDANCES NEEDING	MISSING CORE	MISSING SEASONAL	DETECTION LIMITS NOT LOW
MORE SAMPLES TO ASSESS	PARAMETERS	DISTRIBUTION	ENOUGH
	Insufficient mercury, E. coli, and manganese to assess FC, FBC, and Agl.		Lab detection limits for selenium and dissolved metals (cadmium, copper, lead, mercury) were higher than A&Ww chronic criteria in at least 2 samples.
MONITORING RECOMMENDATIONS			parameters to represent at least 3 seasons during ower lab detection limits for selenium and

TURKEY CREEK From unnamed tributary at	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
341928/1122128 to Poland Creek 15070102 - 036B 21.0 Miles	A&Ww – Impaired FBC – Impaired FC – Inconclusive AgI – Attaining AgL – Impaired	Category 4A Not Attaining	Copper and lead	TMDL o approved by EPA, in 2008. Delist cadmium and zinc.

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 02/08/2000 – 02/23/2004				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients – Related	Other		
At trail 202 MGTRK016.12 102517	ADEQ TMDL	17-46 total and dissolved metals: Arsenic, boron, cadmium, chromium, copper, lead,	20 Dissolved oxygen 46 pH 17 Total phosphorus	4 Suspended sediment concentration 9 Cyanide		
At corral MCTRK015.90 101538	ADEQ TMDL	manganese, and zinc 37 total and 5 dissolved: Mercury	10 Nitrate/nitrite 1 Total nitrogen and total Kjeldahl nitrogen			
Upstream of Bear Creek MGTRK015.47 102511	ADEQ TMDL	3-6 total metals only: Beryllium				
North of Cleator, at Forest Road 93 MGTRK007.28 101083	ADEQ TMDL	1 total and dissolved: Antimony				
Crown King Road bridge MGTRK004.42 101627	ADEQ TMDL					
Below Golden Belt Mine MGTRK004.33 102518	ADEQ TMDL					
Below Golden Turkey Mine MGTRK003.89 102510	ADEQ TMDL					
At old bend below Golden Belt and Golden Turkey MGTRK003.71 101082	ADEQ TMDL					
At Silver Cord Mine MGTRK001.53 100587	ADEQ TMDL					
At Poland Creek MGTRK000.09 102513	ADEQ TMDL					

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Arsenic	50 μg/L – FBC 200 μg/L – AgL 1450 μg/L – FC 2000 μg/L Agl	03/17/2003 – 2800 μg/L 08/14/2003 – 98 μg/L	Attaining – Exceeded the criteria in 2 of 17 events. (Binomial)
Cadmium	50 μg/L – Agl, AgL 84 μg/L – FC	09/09/2003 – 170 μg/L	Attaining – Only 1 exceedance in 46 samples. (Binomial)
Chromium	100 μg/L FBC	08/14/2003 – 147 μg/L	Attaining – 1 exceedance in 17 sampling events (1 in 30 samples). (Binomial)

Copper	500 μg/L – AgL	08/15/2003 - 569 μg/L	Attaining – 1 exceedance in 19 sampling events (1 in 46 samples) (Binomial)
Copper (dissolved)	17.2 µg/L at 130 mg/L hardness 49.6 µg/L at >400 mg/L hardness A&Ww acute	08/15/2003 – 25 μg/L	Remains impaired – 1 exceedances in the last 3 years of monitoring
Dissolved oxygen	6.0 mg/L A&Ww	12/19/2003 – 4.9 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. (Flow 0.001 cfs.)
Lead	14 μg/L – FBC 100 μg/L – AgL	09/11/2002 – 103 μg/L 02/26/2003 – 564 μg/L 03/17/2003 – 4,800 μg/L 08/14/2003 – 1235 μg/L 08/21/2003 – 38 μg/L	Remains impaired – Criterion 14 μ g/L was exceeded in 5 of 20 sampling events (15 of 46 samples). Concentrations were greater than AgL criterion (100 μ g/L) in 4 of 20 sampling events. (Binomial)
Lead (dissolved)	61.8 µg/L at >400 mg/L hardness A&Ww acute	08/21/2003 – 110 μg/L	Remains impaired – 1 exceedance in last 3 years.
Mercury	0.6 μg/L FC	03/17/2003 – 0.76 μg/L 08/15/2003 – 0.9 μg/L	Inconclusive – 2 of 4 sampling events exceeded the criterion. (7 of 18 samples) (Binomial requires a minimum of 5 exceedances and 20 samples to assess as impaired.)
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Ww	13/17/2003 – 490 mg/L	Inconclusive – Exceeded criterion during only sampling event monitored for this parameters. This sample was collected during storm flows, so could not be used in calculating the geometric mean. Insufficient data to calculate a geometric mean.

DATA GAPS AND MC	NITORING NEED	S		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Mercury, SSC	Need <i>E. coli</i> bacteria to assess FBC.		Lab detection limits for dissolved metals (cadmium, copper, lead, mercury, zinc) were higher than A&Ww chronic criteria in at least 10 samples.	
DELIST CADMIUM AND ZINC		Only one exceedance of cadmium criteria in 45 sampling events. No exceedances of total or dissolved zinc in 45 sampling events. Samples were collected at multiple sites and represent various conditions of flow, including runoff events.		
MONITORING RECOMMENDATIONS		Medium Priority – Collect arsenic, mercury and SSC due to exceedances. Collect metals data to determine effectiveness of TMDL implementation strategies, once implemented. Use lower lab detection limits for dissolved metals. Collect arsenic and suspended sediment samples due to the exceedances. Recommend using biocriteria assessments and bottom deposits implementation procedures in this reach, when they are adopted. Collect missing core parameters to represent at least 3 seasons. During the		

UNNAMED TRIBUTARY TO LYNX CREEK

From headwaters to Lynx Creek 15070102 -- 124 1.0 Miles

USE SUPPORT	OVERALL ASSESSMENT	P
A&Wc – Inconclusive	Category 3	
FC - Inconclusive	Inconclusive	

SITE NAMES	AGENCY	SAMPLING DATE: 05/11/2001			
ID#	PURPOSE	NUMBER AND TYPES OF SAMP	LES		
DATABASE #		Metals	Nutrients – Related	Other	
Above Sheldon waste rock MGULN000.75 103428	Weston Inc Special inv for EPA	6 dissolved metal sample at 6 sites: Antimony, arsenic, barium, beryllium, cadmium, chromium,	None	6 Fluoride 6 Total dissolved solids	
At Sheldon waste rock MGULN000.70 103429	Weston Inc Special inv for EPA	copper, lead, manganese, mercury, nickel, silver, thallium, and zinc			
Below Sheldon waste rock MGULN000.64 103430	Weston Inc Special inv for EPA	(All sites sampled once on the same date.)			
Upstream of Blue John trib. MGULN000.23 103419	Weston Inc Special inv for EPA				
At Blue John tributary MGULN000.16 103420	Weston Inc Special inv for EPA				
Downstream of Blue John trib MGULN000.11 103421	Weston Inc Special inv for EPA				

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Cadmium (dissolved)	19.12 µg/L at >400 mg/L hardness A&Wc acute	05/11/2001 – 135 μg/L	Inconclusive – Only 1 sampling event with an exceedance (5 sites). High magnitude noted.
Cadmium	84 μg/L FC	05/11/2001 – 135 μg/L	Inconclusive – Only 1 sampling event with an exceedance (2 sites). (Binomial)
Copper (dissolved)	49.6 µg/L at >400 mg/L hardness A&Wc acute	05/11/2001 – 22,200 μg/L	Inconclusive – Only 1 sampling event with an exceedance (5 sites). High magnitude noted.
Copper	1300 µg/L FBC	05/11/2001 – 22,200 μg/L (dissolved portion)	Inconclusive – Only 1 sampling event with an exceedance (5 sites). (Binomial)
Zinc (dissolved)	379.3 µg/L at >400 mg/L hardness A&Wc acute	05/11/2001 – 8730 μg/L	Inconclusive – Only 1 sampling event with an exceedance (5 sites). High magnitude noted.

Pollutant: Assume "total" concentration, unless shown as dissolved.

DATA GAPS AND MC	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Cadmium, copper, and lead	Insufficient dissolved oxygen and <i>E. coli</i> bacteria to assess A&Wc and FBC.		Lab detection limits for selenium and dissolved mercury were higher than A&Wc chronic criteria.
MONITORING RECOMMENDATIONS		exceedances. Use lower la	cadmium, copper, and zinc samples due to the b detection limits for selenium and dissolved ore parameters to represent at least 3 seasons.

Salt Watershed

Watershed Description

This watershed is composed of the Salt River drainage from its headwaters to Granite Reef Dam, excluding the Verde River drainage. This watershed can be divided into four very distinct sub-basins: White River, Black River, Tonto Creek, and the main stem Salt River.

The population of this 6,242 square mile watershed is approximately 40,500 people (2000 census), with most of this population in the Superior-Globe-Miami mining district. Land ownership is approximately: 49% Tribal, 48% federal, 2% private, and 1% state. The principal land uses are open range grazing, recreation, forestry, and mining. Nine wilderness areas have been set aside, which have restricted land uses and activities.

Elevations range from 10,600 feet (above sea level) in the White Mountains, to about 2,000 feet at Granite Reef Dam. The watershed above Roosevelt Lake (White River, Black River, and Tonto Creek) is above 5,000 feet elevation with high desert flora and fauna, and coldwater aquatic communities where perennial waters exist. The area below Roosevelt Lake is below 5,000 feet, and therefore, contains primarily warmwater aquatic communities.

Water Resources

This Watershed receives more precipitation than most of the state, with approximately 20 inches of rain and 20 inches of snowfall. Roosevelt Lake and a chain of other reservoirs (Apache, Canyon, and Saguaro) were constructed to store perennial flow from this watershed and provide much of the water used in the Phoenix metropolitan area.

An estimate of surface water resources in the Salt Watershed is provided in the following table. Waters on Tribal lands are not assessed by ADEQ; therefore, those statistics are shown separately.


Estimated Surface Water Resources in the Salt Watershed

	Perennial	Intermittent	Ephemeral
Stream miles	510	1,190	2,785
	Perennial	Non-perennial	
Lake acres	25,544	0	

On Tribal Lands – Not Assessed

	Perennial	Intermittent	Ephemeral
Stream miles	825	0	4,275
On Tribal Lands			
	Perennial	Non-perennial	
Lake acres On Tribal Lands	1,858	0	

Ambient monitoring focuses on perennial waters; however, special investigations may identify water quality problems on intermittent and even ephemeral waters. Estimated miles and acres are based on USGS digitized hydrology at 1:100,000 and have been rounded to the nearest 5 miles or 5 acres.





Watershed Partnerships

- The Friends of Pinto Creek
 This group is dedicated to the preservation of Pinto Creek and its tributaries, which flow through the copper mining area near Globe. They are dedicated to the preservation of Pinto Creek, Powers Gulch and Haunted Canyon. This group meets as needed. Contact Tom Sonandres at (623) 583-6764 or pintocreek@asu.edu for more information.
- Northern Gila County Water Planning Alliance The watershed of interest is bounded by Mogollon Rim to the north, Roosevelt Lake to the south, Sierra Ancha Mountains to the east, and Mazatzal Mountains to the west. The alliance was formed to develop water strategies for the area around Payson, Pine, and Strawberry (a.k.a. Tonto Creek Basin). This group meets as needed. Contact Steve Besich, Assistant County Gila Manager at sbesich@co.gila.za.us; Lionel Martinez, rim Trail Water Improvement District at (928) 474-2029; or Howard Matthews, pine-Strawberry Water Improvement District at (928) 476-2142.

Special Studies and Water Quality Improvement Projects

Total Maximum Daily Load Analyses – The following TMDL analyses have been completed, are ongoing, or are scheduled to be completed in this watershed. Further information about the status of these investigations or a copy of the TMDL, if completed, can be obtained at ADEQ's website: www.azdeq.gov.

- Canyon Lake is impaired by low dissolved oxygen.
 Low dissolved oxygen is generally associated with nutrient loading and eutrophic conditions which can lead to algal blooms and even fish kills. A TMDL is to be initiated in 2010 to determine the cause and controllable sources of the low dissolved oxygen and recommend strategies to meet surface water quality standards.
- Crescent Lake is impaired due to high pH (alkalinity).
 High pH readings are also frequently associated with nutrient loading (see Canyon Creek comments). High pH values may represent concerns for most designated uses, but pose the biggest risk to aquatic life.
- Christopher Creek and Tonto Creek, above Haigler Creek confluence, are impaired by bacteria Escherichia coli) contamination.
 Bacteria contamination may pose a risk to humans swimming or even wading in the water. A bacteria TMDL was completed in 2004 for both Christopher Creek and Tonto Creek. Septic and waste disposal systems were identified as the primary source of bacterial loading. The TMDL recommended inspection, repair, and upgrading of these systems, and improving facilities at heavily used recreational sites. The U.S. Forest Service and Gila County Health Department were encouraged to initiate routine bacterial monitoring.
- Tonto Creek, above Haigler Creek confluence, is also impaired by nitrogen (nutrients). Excess nitrogen can lead to eutrophic conditions and algal blooms. A nitrogen TMDL was approved in 2005. Three sources of excess nutrients were identified: septic systems, insufficient restroom facilities at recreational sites along Tonto Creek, and the Tonto Creek Fish Hatchery. ADEQ will work with the Arizona Game and Fish Department to determine new permit discharge limits for the hatchery and the means for achieving these limits. Inspection, repair, and upgrading of septic systems, along with improving waste facilities at recreational sites, were also recommended actions so that nutrient standards will be met.
- Pinto Creek is impaired by copper, and the segment of Pinto Creek downstream of Ripper Spring is also impaired by selenium.
 Both copper and selenium concentrations pose a risk to aquatic life and wildlife. Selenium was added on the 2004 Impaired Waters List for the downstream segment of Pinto Creek and a selenium TMDL is scheduled to be initiated in 2009.

The Pinto Creek Phase II TMDL Modeling Report, written by Malcolm Pirnie, Inc. for ADEQ (2006), describes the hydrology and pollutant transport for Pinto Creek basin in support of allocation of copper from discharges to the creek. Natural mineralization in the area has resulted in numerous historic and active mining related disturbances. This model scenario results lead to the following major conclusions:

- o Gibson Mine is the single largest source of copper loads to Pinto Creek over 90% of the copper load. Remediation efforts are necessary at this mining site;
- o Remediation at other mining sources is expected to reduce copper;
- o Much of upper Pinto Creek would exceed copper criteria even after remediation;
- o The Carlotta Copper project (a new mine site being established on Pinto Creek) is not predicted to cause large changes in copper loads or concentrations.

Aggressive remediation activities are being scheduled for the Gibson Mine, an abandoned mine (see Water Quality Improvement Grants below). Site specific standards are also being developed for copper in Pinto Creek because the natural background concentration is higher than the standard in this copper rich mining area.

• The Salt River, from Stewart Mountain Dam (Saguaro Lake) to the Verde River, is impaired by low dissolved oxygen which poses a threat to aquatic life. More data is needed to identify sources and TMDLs have been scheduled to be initiated in 2010.

Water Quality Improvement Grant Projects – ADEQ awarded the following Water Quality Improvement Grants (319 Grants) in this watershed. More information concerning these grants or projects can be obtained at: http://www.azdeq.gov/environ/water/watershed/fin.html.

• Lower Salt River Pollution Prevention, Education, and Monitoring Project
The Tonto National Forest (2000)

Construct three restrooms in the Salt River Recreational Area and monitor bacteria levels in the segment of stream used for tubing and other recreation.

Camp Geronimo Boy Scout Camp On-site Sewer Improvement Project
 Camp Geronimo Boy Scout (2002)

Camp Geronimo Boy Scouts (2002 and 2004)

Add treatment facilities and provide sealed vault and haul toilet units.

• Trees for the Rim Project

Arizona Community Tree Council (2003)

Provide trees and other vegetation at no cost to those private property owners whose trees and landscape plants were destroyed during the Rodeo-Chediski fire in 2002. These actions are to help restore vegetation and thereby reduce runoff pollution.

• Gibson Mine Remediation Project

Franciscan Friars of California (2005 and 2006)

Design, construct, and implement a manmade wetland to reduce copper, beryllium, zinc, and turbidity loadings to Pinto Creek and Mineral Creek.

• Gila County Septic System Project

Gila County Health Department and Community Services (2005 and 2006)

Identify, repair, upgrade, or replace waste water systems that are structurally unsound or failing in the Christopher Creek and Tonto Creek (headwaters) area. These activities support implementation of the nitrogen and bacteria TMDLs established for these waters.

• R-Bar-C Boy Scout Camp Sewer Facilities Project

Boy Scouts of America - Grand Canyon Council (2006)

Upgrade septic treatment and disposal facilities to prevent contamination of Christopher Creek.

Water Protection Fund Projects – The following Water Protection Fund Projects were awarded by the Arizona Department of Water Resources. More information about these funds or projects can be obtained from the ADWR web site at: http://www.azwater.gov.

• Canyon Creek Riparian Restoration Project

Arizona Game and Fish Department (2005)

Temporarily exclude grazing (5 to 10 years) from a half-mile reach of Canyon Creek. The goal of the exclosure is to improve water quality and restore native habitat.

Other Water Quality Studies

Lower Verde / Lower Salt River Management Plan and Restoration Strategy
 Lower Verde / Lower Salt River Watershed Advisory Group (2000)

 This plan identifies the areas of greatest concern for water resources, initiates pollution source identification, and identifies programs and potential actions to remediate these sources.

• Phoenix Metropolitan Reservoir Study

David Walker, University of Arizona

This is an ongoing and comprehensive study of water quality in reservoirs serving the Phoenix metropolitan area. Goal is to collect and analyze data to answer water quality management questions in a proactive manner. A yearly report is produced. In 2005, the report provided information about:

- Climate and drought effects on water quality,
- Wildfire effects on water quality,
- o Harmful algal blooms,
- o Atmospheric deposition and the use of sediment to look at accumulation of pollutants, and
- Endocrine disruption compounds.
- Characterization of Hydraulic Conductivity of the Alluvium and Basin Fill, Pinal Creek Basin near Globe, Arizona

Cory E. Angeroth – U.S. Geological Survey (2002)

Mining in the Pinal Creek area has resulted in acidic waters containing elevated concentrations of dissolved metals in the ground water. Slug tests were conducted in 1997 and 1998 to better understand contaminant transport through the regional aquifer (i.e., hydraulic conductivity). The tests showed that in the unconsolidated stream alluvium and in the basin fill, the lower the pH of the ground water, the higher the hydraulic conductivity. Likely, the low pH water is causing the dissolution of aquifer material.

• Assessment of Selected Inorganic Constituents in Streams in the Central Arizona Basins Study Area, Arizona and Northern Mexico, through 1998

David Anning – U.S. Geological Survey, National Water Quality Assessment Program (2003) Inorganic chemical data (dissolved solids, suspended sediment, and nutrients) and stream properties (temperature, pH, dissolved oxygen) were analyzed to assess water quality, determine natural and human factors affecting water quality, and compute stream loads.


- The total annual input fluxes from quantifiable sources of nitrogen and phosphorus (nutrients)
 were considerably higher for developed basins than for minimally developed basins (such as the
 Salt Watershed).
- For minimally developed basins, precipitation was the largest quantifiable source of nitrogen.
- The amount of nitrogen and phosphorus transported out of the basins was much smaller than the amount of quantifiable inputs. This indicates that most of the nutrients were not transported out in surface water, but were transported to the subsurface (soil or aquifer), released to the atmosphere (volatilized ammonia), or incorporated into the biomass (plants and animals).

Assessments

The Salt Watershed can be separated into the following drainage areas (subwatersheds):

15060101	Black River
15060102	White River (Tribal land - Not assessed)
15060103	Upper Salt River
15060104	Carrizo Creek (Tribal land - Not assessed)
15060105	Tonto Creek
15060106A	Lower Salt River

These drainage areas and the surface waters assessed as "attaining" or "impaired" are illustrated on the following watershed map. Methods used to complete these assessments are described in the "Surface Water Assessment Methods and Technical Support" document (2006).



15060106A-0070	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
2190 Acres	A&Wc - Impaired FBC - Inconclusive FC - Attaining DWS - Attaining AgI - Attaining AgL - Attaining	Category 5	Low dissolved oxygen	Add low dissolved oxygen to the 303(d) List

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/30/2000				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
At dam SRAPA-A 100997	ADEQ, AGFD, UA Ambient	9-14 total and 5 dissolved: Cadmium, chromium, copper, lead, nickel, silver, zinc	42-45 samples: Ammonia, total nitrogen, nitrite/nitrate, total	11 <i>E. coli</i> bacteria 11 Fluoride 14 Total dissolved solids		
At transition zone SRAPA-B 101712	UA Ambient	6-15 total and 0-2 dissolved: Antimony, arsenic, barium, beryllium, boron, manganese, selenium, mercury, and thallium	Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	24 Turbidity		
In riverine zone SRAPA-C 102139	ADEQ, AGFD, UA Ambient					
At beach SRAPA-BCH 101704	AGFD, UA Ambient					
At camping area SRAPA-BC 101707	AGFD, UA Ambient					
At Burnt Corral SRAPA-COR 102753	ADEQ, AGFD, UA Ambient					
Mid Lake SRAPA-E 100008	ADEQ, AGFD, UA Ambient					
At marina SRAPA-MAR 100998	AGFD Ambient					

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	7.0 mg/L A&Wc	SITES 10/30/2000 - 5.1 mg/L - all 09/05/2001 - 2.3 mg/L - C 10/03/2001 - 4.6 mg/L - C 05/30/2001 - 6.2 mg/L - B and C 08/20/2003 - 6.3 mg/L - A 03/10/2004 - 6.4 mg/L - B and C 04/09/2004 - 6.0 mg/L - C 06/01/2004 - 5.1 mg/L - all 11/05/2004 - 2.9 mg/L - all	Impaired – Low dissolved oxygen in the top meter in 16 of 38 samples in the top meter.) (Binomial) Low dissolved oxygen occurred during 9 of 17 monitoring events in the top meter of lake water. (Note: ADEQ has proposed changing the designated use at this lake to A&Ww, which has a dissolved oxygen standard of 6.0 mg/L. This would adjust the number of low dissolved oxygen samples to 8 of 38 samples (5 of 17 sampling events), and it would remain impaired.)	

pH (high)	<9.0 SU A&Wc, FBC, DWS,	08/06/2001 – 9.2 SU 03/07/2003 – 9.4-9.8 SU	Attaining – pH exceeded standards in 2 of 15 sampling events. (Binomial)
	Agl, AgL		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Need composite nitrogen and phosphorus samples to assess A&Wc and FBC		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria in at least 7 samples.
DISCUSSION OF SITE SPECIFIC NUTRIENT STANDARDS		Nitrogen and phosphorus standards established for this lake are based on composite samples collected at the surface, 2 meter, and 5 meter depths. No composite samples were collected and analyzed during this assessment period. This standard is to be replaced by the proposed lake narrative nutrient implementation procedures currently being adopted through the Triennial Review process.	
MONITORING RECOMMEND	DATIONS	High Priority –Collect mo TMDL.	re dissolved oxygen samples to support a
		nutrient loading. New me standard should be applie whether narrative nutrien	d high pH may be symptoms of excess thods for implementing the narrative nutrient d to this lake once adopted, to determine t violations are occurring based on the violation, and elevated nutrients.
		Use lower lab detection li	mits for selenium and dissolved mercury.

BEAR WALLOW CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From North and South Forks of Bear Wallow to Indian Reservation boundary 15060101 – 023A 5.9 Miles Unique Water	A&Wc - Attaining FBC - Inconclusive FC - Attaining AgL - Attaining	Category 2 Attaining some uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/24/2001 – 08/15/2002			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Below South Fork Bear Wallow Creek SRBWL005.79 101198	ADEQ Ambient	3 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, zinc 3 total and 0-1 dissolved: Boron, lead, manganese, mercury 1 total and 1 dissolved: barium, nickel, silver, and thallium	3 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	2 <i>E. coli</i> bacteria 3 Fluoride 3 Total dissolved solids 3 Turbidity	

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient <i>E. coli</i> bacteria samples to assess FBC		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority – Collect <i>E. coli</i> bacteria samples to represent at least 3 seasons during the assessment period. Use lower lab detection limits for selenium and dissolved mercury.	

BEAVER CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Black River 15060101 008 13.1 Miles	A&Wc – Inconclusive FBC – Inconclusive FC – Attaining Agl – Attaining AgL – Attaining	Category 2 Attaining some uses	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 10/24/2001	- 10/26/2004		
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients – Related	Other	
Above Forest Road #26 SRBEV012.04 102145	ADEQ Special study	3 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, zinc	3 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen	3 E. coli bacteria 3 Fluoride 7 Total dissolved solids	
Above Hannagan Creek SRBEV009.66 102140	ADEQ Special study	3 total and 0-1 dissolved: Boron, lead, manganese, mercury	7 Phosphorus, dissolved oxygen, pH	22 Suspended sediment concentration 22 Turbidity	
Below Hannagan Creek SRBEV009.56 102139	ADEQ Special study	1 total and 1 dissolved: barium, nickel, silver, and thallium			
Above Forest Road 26 bridge SRBEV007.28 102135	ADEQ Special study				
At USGS Gage near Sprucedale SRBEV001.40 100373	ADEQ Ambient and Special study				

POLLUTANT	STANDARD	DATES	DESIGNATED USE SUPPORT
	UNIT DESIGNATED USES	EXCEEDANCES	SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Wc	08/13/2002 - 6.74 mg/L 08/28/2003 - 5.56 mg/L	Inconclusive – On 08/13/2002 low dissolved oxygen was naturally occurring due to low flow (flow as 0.13) due to ground water upwelling. Nitrogen was 0.37, phosphorus = 0.18. Other date was during flood flow at 9 cfs, with phosphorus reading at 13 mg/L. (Binomial)
Phosphorus	0.8 mg/L Single sample maximum A&Wc, FBC	08/27/2003 – 13 mg/L	Inconclusive – Only 1 exceedance in 7 samples. (Binomial)
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Wc	08/27/2003 – 4865 mg/L	Attaining – SSC criteria of 80 mg/L was exceeded once in 22 sampling events. Because the sample was collected during flood flows of 9-10 cfs, the value could not be included in the geometric mean calculation. The geometric mean standard was not exceeded. However, the high sediment concentration suggests that sediment may be a problem in this watershed.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Phosphorus and dissolved oxygen	Core parameters collected.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMEND	ATIONS	samples due to exceedances. Use lower lab detection limit Recommend using biocriteria implementation procedures it to high levels of suspended s	is for selenium and dissolved mercury. a assessments and bottom deposits in this reach, when they are adopted, due ediment during flood flows. Note that the FU) was exceeded during 8 of 22 sampling

BIG LAKE	USE SUPPORT	OVERALL ASSESSMENT	
15060101 0160 440 Acres	A&Wc - Inconclusive FBC - Inconclusive FC - Attaining DWS - Attaining AgI - Attaining AgL - Attaining	Category 2 Attaining some uses	

MONITORING	USED IN TH	IS ASSESSMENT			
SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 11/15/2001 – 06/12/2002			
DATABASE #		NUMBER AND TYPES OF SA	NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other	
At dam SRBIG-A 101322	ADEQ Ambient	3 dissolved and total metals: Antimony, arsenic, barium, boron, beryllium, chromium,	3-4 samples: Ammonia, total nitrogen, nitrite/nitrate, total	2 <i>E. coli</i> bacteria 3 Fluoride 4 Total dissolved solids	
Mid lake SRBIG-B 101355	ADEQ Ambient	selenium, zinc 3 total and 0-1 dissolved: Cadmium, copper, lead, silver, manganese, mercury	Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	3 Turbidity	
At boat dock SRBIG-D 100013	ADEQ Ambient				
Shoreline SRBIG-SH 101358	ADEQ Ambient				
West of floating dock SRBIG-SBR 101359	ADEQ Ambient				

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances			·	

DATA GAPS AND MC	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient <i>E. coli</i> bacteria and dissolved cadmium and dissolved copper to assess FBC and A&Wc		Lab detection limits for dissolved metals (cadmium copper, lead, mercury, and silver) were higher than the A&W chronic criteria in at least 1 sample.
MONITORING RECOMMENDATIONS		Low Priority —Collect missing core parameters to represent at least seasons during the assessment period. Use lower lab detection limit for dissolved metals.	

BLACK RIVER	USE SUPPORT	OVERALL ASSESSMENT	
From Beaver Creek to Reservation Creek 15060101 – 007 13.1 Miles	A&Wc - Attaining FBC - Inconclusive FC - Attaining DWS - Attaining Agl - Attaining AgL - Attaining	Category 2 Attaining some uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/25/200	01 – 08/14/2002	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other
Above Forest Road #25 SRBLR102.24 101202	ADEQ Ambient	3 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc 3 total 0-1 dissolved: Boron, manganese, lead, mercury 1 total, 1 dissolved Barium, nickel, silver, thallium	3 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	2 <i>E. coli</i> bacteria 3 Fluoride 3 Total dissolved solids 3 Suspended sediment concentration 4 Turbidity

EXCEEDANG	-F2		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient <i>E. coli</i> bacteria sample to assess FBC		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMEND	ATIONS		bacteria samples to represent at least 3 period. Use lower lab detection limits for any

CAMPAIGN CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Pinto Creek 15060103 037	A&Ww – Attaining FBC – Attaining	Category 1	
16.6 Miles	FC – Attaining AgL – Attaining	Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 11/27/2001 – 09/11/2002			
DATABASE #	•	NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At Superstition Wilderness Boundary SRCGN009.78 100431	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, zinc	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	3 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids 4 Turbidity	
		4 total metals only: Boron, lead, manganese, mercury			

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances			·	

EXCEEDANCES NEEDING	MISSING CORE	MISSING SEASONAL	DETECTION LIMITS NOT LOW
MORE SAMPLES TO ASSESS	PARAMETERS	DISTRIBUTION	ENOUGH
	Collected all core		Lab detection limit for selenium was
	parameters		higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority –Use lower lab detection limits for selenium.	

CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to White Mountain Apache Reservation 15060103 014 8.6 Miles	A&Wc Attaining FBC Attaining FC Attaining DWS Attaining AgI Attaining AgL Attaining	Category 1 Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 12/18/2001	- 09/06/2002		
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Below OW Ranch Road \$RCYN046.07 100370	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, zinc 4 total metals only: Boron, lead, manganese, mercury	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	3 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids 4 Turbidity	

POLLUTANT STANDARD DATES DESIGNATED USE SUPPORT UNIT EXCEEDANCES SUPPORTING EVIDENCE AND COMMEN					
No Exceedances	DESIGNATED USES				

DATA GAPS AND MO	NITORING NEED!	5	
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limit for selenium was higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority –Use a lower la	b detection limit for selenium.

CANYON LAKE 15060106A 0250	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
450 Acres	A&Wc – Impaired FBC – Inconclusive FC – Attaining DWS – Attaining AgI – Attaining AgL – Attaining	Category 5	Low dissolved oxygen	Added low dissolved oxygen to 303(d) List in 2004

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 07/11/2001 – 10/20/2004				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
At dam SRCAN-A 101697	ADEQ, AGFD, UA Ambient	7-11 total and 7 dissolved: Cadmium, chromium, copper, lead, nickel, silver, zinc	28-30 samples: Ammonia, total nitrogen, nitrite/nitrate, total	8 <i>E. coli</i> bacteria 16 Fluoride 6 Total dissolved solids		
At transition zone SRCAN-B 101699	ADEQ, UA Ambient	7 total and 0-2 dissolved: Antimony, arsenic, barium,	Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	11 Turbidity		
Inflow below Horse Mesa Dam SRAPA-1 102538	AGFD Ambient	beryllium, boron, manganese, selenium, mercury, thallium				
Canyon area SRCAN-CAN 102754	AGFD Ambient					
At campground SRCAN-CG1 101700	ADEQ. AGFD, UA Ambient					
At marina SRCAN-MAR 101701	UA Ambient					
Upper middle lake SRCAN-MID 102837	AGFD Ambient					

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	7.0 mg/L A&Wc	SITES 10/15/2001 – 6.1 mg/L – A and 1 10/18/2002 – 6.7 mg/L – A 06/04/2003 – 4.5 mg/L – A and B 10/15/2003 – 4.4 mg/L – A 01/08/2004 – 5.0 mg/L – A and B 10/20/2004 – 4.2 mg/L – A and B	Impaired – Low dissolved oxygen in 10 of 23 samples in the top meter. (Binomial) Low DO during 6 of 12 sampling events. (Note: ADEQ has proposed changing the designated use at this lake to A&Ww, which has a dissolved oxygen standard of 6.0 mg/L. This would adjust the number of low dissolved oxygen samples to 5 of 23 samples (4 of 12 sampling events), and it would remain impaired.)	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Need composite nitrogen and phosphorus samples to assess A&Wc and FBC		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria in at least 2 samples.
		on composite samples col depths. No composite san assessment period. This standard is to be repl implementation procedun Triennial Review process. The nitrogen criterion (1.0	standards established for this lake are based lected at the surface, 2 meter, and 5 meter apples were collected and analyzed during this aced by the proposed lake narrative nutrient es currently being adopted through the 0 mg/L) was exceeded in 4 of 27 samples. However, since these were not composite not apply.
MONITORING RECOMMENDATIONS		High Priority —Collect more dissolved oxygen samples to support a TMDL Low dissolved oxygen may be a symptom of excess nutrient loading. New methods for implementing the narrative nutrient standard should be applied to this lake once adopted. Use lower lab detection limits for selenium and dissolved mercury.	

CHERRY CREEK	USE SUPPORT	OVERALL ASSESSMENT
From tributary at 340509 / 110 56004 to Salt River 15060103 0158 40.9 Miles	A&Wc - Attaining FBC - Attaining FC - Attaining Agl Attaining AgL - Attaining	Category 1 Attaining all uses

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 11/27/2001	- 09/10/2002		
DATABASE #	NUMB Metals	NUMBER AND TYPES OF SAM	UMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other	
Above road crossing SRCHE032.78 101323	ADEQ Ambient	8 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium,	8 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen,	7 <i>E. coli</i> bacteria 8 Fluoride 8 Total dissolved solids	
Half-mile above Leisure Canyon	ADEQ Ambient	copper, zinc	total phosphorus, dissolved oxygen, pH	8 Turbidity	
SRCHE004.32		8 total metals only: Boron, lead, manganese, mercury			

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances				

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
THE STATE EST TO TWEE	Collected all core		Lab detection limit for selenium was higher than the A&W chronic criteria
MONITORING RECOMMENDATIONS		Low Priority –Use a lower lab detection limit for selenium.	

CHRISTOPHER CREEK From headwaters to Tonto	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Creek 15060105 – 353 8.0 Miles	A&Wc - Impaired FBC - Impaired FC - Attaining AgI - Attaining AgL - Attaining	Category 4A (E. coli) Not attaining Category 5 (phosphorus) Impaired	E. coli bacteria and phosphorus	Add phosphorus. E. coli TMDL was approved in 2005. Implementing strategies to reduce loadings.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 05/23/2000 – 10/25/2003				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients – Related	Other		
Above recreation area SRCRS006.20 101027	ADEQ TMDL	3-4 total and dissolved metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc 3-4 total metals only: Barium, boron, lead, manganese, mercury 1 total metals only: Nickel,	95-102 samples: Total nitrogen, total phosphorus, total	68 <i>E. coli</i> bacteria 4 Fluoride 3 Total dissolved solids		
Below recreation area SRCRS005.68 101028	ADEQ TMDL		Kjeldahl nitrogen, dissolved oxygen, pH 4 samples: Ammonia	163 Suspended sediment concentration 72 Turbidity		
Above Highway 260 at Christopher Creek, AZ SRCRS004.43 100362	ADEQ TMDL					
Below Christopher Creek, AZ SRCRS002.97 101030	ADEQ TMDL	silver, and thallium				
Above Christopher Creek Campground SRCRS002.82 100364	ADEQ TMDL					
Below Christopher Creek Campground SRCRS002.25 100365	ADEQ TMDL					
At top of Box Canyon SRCRS001.24 101033	ADEQ TMDL					
Below Box Canyon SRCRS000.34 100367	ADEQ Ambient					
Above Tonto Creek SRCRS000.08 101034	ADEQ TMDL					

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Wc	05/24/2000 – 6.7 mg/L 09/05/2000 – 6.7 mg/L 05/08/2002 – 6.7 mg/L 06/10/2002 – 6.5 mg/L 07/24/2002 – 6.6 mg/L 07/23/2003 – 6.6 mg/L 08/20/2003 – 6.5 mg/L	Attaining –Low dissolved oxygen normally solely due to natural conditions of low flow and ground water upwelling. (Low flows between 0.03 – 0.5 cfs.) Lowest dissolved oxygen measurement was 6.5 mg/L, which is marginally below the standard.
E. coli bacteria	235 CFU/100 ml FBC	09/02/2000 – 689 CFU/100 ml 10/31/2000 – 479 CFU/100 ml 07/22/2003 – 1120 CFU/100 ml 08/20/2003 >2419 CFU/100 ml 10/08/2003 345 CFU/100 ml	Remains impaired – Exceeded criterion on 5 sampling events during the assessment period. Three exceedances in 2003. Exceedance on one date was associated with flood flows (20 cfs). Exceedances on two other dates were occurred during elevated flows (2-6 cfs).
Phosphorus	0.8 mg/L – Single sample max (SSM) 0.10 mg/L – Annual mean A&Wc and FBC	08/20/2003 – 3.5 mg/L (SSM) 2000 – 0.13 (annual mean) 2003 – 0.44 mg/L (annual mean)	Impaired – Annual mean was exceeded 2 different sites in 2003 and one site in 2000. Single sample maximum (1 mg/L) was exceeded only in 1 of 35 samples (binomial).
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Wc	08/06/2003 – 1603 mg/L 08/20/2003 – 702 mg/L 10/08/2003 – 92 mg/L	Attaining – 3 of 13 sampling events exceeded the 80 mg/L criterion. 1 exceedance occurred during elevated flows (702 mg/L at 5.6 cfs), so was not included in the geometric mean calculation. Using the remaining data, the geometric mean was not exceeded. Note that the old turbidity standard (10 NTU) was also exceeded during 9 sampling events.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limit for selenium was higher than A&Wc chronic criteria.
MONITORING RECOMMEN	IDATIONS	phosphorus loadings; there low priority. Collect additi	to E. coli bacteria loadings will also reduce fore, development of a phosphorus TMDL is a onal phosphorus and E. coli bacteria data to TMDL strategies being implemented. imit for selenium.
			ria assessments and bottom deposits s in this reach, when they are adopted.

COON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From tributary at 334642 / 1105425 to Salt River 15060103 039B 10.1 Miles	A&Ww - Attaining FBC - Attaining FC - Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES AGENCY ID # PURPOSE DATABASE #		SAMPLING DATE: 11/27/2001	- 09/10/2002	
		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
At Forest Road #203 SRCOO001.92 100379	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, zinc 4 total metals only: Boron, lead, manganese, mercury	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	4 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solid: 4 Turbidity

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limit for selenium was higher than the A&W chronic criteria
MONITORING RECOMMENT	DATIONS	Low Priority –Use a lower la	b detection limit for selenium.

COTTONWOOD GULCH	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Pinto Creek 15060103 – 891 1.9 Miles	A&We – Inconclusive PBC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIODS: 01/10/2000 – 07/16/2002; 04/05/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Below Outfall PV004 SRCTG000.39 103443	BHP Permit	9-19 dissolved and total metals: Arsenic, beryllium, cadmium, copper, magnesium, selenium, and zinc.	9 samples: Dissolved oxygen 19 samples: pH	9 Turbidity	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances				

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Dissolved lead needed to assess attainment of A&We.		11100011
MONITORING RECOMMENDATIONS		Low Priority -Collect core parameters to represent at least 3 seasons during the assessment period.	

CRESCENT LAKE 15060101 0420		USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
155 Acres	ADEQ	A&Wc - Inconclusive FBC - Inconclusive FC - Attaining Agl - Inconclusive AgL - Inconclusive	Category 2 Attaining Some Uses		
	E P A	A&Wc – Impaired FBC – Impaired AgI – Impaired AgL – Impaired	Category 5	High pH	EPA listed lake due to high pH in 2002

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B and Appendix C).

SITE NAMES	AGENCY	SAMPLING DATE: 11/14/2001	- 06/12/2002		
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES			
DATABASE #		Metals	Nutrients - Related	Other	
Mid lake SRCRE-B 100993	ADEQ Ambient	3 dissolved and total metals: Antimony, arsenic, barium, boron, beryllium, chromium,	3 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen,	3 E. coli bacteria 3 Fluoride 4 Total dissolved solid:	
At boat ramp SRCRE-BR 101320	ADEQ Ambient	manganese, nickel, silver, selenium, zinc	total phosphorus, dissolved oxygen, pH	2 Turbidity	
		3 total and 0-2 dissolved: Cadmium, copper, lead, mercury			

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
pH	<9.0 SU A&Wc, FBC, Agl, AgL	11/14/2001 – 9.6 SU	Inconclusive – 1 exceedance in 3 samples. (EPA's original listing considered older data.)		

Pollutant: Assume "total" concentration, unless shown as dissolved.

EXCEEDANCES NEEDING	MISSING CORE	MISSING SEASONAL	DETECTION LIMITS NOT LOW
MORE SAMPLES TO ASSESS	PARAMETERS	DISTRIBUTION	ENOUGH
	Insufficient dissolved cadmium and dissolved copper to assess A&Wc		Lab detection limits for dissolved metals (cadmium, copper, lead, and mercury) were higher than the A&W chronic criteria in at least 1 sample.
DISCUSSION OF HIGH PH IMPAIRMENT		Evidence of potential impairment: No newer monitoring data since lake was listed as impaired.	
MONITORING RECOMMENDATIONS		High Priority – Collect pH m TMDL. High pH may be a sy methods for implementing t	measurements to support development of a symptom of excess nutrient loading. New the narrative nutrient standard should be applied o determine whether narrative nutrient
		Collect missing core parame Use lower lab detection limi	eters to represent at least 3 seasons. lits for dissolved metals.

DEER CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Rye Creek 15060105 018 11.9 Miles	A&Wc - Attaining FBC - Attaining FC - Attaining	Category 1 Attaining all uses	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 01/10/2002 – 04/23/2002				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients – Related	Other		
Above Mazatzal Wilderness Boundary SRD4E005.86 100531	ADEQ Ambient	3 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc	3 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	3 E. coli bacteria 3 Fluoride 3 Total dissolved solids 3 Turbidity		
		3 total metals only: Boron, lead, manganese, mercury				

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
No Exceedances					

DATA GAPS AND MO EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
S	Collected all core parameters		Lab detection limits for selenium was higher than the A&W chronic criteria.
MONITORING RECOMMENT	DATIONS	Low Priority –Use a lower la	b detection limit for selenium.

EAST FORK BLACK RIVER	USE SUPPORT	OVERALL ASSESSMENT
From headwaters to Black River 15060101 009 26.7 Miles	A&Wc – Attaining FBC – Attaining FC – Attaining DWS – Attaining Agl – Attaining AgL – Attaining	Category 1 Attaining all uses

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 10/24/2001 – 11/19/2003				
DATABASE #		NUMBER AND TYPES OF SAM	NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other		
Below the three Black River forks SREFB011.86 101203	ADEQ Special study	8 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, zinc	8 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved	8 <i>E. coli</i> bacteria 8 Fluoride 8 Total dissolved solids 4 Suspended sediment		
Above old Buffalo Crossing bridge SREFB000.91 100375	ADEQ Special study	8 total and 0-2 dissolved: Boron, lead, manganese, mercury	oxygen, pH	concentration 12 Turbidity		
Below Forest Road 24 at USGS gage SREFB000.62 102131	ADEQ Special study	2 total and 2 dissolved: barium, nickel, silver, and thallium				

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority –Use lower lab de mercury.	tection limits for selenium and dissolved

ELLIS RANCH TRIBUTARY	USE SUPPORT	OVERALL ASSESSMENT	
Troill iteautraters to rittle aroun	A&We –Inconclusive PBC – Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 03/05/2004 – 01/12/2005 NUMBER AND TYPES OF SAMPLES		
DATABASE #				
		Metals	Nutrients - Related	Other
Above Forest Road #349 SRERTO00.48 102647	ADEQ TMDL	27 dissolved and 5 total: Copper 5 total and 5 dissolved: Selenium and zinc		
At Forest Road #349 SRERT000.10 102648	ADEQ TMDL	4 pH		

EXCEEDANCE	S		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	5.8 µg/L at 23 mg/L hardness 5.8 µg/L at 23 mg/L hardness 7.5 µg/L at 30 mg/L hardness A&We acute	12/29/2004 – 36 μg/L 01/04/2005 – 67 μg/L 01/12/2005 – 37 μg/L	Inconclusive —Field investigations for the Pinto Creek TMDL have concluded that copper loads are due to a combination of natural background conditions, as well as abandoned mines in the subwatershed. Further monitoring is needed in order to determine natural background levels.
Low pH	<6.5 SU A&We, PBC	03/05/2004 - 6.1 SU	Inconclusive – Did not meet standards in 1 of 4 samples. (Binomial)

Frequency Exceed = Samples collected within a 7-day period are aggregated and counted as one sample per site.

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
рН	Missing most core parameters	Insufficient sampling events	Lab detection limits for selenium was higher than the A&W chronic criteria
MONITORING RECOMMENI	DATIONS	Collect missing core parameter	measurements due to the low pH value. s to represent at least 3 seasons during er detection limits for selenium and

November 2008

FISH CREEK	USE SUPPORT	OVERALL ASSESSMENT
From headwaters to Black River 15060101 – 032 13.8 Miles	A&Wc - Attaining FBC - Inconclusive FC - Attaining Agl Attaining AgL Attaining	Category 2 Attaining some uses

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/25/2001 - 08/14/2002			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Above Black River SRFISO00.01 101200	ADEQ Ambient	3 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, zinc 3 total and 0-1 dissolved: Boron, lead, manganese, mercury 1 total and 1 dissolved: barium, nickel, silver, and thallium	3 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	2 <i>E. coli</i> bacteria 3 Fluoride 3 Total dissolved solids 3 Turbidity	

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient <i>E. coli</i> bacteria samples		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		the A&W chronic criteria. Low Priority – Collect E. coli bacteria samples to represent at least 3 seasons during the assessment period. Use lower lab detection limits for selenium and dissolved mercury.	

FIVE POINT MOUNTAIN TRIBUTARY	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
From headwaters to Pinto Creek 15060103 – 885 2.9 Miles	A&We Impaired PBC Inconclusive	Category 5	Copper	Add copper to 303(d) List. (see discussion below)

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 03/30/2001 – 01/04/2005 NUMBER AND TYPES OF SAMPLES		
DATABASE #				
		Metals	Nutrients - Related	Other
At 60W3 ** SRFPM002.24 102657	ADEQ TMDL	6 total and dissolved: Copper 5 total and dissolved: Selenium,	None	1 Fluoride
Below unnamed mine SRFPM001.69 102658	ADEQ TMDL	and zinc 1 dissolved and total metals:		
Above Bronx Mine SRFPM000.99 102659	ADEQ TMDL	Antimony, arsenic, barium, beryllium, boron, cadmium, chromium, lead, manganese,		
Below Bronx Mine SRFPM000.90 102660	ADEQ TMDL	mercury, nickel, silver, thallium		

^{** 60}W3 was a natural background site located above any mining or other anthropogenic disturbances.

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	12.5 µg/L at 52 mg/L hardness 7.0 µg/L at 28 mg/L hardness 8.6 µg/L at 35 mg/L hardness 7.7 µg/L at 31 mg/L hardness 5.6 µg/L at 22 mg/L hardness 4.4 µg/L at 17 mg/L hardness A&We acute	03/30/2001 – 380 μg/L 02/26/2003 – 45 μg/L 03/04/2003 – 100 μg/L (02/23/2004 – 62 μg/L)* (12/29/2004 – 72 μg/L)* (01/04/2005 – 46 μg/L)*	Impaired – 3 exceedances within a 3-year period. *These exceedances occurred at the natural background site, and were not used in determining impairment.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Pinto Creek copper TMDL and site specific copper standard development. Copper loadings from this tributary will be addressed in the Pinto Creek copper TMDL currently being developed.	
MONITORING RECOMMENDATIONS		High Priority -Collect addition development as needed.	onal samples to support TMDL
		Use lower detection limits fo	or selenium and dissolved mercury.

GIBSON MINE TRIBUTARY	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
	A&Ww – Impaired FBC – Inconclusive FC – Inconclusive	Category 4A Not Attaining	Copper	Currently undergoing a Phase II copper TMDL.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/22/2000 – 03/	05/2004	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
At Pinto Creek SRGIB000.11 101071	ADEQ TMDL	31-50 dissolved and total metals: Copper and zinc 1 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, lead, manganese, mercury, nickel, silver, thallium	4 samples: Dissolved oxygen 17 pH	1 Fluoride 1 Turbidity

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	4.9 µg/L at 34 mg/L hardness 9.1 µg/L at 66 mg/L hardness 9.3 µg/L at 68 mg/L hardness 78 µg/L at 56 mg/L hardness 12.2 µg/L at 90 mg/L hardness 14.7 µg/L at 110 mg/L hardness 5.5 µg/L at 39 mg/L hardness 6.6 µg/L at 47 mg/L hardness 15.4 µg/L at 140 mg/L hardness 7.5 µg/L at 54 mg/L hardness A&Ww acute	03/05/2004 - 2,400 μg/L 08/26/2003 - 4,200 μg/L 03/04/2003 - 7,000 μg/L 02/27/2003 - 7,400 μg/L 02/15/2003 - 6,000 μg/L 03/30/2001 - 2,300 μg/L 03/08/2001 - 2,100 μg/L 02/16/2001 - 2,500 μg/L 01/12/2001 - 5,600 μg/L 10/22/2000 - 5,900 μg/L	Impaired – Exceeded standards during all 10 monitoring periods – 9 exceedances in the last 3 years of monitoring.
Low pH	<6.5 SU A&Ww, FBC	03/05/2004 – 6.0 SU 08/26/2003 – 5.7 SU 03/04/2003 – 6.2 SU 02/27/2003 – 6.0 SU 02/15/2003 – 5.7 SU 03/08/2001 – 6.4 SU 01/12/2001 – 5.9 SU 10/22/2000 – 5.4 SU	Inconclusive – Did not meet standards in 8 of 10 sampling events (13 of 17 samples). Binomial method requires a minimum of 5 exceedances and 20 samples to list as impaired. (See discussion below)

DATA GAPS AND MONITORING NEEDS				
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
pН	Missing most core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.	
DISCUSSION OF EXCEEDANCES		Gibson Mine tributary is heavily impacted by mining activities; however, remediation activities are currently trying to address this contamination. Copper loadings from this tributary will be addressed in the Pinto Creek copper TMDL currently being developed.		
MONITORING RECOMMENDATIONS			al samples to support TMDL development as mits for selenium and dissolved mercury.	

GOLD GULCH	USE SUPPORT	OVERALL ASSESSMENT	
The state of the s	A&We – Inconclusive PBC – Inconclusive	Category 3 Inconclusive	

TE NAMES AGENCY PURPOSE		SAMPLING PERIODS: 01/06/2000 – 04/03/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
North of #3 tailing impoundment \$RGDG000.21 103442	BHP Permit	33 total and 3 dissolved metals: Copper, selenium, zinc 23-33 total metals only: Arsenic,	21 samples: Dissolved oxygen 42 samples: pH	30 Turbidity	
At weir SRGDG000.03 102666	BHP Permit	beryllium, cadmium, and magnesium			

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances				

DATA GAPS AND MONITORING NEEDS				
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Need dissolved lead to assess A&We.		Lab detection limit for selenium was higher than A&W chronic criteria.	
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Pinto Creek copper TMDL ansite specific copper standard development. Copper loadings from this tributary will be addressed in the Pinto Creek copper TMDL currently being developed.		
MONITORING RECOMMENDATIONS		High Priority —Collect additional samples to support TMDL development as needed.		
			ers to represent at least 3 seasons during lower detection limits for selenium.	

GREENBACK CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Tonto Creek 15060105 005	A&Ww - Attaining FBC - Attaining	Category 1	
16.4 Miles	FC - Attaining AgL - Attaining	Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 11/28/2	001 – 05/08/2002	
DATABASE #		NUMBER AND TYPES OF SA	MPLES	
		Metals	Nutrients - Related	Other
Below Conway Ranch SRGRE009.81 101221	ADEQ Ambient	3 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, zinc 3 total and 0-2 dissolved: Boron, lead, manganese, mercury	3 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	3 E. coli bacteria 3 Fluoride 3 Total dissolved solids 3 Turbidity

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances				

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limit for selenium was higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority –Use a lower lab detection limit for selenium.	

HAIGLER CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to unnamed tributary at 341223 / 1110011 15060105 – 012A 15.4 Miles	A&Wc - Attaining FBC - Attaining FC - Attaining Agl Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 12/18/20	01 – 08/29/2002			
DATABASE #		NUMBER AND TYPES OF SAM	NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other		
Near Boy Scout Camp SRHAG009.01 100372	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc 4 total metals only: Boron, lead,	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	3 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids 4 Turbidity		

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances		1	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
3 744 - 1	Core parameters collected.		Lab detection limit for selenium was higher than the A&W chronic criteria.
MONITORING RECOMMENT	DATIONS	Low Priority –Use a lower la	b detection limit for selenium.

HANNAGAN CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Beaver Creek 15060101 034 7.2 Miles	A&Wc – Inconclusive FBC – Inconclusive FC – Inconclusive AgL – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE:	04/09/2002 – 03/23/2004	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other
At Highway 181 SRHAN002.27 102149	ADEQ Ambient		5-7 samples: Total phosphorus, dissolved oxygen, pH	7 Total dissolved solids 4 Suspended sediment concentration
Above Beaver Creek SRHAN000.06 102141	ADEQ Ambient			4 Turbidity

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Wc	06/20/2003 – 6.2 mg/L	Attaining Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Flow at 0.05 cfs. Nutrient tested showed low concentration (phosphorus 0.068 mg/L).
Phosphorus	0.8 mg/L Single sample maximum A&Wc, FBC	08/27/2003 – 6.2 mg/L	Inconclusive – Only 1 exceedance in 7 samples. (Binomial) Occurred during very high flow (10.3 cfs)
Suspended sediment concentration	Geometric mean 80 mg/L A&Wc	08/27/2003 – 3,500 mg/L 03/10/2004 – 95 mg/L 03/23/2004 – 135 mg/L	Attaining – Exceeded 80 mg/L on 3 of 7 monitoring events. Two of the results were not included in the geometric mean calculation, because flows were elevated (3,500 mg/L and 135 mg/L). Using the remaining samples, the geometric mean standard was not exceeded.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Phosphorus	Insufficient core parameters			
MONITORING RECOMMENDATIONS		Medium Priority –Collect more phosphorus and suspended sediment concentration data due to exceedances. Recommend using biocriteria assessments and bottom deposits implementation procedures in this reach, when they are adopted, due to high levels of suspended sediment during flood flows. Collect core parameters to represent at least 3 seasons during the		

HAUNTED CANYON	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Pinto Creek 15060103 – 879 6.8 Miles	A&Ww – Inconclusive FBC – Attaining FC – Attaining	Category 2 Attaining some uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 03/23/2000 – 01/14/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Below Powers Gulch SRHNC000.45 101131 At Carlota Weir SRHNC000.14 101072	ADEQ Ambient And TMDL ADEQ TMDL	19 total and 61 dissolved: Copper 3-15 total and dissolved: Antimony, arsenic, barium, beryllium, cadmium, chromium, lead, nickel, selenium, silver, thallium, zinc	5-7 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus 10 Dissolved oxygen, 26 pH	4 E. coli bacteria 9 Fluoride 5 Total dissolved solid: 6 Turbidity	
		8 total and 0-2 dissolved: Boron, manganese, mercury			

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	7.6 µg/L at 55 mg/L hardness 13.2 µg/L at 98 mg/L hardness A&Ww acute	12/30/2004 – 22 μg/L 03/10/2004 – 17 μg/L	Inconclusive – ADEQ will collect further monitoring because weight-of-evidence does not support listing this reach as impaired. (See discussion below)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Collected all core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.	
DISCUSSION OF COPPER EXCEEDANCES		for a margin of er on 03/10/2004 cc be an exceedance. 2. Both exceedances five samples collect Coulch) were below copper ore body the exceedances of due to natural cortain sample on 03/10/2 than 1 cfs), which represented natural cortains and the contains and t	are based on calculated hardness. Allowing for in the analysis, the acute copper criteria ould be as high as $17 \mu g/L$, which would not cocurred at the Carlota Weir; however, all cted 3/10 mile upstream (below Power of the lab reporting limit of $10 \mu g/L$. A rich is known to exist near the lower site where eccurred; therefore the exceedances may be additions (not a violation of standards). The 2004 was collected during low flow (less further supports the proposal that it all background for this site.	
MONITORING RECOMMENDATIONS			opper data to support Phase II copper ion limits for selenium and dissolved	

HAY CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to West Fork Black River 15060101 353 4.5 Miles Unique Water	A&Wc - Inconclusive FBC - Inconclusive FC - Inconclusive AgL - Inconclusive	Category 3 Inconclusive	

MONITORING USED IN THI SITE NAMES AGENCY PURPOSE		SAMPLING PERIOD: 11/15/200	01-05/05/2004	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
In Exclusion area SRHAY003.25 102121	ADEQ Special study	2 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper,	2 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus,	1 <i>E. coli</i> bacteria 2 Fluoride 2 Total dissolved solids
Above West Fork Black River SRHAY000.04 101299	ADEQ Ambient and Special Study	zinc 2 total and 0-1 dissolved: Boron, lead, manganese, mercury	nitrite/nitrate, total Kjeldahl nitrogen	8 Suspended sediment concentration 8 Turbidity

EXCEEDANG	- []		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Insufficient core parameters	Insufficient sampling events	Lab detection limit for selenium is higher than A&Wc chronic criteria.	
MONITORING RECOMMEND	MONITORING RECOMMENDATIONS		Low Priority -Collect core parameters to represent at least 3 seasons during the assessment period. Use a lower lab detection limit for selenium.	

HOME CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to West Fork Black River 15060101 339 9.1 Miles	A&Wc Inconclusive FBC Inconclusive FC Inconclusive AgL Inconclusive	Category 3 Inconclusive	

SITE NAMES AGENCY ID # PURPOSE		SAMPLING DATE:	04/16/2003 – 03/23/2004		
DATABASE #		NUMBER AND TYPES OF SAMPLES	PES OF SAMPLES		
		Metals	Nutrients – Related	Other	
Above fish barrier SRHOM001.01 102128	ADEQ Special study		1 sample: Total phosphorus, 4 samples: Dissolved	2 Total dissolved solids 6 Suspended sediment concentration	
Above West Fork Black River SRHOM000.02 102129	ADEQ Special study		oxygen and pH	6 Turbidity	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances				

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	
MONITORING RECOMMEN	DATIONS	Low Priority -Collect core para during the assessment period.	ameters to represent at least 3 seasons

HORTON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Beaver Creek 15060101 036 4.6 Miles	A&Wc – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE:	04/15/2003 – 03/23/2004	
DATABASE #	NUMBER AND TY	PES OF SAMPLES		
	Metals	Nutrients – Related	Other	
Above Forest Road #26 SRHRT002.27 102149	ADEQ Ambient		2 samples: Total phosphorus, dissolved oxygen, pH	1 Total dissolved solids 3 Suspended sediment concentration 3 Turbidity

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances				

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	
MONITORING RECOMMEND	PATIONS	Low Priority -Collect core para during the assessment period.	ameters to represent at least 3 seasons

JK MOUNTAIN TRIBUTARY	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to West Fork Pinto Creek 15060103 – 873 1.1 Miles	A&We – Inconclusive PBC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 03/05/2004; 01/04/2005			
DATABASE #		NUMBER AND TYPES OF SA	MPLES		
		Metals	Nutrients - Related	Other	
Above West Fork Pinto	ADEQ	2 dissolved and total metals:			
Creek	TMDL	Copper, selenium, zinc			
SRJKM000.22		2 pH			
102668					

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	9.1 µg/L at 37 mg/L hardness 13.9 µg/L at 58 mg/L hardness A&We acute	01/04/2005 – 18 μg/L 03/05/2004 – 28 μg/L	Attaining –Field investigations for the Pinto Creek TMDL have concluded that copper loads are entirely due to natural background conditions. Exceedances entirely due to natural background are not violations of copper criteria and are not used to list a surface water as impaired. This data was used to develop a site-specific standard for Pinto Creek.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameter	Insufficient sampling events	Lab detection limit for selenium was higher than A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority -Collect core parameters to represent at least 3 season during an assessment period.	
		Use lower detection limits fo	r selenium.

MEAD CANYON	USE SUPPORT	OVERALL ASSESSMENT	
	A&We - Inconclusive PBC - Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATES: 03/05/2004; 12	/30/2004	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
Below MF Ranch SRMEC001.13 102655	ADEQ TMDL	2 dissolved and total metals: Copper and zinc 2 pH		
At Forest Road #349 SRMEC000.53 102656	ADEQ TMDL			

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	14.2 µg/L at 59 mg/L hardness 9.3 µg/L at 38 mg/L hardness A&We acute	03/05/2004 – 22 μg/L 12/30/2004 – 67 μg/L	Attaining –Field investigations for the Pinto Creek TMDL have concluded that copper loads are entirely due to natural background conditions. Exceedances entirely due to natural background are not violations of copper criteria and are not used to list a surface water as impaired. This data was used to develop a site-specific standard for Pinto Creek.
Low pH	>6.5 SU A&We, PBC	03/05/2004 - 5.3 SU	Inconclusive – Did not meet standards in 1 of 2 sampling events. (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
рН	Insufficient core parameters	Insufficient sampling events	Lab detection limit for selenium was higher than the A&W chronic criteria
MONITORING RECOMMENDATIONS		Medium Priority -Collect pH s	amples due to the low pH value.
		Collect core parameters to rep assessment period. Use a lower	resent at least 3 seasons during an r detection limit for selenium.

NORTH FORK BEAR WALLOW CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Bear Wallow Creek 15060101 – 022 5.2 Miles Unique Water	A&Wc – Inconclusive FBC – Inconclusive FC – Inconclusive AgL – Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATES: 11/14/2001; 06/11/2002 NUMBER AND TYPES OF SAMPLES			
DATABASE #					
		Metals	Nutrients – Related	Other	
Just above South Fork Bear Wallow Creek SRNBE000.10 101262	ADEQ Ambient	Ambient	2 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, manganese, mercury, zinc	2 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	2 <i>E. coli</i> bacteria 2 Fluoride 2 Total dissolved solids 2 Turbidity
		2 total and 0-1 dissolved: Boron, lead, manganese, mercury			

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameter	Insufficient sampling events	Lab detection limit for selenium was higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS			ameters to represent at least 3 seasons Use a lower lab detection limit for the

PINAL CREEK USE SUPPORT OVERALL ASSESSMENT
From Lower Pinal Creek WTP A&Ww – Inconclusive Category 2 FBC – Attaining
discharge to Salt River 15060103 – 280D Attaining AgL – Attaining some uses

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 02/16/2000 – 04/28/2005				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
At Setka Ranch SRPNL006.87 101491 At site Z2.2 SRPNL006.70	USGS Pinal Group Effectiveness USGS Special study	93-173 total and dissolved metals: Beryllium, cadmium, chromium, copper, manganese, nickel, zinc 25-60 total and dissolved metals:	22 samples: Ammonia, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	22 E. coli bacteria 11 Fluoride 8 Total dissolved solids 22 Suspended sediment concentration		
101503 At site Z4 SRPNL006.62	USGS Special study	Antimony, arsenic, barium, boron, lead, thallium,	109 Dissolved oxygen	22 Turbidity		
101504	openii staay	17-25 total and dissolved:	273 pH			
At site Z4.3 SRPNL006.54 101505	USGS Special study	Selenium, silver 25 total and 4 dissolved: Mercury				
At site Z4.7 SRPNL006.49 101507	USGS Special study					
At site Z5 SRPNL006.41 101509	USGS Special study					
At site Z5.7 SRPNL006.24 101510	USGS Special study					
At site Z6.2 SRPNL006.17 101511	USGS Special study					
At site Z7 SRPNL005.96 101513	USGS Special study					
At USGS site SRPNL005.82 101515	USGS Special study					
At size Z9A SRPNL005.65 101516	USGS Special study					
At site Z105W SRPNL005.51 102171	USGS Special study					
At site JJ15 SRPNL005.12 101518	USGS Pinal Group Effectiveness					
At Inspiration Dam SRPNL003.79 100727	USGS Pinal Group Effectiveness					

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Excluded metals e	exceedances and low pH values be	fore treatment initiated in	2001
Cadmium (dissolved)	6.22 μg/L at >400 mg/L hardness A&Ww chronic	07/14/2004 – 7.0 μg/L	Inconclusive – One exceedance the assessment period. Occurred during normal flow.
Chromium	100 μg/L FBC	12/08/2004 – 140	Attaining – Only 1 exceedance in 70 samples (Binomial)
Dissolved oxygen	6.0 mg/L A&Ww	06/13/2000 – 4.7 mg/L 08/20/2000 – 5.5 mg/L 10/17/2000 – 5.5 mg/L 01/25/2001 – 4.8 mg/L 04/05/2001 – 1.7 mg/L 06/12/2001 – 5.5 mg/L 08/07/2001 – 3.8 mg/L 01/16/2002 – 5.4 mg/L 05/27/2003 – 4.0 mg/L	Attaining Low dissolved oxygen due to natural conditions of ground water upwelling in the area.
pH	>6.5 SU	05/18/2004 – 5.4 mg/L 05/27/2003 – 6.4 SU	Attaining – Surface water treatment in 2001. Only
рп	A&Ww, FBC, AgL	03/21/2003 - 6.430	1 low pH in 63 monitoring events. (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Dissolved cadmium	Collected all core parameters		Lab detection limits for dissolved metals (beryllium, cadmium, chromium, copper, mercury, nickel, silver, and zinc) and selenium were higher than A&W criteria in at least 6 samples.
MONITORING RECOMMENDATIONS		Medium Priority –Collect additional dissolved cadmium and dissolved zinc samples due to exceedances. Use lower lab detection limits for dissolved metals and total selenium.	

PINTO CREEK From headwaters to unnamed	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
tributary at 331927 / 1105456	A&Ww – Impaired FBC – Inconclusive FC – Inconclusive AgI – Inconclusive AgL – Inconclusive	Category 4A Not Attaining	Copper	Currently undergoing a Phase II copper TMDL.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 02/16/200	1 – 03/05/2004	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
At Simpson Dam	ADEQ	7 dissolved and 6 total copper	2 samples: Dissolved	
SRPNT033.02	Ambient	2 total and 3 dissolved zinc	oxygen and pH	
102428		7 pH		

EXCEEDAN	ICES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper	500 μg/L AgL	08/26/2003 – 1300 μg/L 03/05/2004 – 1000 μg/L	Remains impaired – 2 exceedances in 6 samples.
Copper (dissolved)	5.7 µg/L at 40 mg/L hardness 16.0 µg/L at 120 mg/L hardness A&Ww acute	02/27/2003 – 16 μg/L 03/05/2004 – 18 μg/L	Remains impaired – 2 exceedances in the last 3 years of monitoring
pН	>6.5 µg/L A&Ww, FBC, AgL	08/26/2003 – 5.9 μg/L 03/05/2004 – 5.7 μg/L	Inconclusive – Only 2 exceedances in 6 sampling events. (Binomial method requires a minimum of 5 exceedances and 20 samples to assess as impaired.)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
pH Insufficient core parameters			Lab detection limit for selenium was higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		High Priority –Collect copper samples to support development of the Pha- II copper TMDL and site specific copper standards. Collect additional pH samples due to exceedances.	
		Use a lower lab detection l	

PINTO CREEK From unnamed tributary at	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
331927 / 1105456 to West Fork Pinto Creek 15060103 – 018B 15.3 Miles	A&Ww – Impaired FBC – Attaining FC – Attaining AgI – Attaining AgL – Attaining	Category 4A Not Attaining	Copper	Currently undergoing a Phase II copper TMDL.

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 02/16/2000 - 04/28/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
	*	Metals	Nutrients - Related	Other	
Above Henderson Ranch Mines SRPNT032.25 101039	ADEQ TMDL	96 total and 80 dissolved: Copper 58 total and 38 dissolved: Zinc		9 Fluoride 7 Turbidity	
At Henderson Ranch Mines SRPNT031.89 102429	ADEQ TMDL	33 total and 8 dissolved: Arsenic, beryllium, cadmium, manganese. 26 total metals only: Selenium		·	
Below Henderson Ranch Mines SRPNT031.74 101061	ADEQ TMDL	8-9 dissolved and total metals: Antimony, barium, boron, chromium, lead, nickel, silver,			
Above Gibson Mine tributary SRPNT028.85 101062	ADEQ TMDL	8 total metals only: Mercury			
At old Highway 60 SRPNT027.51 101064	ADEQ TMDL	112 pH			
Above Cottonwood Gulch and below Cactus Breccia SRPNT024.85 103311	ADEQ TMDL And BHP Effectiveness				
Above Carlotta Cactus Breccia SRPNT024.04 102430	ADEQ TMDL And BHP Effectiveness				
Below Carlotta Cactus Breccia SRPNT023.29 102431	ADEQ TMDL				
Below Haunted Canyon USGS # 09498501 SRPNT020.12 101068	ADEQ TMDL				
Below USGS gage SRPNT019.77 102432	ADEQ TMDL				
Below Iron Bridge SRPNT019.23 103313	BHP Effectiveness				

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper	500 μg/L – AgL 1300 μg/L FBC	10/23/2000 – 810 µg/L 02/25/2003 – 1172 µg/L 08/26/2003 – 1600 µg/L 03/05/2004 – 1700 µg/L 12/29/2004 – 1600 µg/L	Remains impaired – 3-5 exceedances in 28 sampling events (3-6 of 96 samples). (Binomial method requires a minimum of 10 samples with no exceedances.)
Copper (dissolved)	Varies by hardness between 2.7 to 49.6 µg/L) A&Ww acute	10/23/2000 - 920 µg/L 01/13/2001 - 150 µg/L 02/16/2001 - 210 µg/L 03/06/2001 - 260 µg/L 03/30/2001 - 81 µg/L 02/13/2003 - 530 µg/L 02/25/2003 - 820 µg/L 03/04/2003 - 480 µg/L 03/17/2003 - 340 µg/L 04/21/2003 - 70 µg/L 08/26/2003 - 230 µg/L 02/23/2004 - 93 µg/L 03/05/2004 - 450 µg/L 12/29/2004 - 83 µg/L 01/04/2005 - 77 µg/L	Remains impaired – 15 exceedances in 15 sampling events.
pН	<6.5 SU A&Ww FBC AgL	10/23/2000 - 5.6 SU 02/15/2003 - 5.7 SU 08/26/2003 - 5.9 SU 03/05/2004 - 5.7 SU	Attaining—Only 4 exceedances in 28 sampling events (Binomial method requires a minimum of 6 exceedances in 28 samples.)
Selenium	2.0 µg/L A&Ww chronic	04/22/2003 - 3 μg/L 02/03/2004 - 3 μg/L* 10/18/2004 - 3 μg/L*	Inconclusive – 1 exceedances during the assessment period. *Exceedances may be due to groundwater upwelling.
Zinc (dissolved)	232 μg/L at 224 mg/L hardness 379.3 μg/L at >400 μg/L hardness	10/23/2000 – 390 µg/L 08/26/2003 – 5,100 µg/L	Inconclusive – 2 exceedances; however, exceedances occurred more than 3 years apart. (A minimum of 2 exceedances in a 3-year period are required to determine impairment.)

DATA GAPS ANI	MONITORING NEED	S	
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Selenium, dissolved zinc	Insufficient E. coli bacteria, total nitrogen, and total phosphorus to assess FBC and A&Ww		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		II copper TMDL and site sp Collect additional selenium Use lower lab detection lin The old turbidity criterion Collect suspended sedimen	and dissolved zinc samples due to exceedances. nits for selenium and dissolved mercury. (50 NTU) was exceeded in 7 of 39 samples. t concentration (SSC) samples. Also, recommend and bottom deposits implementation

PINTO CREEK From West Fork Pinto	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Creek to Roosevelt Lake 15060103 - 018C 17.8 Miles	A&Ww – Impaired FBC – Impaired FC – Attaining Agl – Attaining AgL – Impaired	Category 5 (Selenium) Impaired Category 4A (Copper) Not Attaining	Copper, selenium	Added selenium in 2004. Currently undergoing a Phase II copper TMDL.

SITE NAMES	AGENCY	SAMPLING DATE: 01/31/2000 - 01/11/2005				
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES				
DATABASE #		Metals	Nutrients - Related	Other		
Above Pinto Valley Weir SRPNT014.93 102436	ADEQ TMDL	31 total and 35 dissolved: Copper 26 total and 25 dissolved: Zinc 22-23 total and dissolved:	20-21 samples: Ammonia, nitrate-nitrite, total nitrogen, total	19 <i>E. coli</i> bacteria 23 Fluoride 20 Total dissolved solid:		
At Pinto Valley Weir USGS #09498502 SRPNT014.51 101070	ADEQ TMDL	Antimony, arsenic, beryllium, cadmium, chromium, lead manganese. 9-10 dissolved and total metals:	phosphorus, 24 samples: Dissolved oxygen 33 samples: pH	10 Suspended sediment concentration 21 Turbidity		
Above Henderson Ford SRPNT008.48 100346	ADEQ TMDL	Barium, nickel, silver, thallium 22-23 total and 0-2 dissolved: Boron, manganese,				
At State Route 188 SRPNT004.37 102437	ADEQ TMDL	22 total 4 dissolved: Mercury 1-2 total and dissolved: Selenium				

POLLUTANT	STANDARD	DATES	DESIGNATED USE SUPPORT
	UNIT DESIGNATED USES	EXCEEDANCES	SUPPORTING EVIDENCE AND COMMENTS
Cadmium	50 μg/L for AgI, AgL 84 μg/L for FC	04/27/2004 – 200 μg/L	Attaining – 1 exceedance in 23 samples. (Binomial)
Copper (dissolved)	20.9 µg/L at 160 mg/L hardness 22.2 µg/L at 170 mg/L hardness A&Ww acute	03/05/2004 – 27 μg/L 01/05/2005 – 32 μg/L	Remains impaired – 2 exceedances in the last 3 years of monitoring. (Chronic criteria also exceeded in 4 samples.)
Dissolved oxygen	6.0 mg/L A&Ww	08/31/2004 – 3.9 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow (0.05 cfs) and ground water upwelling. Nutrients are low (nitrogen 0.28 mg/L and phosphorus 0.024 mg/L)
Selenium	2.0 µg/L A&Ww chronic	01/31/2000 – 7.6 μg/L 01/19/2001 – 9.0 μg/L	Remains Impaired – 2 exceedances during the assessment period. Due to the lab reporting limit for selenium, 16 other samples could not be used to determine attainment (see note below)

DATA GAPS AND MC	NITORING NEE	DS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Collected all core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.	
MONITORING RECOMMENDATIONS		of TMDLs and site specific	High Priority –Collect copper and selenium samples to support developmen of TMDLs and site specific copper standards.	
		Use lower lab detection lin	nits for selenium and dissolved mercury.	

POWERS GULCH	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Haunted Canyon 15060103 – 884 3.8 Miles	A&We – Inconclusive PBC – Inconclusive	Category 3 Inconclusive	

SITE NAMES AGENCY ID # PURPOSE		SAMPLING DATE: 04/17/2003	2 – 04/28/2005	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
Near Haunted Canyon \$RPWG000.15 102665	BHP Ambient ADEQ TMDL	8-9 dissolved and total metals: Copper, selenium, and zinc 8 total metals only: Arsenic, beryllium, cadmium, manganese,		8 Turbidity

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Copper (dissolved)	9.8 µg/L at 40 mg/L hardness A&We acute	03/10/2004 – 21 μg/L	Inconclusive – Only 1 exceedance in the last 3 years of monitoring.		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Copper	Insufficient core parameters to assess designated uses		Lab detection limit for selenium was higher than A&W chronic criteria.
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Pinto Creek copper TMDL ansite specific copper standard development. Copper loadings from this tributary will be addressed in the Pinto Creek copper TMDL currently being developed.	
MONITORING RECOMMENDATIONS		High Priority -Collect addition development as needed.	onal samples to support TMDL
		Use lower detection limits fo	or selenium.
		Collect core parameters to re assessment period.	epresent at least 3 seasons during an

ROOSEVELT LAKE	USE SUPPORT	OVERALL ASSESSMENT	
15060103 1240 18,350 Acres	A&Ww – Inconclusive FBC – Inconclusive FC – Attaining DWS – Attaining Agl – Attaining AgL – Attaining	Category 2 Attaining some uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 01/31/2000 – 01/11/2005				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
A dam SRROO-A 100075	UA and AGFD Ambient	9-25 total and 3-6 dissolved: Arsenic, cadmium, chromium, copper, lead, nickel, silver, zinc	68-90 samples: Ammonia, nitrate-nitrite, total nitrogen, dissolved	3 <i>E. coli</i> bacteria 24 Fluoride 61 Total dissolved solids		
At Salt River Inlet SRROO-B 10076	UA and AGFD Ambient	9-25 total and 0-2 dissolved: Antimony, beryllium, boron,	oxygen, pH 18 samples: Total phosphorus.	21 Turbidity		
At Tonto Creek Inlet SRROO-C 100077	UA and AGFD Ambient	manganese, selenium, thallium				
Mid lake SRROO-E 100079	UA and AGFD Ambient					
At Marina SRROO-MAR 101711	UA Ambient					
At Windy Hill SRROO-WIND 102557	AGFD Ambient					

EXCEEDANCES						
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS			
Copper	500 μg/L AgL	10/08/2002 – 715 μg/L	Attaining – 1 exceedance in 27 samples. (Binomial)			
Dissolved oxygen	6.0 mg/L A&WW	10/08/2004 – 4.5 mg/L	Attaining – One low dissolved oxygen out of 75 samples. (Binomial)			
Lead	15 μg/L DWS and FBC	07/19/2002 – 35 μg/L	Attaining – 1 exceedance in 24 samples. (Binomial)			
Manganese	980 μg/L DWS	07/19/2002 – 1680 μg/L 12/17/2003 – 1120 μg/L	Attaining – Only 2 exceedances in 30 samples. (Binomial)			
рН	<9.0 SU A&Ww, FBC, AgI, AgL, DWS	03/06/2003 - 9.3 SU 09/30/2004 - 10.4 SU	Attaining – only 2 exceedances in 79 samples. (Binomial)			

EXCEEDANCES NEEDING	MISSING CORE	MISSING SEASONAL	DETECTION LIMITS NOT LOW
MORE SAMPLES TO ASSESS	PARAMETERS Need composite nitrogen and phosphorus samples to assess A&Wc and FBC as attaining uses (see comment below)	DISTRIBUTION	ENOUGH
DISCUSSION OF SITE SPECIFIC N	IUTRIENT STANDARDS	composite samples collecte composite samples were coperiod. This standard is to be repla implementation procedure Review process. The nitrogen criterion (1.0 in the top meter. At site B,	trandards established for this lake require d at the surface, 2 meter, and 5 meter depths. No ollected and analyzed during this assessment ced by the proposed lake narrative nutrient is currently being adapted through the Triennial mg/L) was exceeded in 12 of 89 samples collected 1.0 mg/L was exceeded in 6 of 23 samples (which vever, since these were not composite samples,
MONITORING RECOMMENDATIONS		Medium Priority –New me standard should be applied	thods for implementing the narrative nutrient to this lake once adopted.

RYE CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Tonto Creek	A&WW - Attaining FBC - Inconclusive	Category 2	
II I Z.O ZYMES	FC – Attaining AgL – Attaining	Attaining some uses	

MONITORING USED IN THIS ASSESSMENT					
SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 01/09/2002 – 09/04/2002			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Above Rye Arizona SRRYE007.56 102832	AGFD Ambient	4 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper,	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	2 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids 4 Turbidity	
Below Rye Arizona SRRYE006.15 102833	AGFD Ambient	zinc 4 total metals only: Boron, lead,			
Above Bridge SRFYE001.27 101297	ADEQ Ambient	manganese, mercury			

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Dissolved oxygen	6.0 mg/L A&Ww	04/18/2002 – 5.79 mg/L 09/04/2002 – 2.72 mg/L	Attaining – Low dissolved oxygen due to natural conditions related to low flow and ground water upwelling. Flow 0.3 – 0.5 cfs. Low nutrients (nitrogen 0.2 to 0.03 mg/L; phosphorus 0.01to 0.03 mg/L).		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	E. coli bacteria needed to assess FBC		Lab detection limits for selenium was higher than the A&W chronic criteria
MONITORING RECOMMENDATIONS		Low Priority –Use a lower lab detection limit for selenium. Collect missing core parameters to represent at least 3 seasons during an assessment period.	

SAGUARO LAKE	USE SUPPORT	OVERALL ASSESSMENT	
15060106A 1290 1025 Acres	A&Wc - Inconclusive FBC - Inconclusive FC - Attaining DWS Attaining AgI - Attaining AgL - Attaining	Category 2 Attaining some uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/30/2000 – 11/05/2004			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients – Related	Other	
At dam SRSAG-A 100082	ADEQ, AGFD, UA Ambient	6-16 total and 5 dissolved: Antimony, arsenic, barium, beryllium, boron, cadmium,	40-44 samples: Ammonia, total nitrogen, nitrite/nitrate, total	16 <i>E. coli</i> bacteria 25 Fluoride 14 Total dissolved solids	
Southeast of Bagley Flat SRSAG-B 101810	UA, AGFD Ambient	chromium, copper, lead, manganese, nickel, selenium, silver, and zinc 15 total metals only: Mercury 4 total metals only: Thallium	Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	19 Turbidity	
Near Perrigrin Cove SRSAG-2 102559	AGFD Ambient				
At Bagley Flat SRSAG-BAG 101001	AGFD Ambient				
At Butcher Jones SRSAG-BJ 100081	ADEQ, UA Ambient				
At campground SRSAG-MFLAT 101698	AGFD, UA Ambient				
Marina site 1 SRSAG-MAR1 100994	ADEQ, UA Ambient				
Marina site 2 SRSAG-MAR2 100995	ADEQ, AGFD Ambient				

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Wc	06/27/2001 – 6.0 mg/L – MFLAT 08/06/2001 – 2.2 mg/L – 1 & B 10/15/2001 – 6.1 mg/L – 1 06/04/2003 – 6.6 mg/L – B 08/20/2004 – 6.4 mg/L – A	Inconclusive – Low dissolved oxygen in the top meter at least at one site during 5 of 19 sampling events (7-day periods). Low dissolved oxygen in 6 of 42 samples in the top meter. (Binomial method requires a minimum of 5 exceedances and 20 samples. At 42 samples, impairment occurs at 8 exceedances.)
Fluorine	4000 μg/L DWS	01/18/2001 – 15,800 μg/L	Attaining – Only 1 exceedance in 25 samples. (Binomial) Data reliability is questionable because result was several levels of magnitude higher than other values reported.
pH (high)	<9.0 SU	06/27/2001 - 9.6 SU 05/03/2002 - 9.4 SU	Attaining – pH exceeded standards in 2 of 19 sampling events (2 of 42 samples). (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Dissolved oxygen	Need composite nitrogen and phosphorus samples to assess A&Wc and FBC		Lab detection limit for dissolved mercury was higher than the A&W chronic criteria.	
DISCUSSION OF SITE SPECIFIC NUTRIENT STANDARDS .		Nitrogen and phosphorus standards established for this lake require composite samples collected at the surface, 2 meter, and 5 meter depths. No composite samples were collected and analyzed during this assessment period. This standard is to be replaced by the proposed lake narrative nutrient implementation procedures currently being adopted through the Triennial Review process. The nitrogen criterion (1.0 mg/L) was exceeded in 8 of 43 samples collected in the top meter, but since these were not composite samples the standard did not apply.		
MONITORING RECOMMENDATIONS		Medium Priority –Collect more dissolved oxygen samples due to exceedances. Low dissolved oxygen and high pH may be symptoms of excess nutrient loading. New methods for implementing the narrative nutrient standard should be applied to this lake once adopted, to determine whether narrative nutrient violations are occurring. Use a lower lab detection limit for dissolved mercury.		

SALT RIVER From Pinal Creek to Roosevelt	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Dam 15060103 004 7.5 Miles	A&Ww – Impaired FBC – Attaining FC – Attaining AgI – Attaining AgL – Attaining	Category 5	Suspended sediment concentration	Add Suspended sediment concentration (SSC)

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 02/16/2000 – 08/31/2004		
DATABASE # NUMBER AND TYPES OF SAMPLES		MPLES		
		Metals	Nutrients – Related	Other
Above Lake Roosevelt USGS #09498500 SRSLR107.43 100745	USGS Ambient	27-28 dissolved and total metals: Antimony, arsenic, barium, boron, beryllium, cadmium, chromium, copper, lead, manganese, nickel, selenium, silver, thallium, and zinc	22-28 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	23 E. coli bacteria 28 Total dissolved solids 28 Suspended sediment concentration 27 Turbidity 13 Cyanide

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Arsenic	50 μg/L FBC	08/05/2002 – 87.7 μg/L 07/22/2003 – 70 μg/L 08/01/2003 – 91 μg/L	Attaining – Only 3 of 28 samples exceeded criterion (Binomial) Exceedances appear related to the Rodeo-Chediski Wildfire in 2002. Fire recovery shown in the five samples taken in 2004, as arsenic averaged 6.8 µg/L.
Chromium	100 μg/L FBC	08/07/2002 – 101.3 μg/L 06/03/2003 – 134 μg/L 07/22/2003 – 170 μg/L 08/01/2003 – 218 μg/L	Attaining – Only 4 of 28 samples exceeded criterion (Binomial) Exceedances appear related to the Rodeo-Chediski Wildfire in 2002. Fire recovery shown in the five samples taken in 2004, as chromium averaged 2 µg/L.
Cyanide	41 μg/L – A&Ww acute 10 μg/L – A&Ww chronic	08/07/2002 – 120 μg/L 07/22/2003 – 30 μg/L 08/01/2003 – 30 μg/L	Inconclusive –Chronic exceedances occurred during elevated flows and may not indicate conditions during a 4-day period. Exceedances appear related to the Rodeo-Chediski Wildfire in 2002. Fire recovery shown in the last 5 samples collected, as cyanide was below the lab detection limit (<10 µg/L).
Dissolved oxygen	6.0 mg/L A&Ww	07/16/2002 – 0.9 μg/L 08/06/2002 – 0.1 μg/L 06/03/2003 – 5.7 μg/L 07/22/2003 – 2.8 μg/L 08/01/2003 – 4.0 μg/L	Inconclusive – 5 of 28 samples showed low DO. (Binomial) Exceedances appear related to the Rodeo-Chediski Wildfire in 2002. Fire recovery shown as all 5 samples taken in 2004 met standards (averaged 8.8 mg/L).
E. coli bacteria	235 CFU/100 ml	07/17/2002 - >2,700 CFU/100 ml 06/03/2003 - 2000 CFU/100 ml 07/22/2003 - 3000 CFU/100 ml 08/01/2003 - 19,000 CFU/100 ml	Inconclusive –4 exceedances in the past 3 years of monitoring. All appear related to the Rodeo-Chediski Wildfire in 2002. Fire recovery shown in the five samples taker in 2004, E. coli bacteria results ranged from 2.0 to 200 CFU/100 ml.

Lead	15 μg/L – FBC 100 μg/L – AgL	07/16/2002 – 131 μg/L 08/05/2002 – 529.7 μg/L 06/03/2003 – 313 μg/L 07/22/2003 – 300 μg/L 08/01/2003 – 414 μg/L	Inconclusive – 5 exceedances in 28 samples. (Binomial) Exceedances appear related to the Rodeo-Chediski Wildfire in 2002. Fire recovery shown in 5 samples collected in 2004, as Lead averaged 3.8 µg/L.
Manganese	10,000 μg/L – Agl 19,699 μg/L FBC Agl	08/05/2002 – 29,733 μg/L 06/03/2003 – 11,000 μg/L 07/22/2003 – 18,100 μg/L	Attaining – 3 of 28 samples exceeded the 10,000 and only 1 exceeded the 19,699. (Binomial) Exceedances appear related to the Rodeo-Chediski Wildfire in 2002. Fire recovery shown in the five samples taken in 2004, as manganese averaged 98 µg/L.
Selenium	2 μg/L A&Ww chronic	08/07/2002 – 2.7 μg/L 07/17/2003 – 3 μg/L 07/22/2003 – 8 μg/L 08/01/2003 – 9 μg/L	Inconclusive – Four exceedances in the assessment period; however, all appear related to the Rodeo-Chediski Wildfire in 2002. Fire recovery shown in the last 4 samples in 2004, as selenium was below the criterion.
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Wc	04/18/2001 - 176 mg/L - 1700 cfs* 09/05/2001 - 307 mg/L - 206 cfs 06/12/2002 - 101 mg/L - 75 cfs 07/16/2002 - 5366 mg/L - 624 cfs* 08/05/2002 - 22,850 mg/L - 2030 cfs* 08/19/2002 - 632 mg/L - 172 cfs 06/03/2003 - 15,300 mg/L - 325 cfs 07/22/2003 - 42,500 mg/L - 1120 cfs* 08/01/2003 - 25,800 mg/L - 627 cfs* 03/31/2004 - 273 mg/L - 1010 cfs* 04/21/2004 - 331 mg/L - 804 cfs* 08/31/2004 - 492 mg/L - 130 cfs	Impaired – SSC criterion of 80 mg/L was exceeded in 12 of 28 sampling events. Seven of the exceedances (*) were not included in the geometric mean calculation, because flows were above the 50th percentile of flow. Using the remaining 21 samples, the geometric mean of a minimum of 4 consecutive samples exceeded 80 mg/L four times. Some of the exceedances were due to the fire in 2002; however, high levels of sediment transport were indicated in 2001 before the fire also. (Note that the old turbidity standard (50 NTU) was also exceeded in 10 of 27 field turbidity samples.)

DATA GAPS AND MONITORING NEEDS						
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH			
Cyanide, dissolved oxygen, lead, selenium, and <i>E. coli</i> collected.		Lab detection limit for dissolved me higher than the A&W chronic criter				
MONITORING RECOMMENDATIONS		High Priority –Collect sediment samples to support development of an SSC TMDL. Recommend using biocriteria assessments and bottom deposits implementation procedures in this reach, when they are adopted. Collect additional cyanide, dissolved oxygen, lead, selenium, and <i>E. coli</i> bacteria samples due to exceedances.				
			limit for dissolved mercury.			

SALT RIVER From Stewart Mountain Dam	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
(Saguaro Lake) to Verde River 15060106A 003	A&Wc - Impaired FBC - Inconclusive FC - Attaining DWS - Attaining AgI - Attaining AgL - Attaining	Category 5	Low dissolved oxygen	Low dissolved oxygen and copper were added to 303(d) List in 2004. Delist copper (see discussion below)

MONITORING US SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 02/01/2000		
DATABASE #		NUMBER AND TYPES OF SAN	APLES	
		Metals	Nutrients - Related	Other
Tubing siteSaguaro Lake Ranch SLSLR054.49 103271	USFS Bacteria only	21-22 dissolved and total metals: Antimony, arsenic, barium, boron, beryllium, cadmium, chromium, copper, lead,	22-23 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total	22 E. coli bacteria 1 Fluoride (22 dissolved) 22 Total dissolved solids 22 Suspended sediment
Below Steward Mountain Dam USGS #09502000 Tubing Bus Stop 2 SRSLR051.32 100746	USGS Ambient	manganese, nickel, selenium, silver, thallium, and zinc 22 total metals only: Mercury	phosphorus, dissolved oxygen, pH	concentration 21 Turbidity
Tubing Bus Stop 4 SLSLR047.21 103272	USFS Bacteria only			
Phon D Sutton Picnic Site SLSLR044.95 103273	USFS Bacteria only			

EXCEEDAN	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Wc	07/27/2000 – 5.9 mg/L 07/25/2001 – 5.5 mg/L 10/03/2001 – 6.0 mg/L 05/10/2002 – 6.5 mg/L 08/29/2002 – 6.5 mg/L 04/04/2003 – 5.1 mg/L 06/27/2003 – 5.5 mg/L 08/08/2003 – 4.5 mg/L 04/26/2004 – 6.4 mg/L 05/06/2003 – 6.3 mg/L	Remains impaired – Did not meet standards in 10 of 23 samples. Low flow (4.2-5.8 cfs) associated with only two measurements. Elevated nitrogen (at 1.24 mg/L) in only 1 sample. (Binomial) (Note: ADEQ has proposed changing the designated use at this lake to A&Ww, which has a dissolved oxygen standard of 6.0 mg/L. This would adjust the number of low dissolved oxygen samples to 5 of 23 samples. It would remain impaired.)
E. coli bacteria	235 CFU/100 ml	08/15/2001 – 300 CFU/100 ml 06/13/2002 – 240 CFU/100 ml	Inconclusive – Exceedances do not exceed the assessment screening value of 300 CFU/100 ml; therefore, ADEQ will do further monitoring before listing the reach as impaired. (See assessment methods concerning this screening value.)

DATA GAPS AND MC	NITORING NEE	:DS	
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limit for dissolved mercury was higher than the A&W chronic criteria.
DISSOLVED COPPER		Delisting copper. In 22 total exceed a surface water qua	al and 22 dissolved samples, copper did not lity standard.
MONITORING RECOMMENDATIONS		High Priority -Collect dissort TMDL.	lved oxygen samples to support development of
		Collect additional <i>E. coli</i> samples due to the exceedances.	
		Use a lower lab detection l	imit for dissolved mercury.

SNAKE RIVER	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Black River 15060101 – 045 6.2 Miles Unique Water	A&Wc - Inconclusive FBC - Inconclusive FC - Inconclusive AgL - Inconclusive	Category 3 Inconclusive	

SITE NAMES AGENCY		SAMPLING DATES: 11/15/2001; 06/12/2002			
ID#	PURPOSE	NUMBER AND TYPES OF SAN			
DATABASE #		Metals	Nutrients - Related	Other	
1.3 miles above Black River SRSNK001.33 101298	ADEQ Ambient	2 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, mercury, zinc	2 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	2 E. coli bacteria 2 Fluoride 2 Total dissolved solid: 2 Turbidity	
		2 total and 0-1 dissolved: Boron, lead, manganese, mercury			

EXCEEDANG	- []		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters to assess any designated uses.	Insufficient sampling events (only 2)	Lab detection limits for selenium was higher than the A&W chronic criteria
MONITORING RECOMMEND	DATIONS		ameters to represent at least 3 seasons Use a lower lab detection limit for the

SOUTH FORK BEAR WALLOW CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Bear Wallow Creek 15060101 258 3.8 Miles Unique Water	A&Wc - Inconclusive FBC - Inconclusive FC - Inconclusive AgL - Inconclusive	Category 3 Inconclusive	

SITE NAMES ID # DATABASE # AGENCY PURPOSE		NUMBER AND TYPES OF SAMPLES			
Above pack trail crossing SRSBE000.13 101261	ADEQ Ambient	2 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc 2 total and 0-1 dissolved: Boron,	2 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	2 E. coli bacteria 2 Fluoride 2 Total dissolved solids 2 Turbidity	

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limit for selenium was higher than A&Wc chronic standards
MONITORING RECOMMEND	PATIONS		meters to represent at least 3 seasons Use a lower lab detection limit for

SPRING CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Tonto Creek 15060105 010	FBC - inconclusive	Category 2	
20.5 Miles	FC Attaining AgL Attaining	Attaining some uses	

SITE NAMES AGENCY ID # PURPOSE		SAMPLING PERIOD: 12/19/20	001 – 09/05/2002	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
	Metals	Nutrients – Related	Other	
West of Young, AZ SRSPI011.54 100380	ADEQ Ambient	3-4 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc 3 total and 0-2 dissolved: Boron, lead, manganese, mercury	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	2 <i>E. coli</i> bacteria 3 Fluoride 3 Total dissolved solids 3 Turbidity

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient <i>E. coli</i> bacteria to assess FBC.		Lab detection limits for selenium was higher than the A&W chronic criteria.
MONITORING RECOMMEND	DATIONS		arameters to represent at least 3 seasons L. Use a lower lab detection limit for

STINKY CREEK	USE SUPPORT	OVERALL ASSESSMENT
From headwaters to Fort Apache Reservation 15060101 – 352A 2.1 Miles	A&Wc – Inconclusive FBC – Inconclusive FC – Inconclusive AgL – Inconclusive	Category 3 Inconclusive

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATES: 11/15/2001	; 06/10/2002	
DATABASE #	_	NUMBER AND TYPES OF SAM	APLES .	
		Metals	Nutrients - Related	Other
Above West Fork Black River SRST1000.38 101303	ADEQ Ambient	2 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc	2 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	1 <i>E. coli</i> bacteria 2 Fluoride 2 Total dissolved solid: 2 Turbidity
		2 total and 0-1 dissolved: Boron, lead, manganese, mercury		

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Wc	06/10/2002 – 5.5 mg/L	Attaining Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Flow 0.46 cfs. Low nutrients (nitrogen 0.4 mg/L, phosphorus 0.06 mg/L)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limit for selenium is higher than A&Wc chronic criteria.
MONITORING RECOMMEND	DATIONS		ameters to represent at least 3 seasons Use a lower lab detection limit for

THOMAS CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Beaver Creek 15060101 285 4.1 Miles	A&Wc - Inconclusive FBC - Inconclusive FC - Inconclusive AgL - Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE:	04/16/2003 – 03/23/2004	
DATABASE #		NUMBER AND TY	PES OF SAMPLES	
		Metals	Nutrients - Related	Other
East Weir #1 SRTHO002.92 102148	ADEQ Special study		2 samples: Total phosphorus, dissolved oxygen, pH	1 Total dissolved solid 3 Suspended sediment concentration
East Weir #2 SRTHO002.86 102147	ADEQ Special study			3 Turbidity
Above Beaver Creek SRTHO000.05 102138	ADEQ Special study			

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Wc	06/20/2003 – 5.6 mg/L	Attaining Low dissolved oxygen due to natural conditions caused by low flow (0.01 cfs) and ground water upwelling. Low nutrients (0.07 mg/L total phosphorus at time)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	
MONITORING RECOMMENI	DATIONS	Low Priority –Collect core para during the assessment period.	ameters to represent at least 3 seasons

TONTO CREEK From headwaters to		USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
unnamed tributary at 341810 / 1110414 15060105 – 013A 8.1 Miles	A II	A&Wc – Impaired FBC – Impaired FC – Attaining Agl – Attaining AgL – Attaining	Category 4A (E. coll) Not attaining (Impaired) Category 5 (phosphorus and low dissolved oxygen) Impaired	E. coli bacteria, and phosphorus	Add phosphorus and low dissolved oxygen. E. coli and TMDL approved in 2005. Implementing strategies to reduce loadings.
		A&Wc – Impaired FBC – Impaired	Category 4A (nitrogen) Not attaining (Impaired) Category 5 (Low dissolved oxygen)	Nitrogen and low dissolved oxygen	EPA listed nitrogen and low dissolved oxygen in 2004. Nitrogen TMDL approved in 2005. Implementing strategies to reduce loadings

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B and Appendix C).

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 05/23/2000 – 10/23/2003				
DATABASE #		NUMBER AND TYPES OF SAM				
		Metals	Nutrients - Related	Other		
At headwater spring SRTON062.89 101016	ADEQ TMDL	5-26 total and dissolved metals: Antimony, arsenic, barium, beryllium, cadmium, chromium,	nitrogen, total phosphorus, total	103 <i>E. coli</i> bacteria 26 Fluoride 23 Total dissolved solide		
Below AGFD Hatchery SRTON062.40 100351	ADEQ TMDL & Ambient	copper, lead, nickel, manganese, mercury, silver, thallium, and zinc	Kjeldahl nitrogen, dissolved oxygen, pH	124 Suspended sediment concentration 167 Turbidity		
Below hatchery mixing zone SRTON062.28 101017	ADEQ TMDL	25-26 Total metals only: Boron, manganese	26 samples: Ammonia			
Above Baptist Camp SRTON061.37 101018	ADEQ TMDL					
Below Baptist Camp SRTON060.50 100352	ADEQ TMDL					
Above Horton Creek and waterfall SRTON059.65 101759	ADEQ TMDL					
Above Horton Creek SRTON059.53 101020	ADEQ TMDL					
Below Horton Creek SRTON059.49 101761	ADEQ TMDL					
Further below Horton Creek SRTON059.44 101021	ADEQ TMDL					
Upstream from campground SRTON058.93 101629	ADEQ TMDL					

Above Kohl's Ranch SRTON058.63 100354	ADEQ TMDL
Below Kohl's Ranch SRTON057.70 100929	ADEQ TMDL
Above Christopher Creek SRTON056.59 101018	ADEQ TMDL
Below Christopher Creek SRTON056.39 100360	ADEQ & USGS Ambient & TMDL

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&W/c	05/23/2000 - 6.0 mg/L 05/21/2002 - 6.2 mg/L 06/11/2002 - 4.9 mg/L 06/25/2002 - 6.3 mg/L 07/09/2002 - 6.5 mg/L 07/22/2002 - 6.5 mg/L 07/08/2003 - 6.0 mg/L 07/21/2003 - 6.3 mg/L 08/18/2003 - 6.3 mg/L 10/22/2003 - 6.1 mg/L	Remains impaired – 10 of 166 samples measured low dissolved oxyger. Ground water upwelling may be the primary cause; however, nutrient loading may also contribute to low dissolved oxygen.
E. coli bacteria	235 CFU/100 ml FBC	09/03/2000 - 659 CFU/100 ml 07/23/2003 - 613 CFU/100 ml 07/30/2003 - >2419 CFU/100 ml 08/06/2003 - 260 CFU/100 ml 08/12/2003 - 520 CFU/100 ml 08/20/2003 >2419 CFU/100 ml	Remains impaired – 6 exceedances during the assessment period.
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Wc	07/23/2002 – 166 mg/L 07/23/2003 – 202 mg/L 07/30/2003 – 232 mg/L 08/20/2003 – 561 mg/L	Attaining – 4 samples exceeded the 80 mg/L criterion; however, the grometric mean was not exceeded. Note that the old turbidity standard (10 NTU) was also exceeded during 18 sampling events.
Nitrogen	0.5 mg/L – annual mean A&Wc and FBC	2002 – 0.635 mg/L	Inconclusive – The annual mean was exceeded at one site in 2002.
Phosphorus	0.1 mg/L – annual mean A&Wc and FBC	2000 – 0.21 mg/L annual mean 2003 0.14 mg/L annual mean	Impaired – The annual mean was exceeded at one site in 2000 and at a different site in 2003. (Binomial)

DATA GAPS AND MO	DNITORING NEE	DS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Collected all core parameters		Lab detection limits for selenium and dissolved metal: (copper, lead, mercury) were higher than Al&Wc chronic criteria.	
DISCUSSION OF NITROGEN	THENGHAPAN	2005; 2. The annual mean	ent impairment: ADL was completed and approved by EPA in n was exceeded at one site in 2002; and conducted in 2000-2004.	
MONITORING RECOMMEN	IDATIONS	determine effectiveness of Actions to reduce nitrogen phosphorus loadings; there low priority. Use lower lab detection lin Recommend using biocrites	Idditional nutrient and E. coli bacteria data to TMDL strategies being implemented. and E. coli bacteria loadings will also reduce fore, development of a phosphorus TMDL is a nits for selenium and dissolved metals. ria assessments and bottom deposits in this reach, when the y are adopted.	

TONTO CREEK		USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
From tributary at 341810 / 1110414 to Haigler Creek 15060105 – 0138 8.5 Miles	A D m Q	A&Ww – Inconclusive FBC – Impaired FC – Attaining Agl – Attaining AgL – Attaining	Not attaining (Impaired)	E. coll bacteria	E. coliTMDL approved in 2005. Implementing strategies to reduce loadings.
	E P A	A&Wc – Impaired FBC – Impaired	Category 4A Not attaining	Nitrogen	EPA listed nitrogen in 2004. Nitrogen TMDL approved in 2005. Implementing strategies to reduce loadings

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B and Appendix C).

SITE NAMES	AGENCY	SAMPLING DATE: 05/23/2000 – 10/23/2003			
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES			
DATABASE #		Metals	Nutrients – Related	Other	
Above Bear Flats SRTON055.09 100357	ADEQ TMDL	4 total and dissolved metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc	32-35 samples: Total nitrogen, total phosphorus, total	23 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids	
Below Bear Flats SRTON053.87 100358	ADEQ TMDL & Ambient	4 total and 0-2 dissolved: Boron, lead, manganese, mercury	Kjeldahl nitrogen, dissolved oxygen, pH 4 samples: Ammonia	24 Suspended sediment concentration 34 Turbidity	

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
E. coli bacteria	235 CFU/100 ml FBC	09/02/2000 - 524.7 CFU/100 ml 10/31/2000 - 272 CFU/100 ml 07/23/2003 - >2419 CFU/100 ml 08/07/2003 - 299 CFU/100 ml 08/20/2003 >2419 CFU/100 ml	Remains impaired – 5 exceedances during the assessment period.
Nitrogen	0.5 mg/L – annual mean 2.0 mg/L – single sample maximum A&Ww and FBC	07/23/2002 – 2.08 mg/L (SSM) 2002 – 0.59 mg/L (annual mean)	Inconclusive – The annual mean was exceeded at one site in 2002. The single sample maximum was exceeded once in 35 samples (17 sampling events). (Binomial)
Phosphorus	0.1 mg/L – annual mean 0.8 mg/L – single sample maximum A&Ww and FBC	08/20/2003 – 1.5 mg/L 2003 – 0.57 mg/L (annual mean)	Inconclusive – The annual mean was exceeded at one site in 2003. (Another site was at the standard 0.101 mg/L in 2002.)
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Ww	07/23/2002 – 734 mg/L 08/20/2003 – 1117 mg/L	Attaining – 2 samples exceeded the 80 mg/L criterion; however, both exceedances occurred during elevated flows so the values were not included in the geometric mean calculation.

Pollutant: Assume "total" concentration, unless shown as dissolved.

DATA GAPS AND MO	DNITOKING NE	EDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Phosphorus	Collected all core parameters		Lab detection limit for selenium was higher than A&Wc chronic criteria.	
DISCUSSION OF NITROGEN	IMPAIRMENT	2. The annual mean	nt impairment: DL was completed and approved by EPA in 2005; was exceeded at one site in 2002; and onducted in 2000-2004.	
MONITORING RECOMMENDATIONS		Medium Priority —Collect additional nutrient and E. coli bacteria data to determine effectiveness of TMDL strategies being implemented. Collect sample during critical conditions. Use a lower lab detection limit for selenium. Recommend using biocriteria assessments and bottom deposits implementation procedures in this reach, when they are adopted.		

TONTO CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From Rye Creek to Gun Creek 15060105 008 4.7 Miles	A&Ww - Attaining FBC - Attaining FC - Attaining Agl Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 01/31/2000 – 12/01/2005 NUMBER AND TYPES OF SAMPLES		
DATABASE #				
		Metals	Nutrients – Related	Other
Above Gun Creek and USGS gage SRTON019.37 100349	ADEQ Ambient	7-20 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, mercury, silver, thallium, and zinc	20-21 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, pH	20 E. coli bacteria 20 Fluoride 20 Total dissolved solids 10 Suspended sediment concentration 21 Turbidity
		20 total and 0-2 dissolved: Boron, manganese	oxygen, pri	21 Turbidity

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limit for dissolved mercury and selenium were higher than the A&W chronic criteria in at least 11 samples.
MONITORING RECOMMEND	DATIONS	Low Priority –Use lower lab mercury.	detection limits for selenium and dissolved

WEST FORK BLACK RIVER	USE SUPPORT	OVERALL ASSESSMENT	
From Indian Reservation boundary to Black River 15060101 048 14.6 Miles	A&Wc - Inconclusive FBC - Attaining FC - Attaining DWS - Attaining AgI - Attaining AgL - Attaining	Category 2 Attaining some uses	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 10/24/2000 - 01/26/2004				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
Above Thompson Creek SRWFB015.22 100692	ADEQ Special study	8 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, zinc	8 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen,	7 <i>E. coli</i> bacteria 8 Fluoride 7 Total dissolved solids		
Above Forest Road #116 SRWFB013.89 102120	ADEQ Special study	8 total and 0-1 dissolved: Boron, lead, manganese, mercury	total phosphorus, dissolved oxygen, pH	69 Suspended sediment concentration 95 Turbidity		
Below Forest Road #116 SRWFB013.67 101204	ADEQ Ambient and Special study	2 total and 1 dissolved: Barium, nickel, silver, and thallium				
At Forest Road #88 SRWFB003.45 102126	ADEQ Special study					
Above Home Creek SRWFB001.47 102130	ADEQ Special study					
At Buffalo Crossing SRWFB001.13 100376	ADEQ Ambient and Special study					

EXCEEDANCE	S		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Wc	03/24/2004 – 122.8 mg/L	Attaining – SSC criteria of 80 mg/L was exceeded once in 40 sampling events. The geometric mean standard was not exceeded.

DATA GAPS AND MO			
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority –Use lower la mercury.	b detection limits for selenium and dissolved
		events. Recommend using	(10 NTU) was exceeded in 10 of 40 sampling biocriteria assessments and bottom deposits s in this reach, when they are adopted.

WEST FORK PINTO CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Pinto Creek 15060103 – 066 11.6 Miles	A&We Inconclusive PBC Inconclusive	Category 3 Inconclusive	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 03/30/2001 – 01/04/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Below Kennedy Ranch SRWPN004.47 102433	ADEQ TMDL	4-5 dissolved and total: Copper, selenium, and zinc	1 samples: Ammonia, total nitrogen, total phosphorus, nitrite/nitrate, total	1 Fluoride	
At WF SRWPN000.39 102434	ADEQ TMDL	1 dissolved and total metals: Antimony, arsenic, barium, beryllium, boron, cadmium,	Kjeldahl nitrogen 2 Dissolved oxygen 7 pH		
At Pinto Creek SRWPN000.01 102435	ADEQ TMDL	chromium, lead, manganese, mercury, nickel, silver, thallium.			

EXCEEDANCE	S		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	7.8 µg/L at 78 mg/L hardness A&We acute	01/04/2005 – 78 μg/L	Inconclusive – 1 exceedance in the last 3 years of monitoring.

DATA GAPS AND MO	NITORING NEEDS	•		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Insufficient core parameters	Insufficient sampling events		
DISCUSSION OF EXCEEDANCE	ES	Samples were collected to support the Pinto Creek copper TMDL and site specific copper standard development. Copper loadings from this tributary will be addressed in the Pinto Creek copper TMDL currently being developed.		
MONITORING RECOMMENT	DATIONS	High Priority -Collect additional samples to support TMDL development as needed.		
		Collect core parameters to rep assessment period.	resent at least 3 seasons during the	
		Use lower detection limits for	selenium and dissolved mercury.	

WILLOW CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Beaver Creek 15060101 049 7.0 Miles	A&Wc – Inconclusive FBC – Inconclusive FC – Inconclusive AgL – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOR	9: 04/15/2003 – 03/23/2004	
DATABASE #		NUMBER AND TY	PES OF SAMPLES	
		Metals	Nutrients – Related	Other
Above Forest Road #26 SRWIL001.73 102146	ADEQ Special Study		2 samples: Total phosphorus, dissolved oxygen, pH	1 Total dissolved solid: 3 Suspended sediment concentration 3 Turbidity

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	
MONITORING RECOMMENDATIONS		Low Priority -Collect core para during the assessment period.	ameters to represent at least 3 seasons

San Pedro Watershed

Watershed Description

This watershed encompasses three hydrological areas:

- San Pedro River, which begins in the mountains near Cananea Sonora, Mexico, and flows north about 100 miles through the southeast corner of Arizona to join the Gila River near Winkelman, Arizona;
- Willcox Playa, a terminal basin (does not drain out of the area), which contains a 30,000 acre ephemeral lake (playa); and
- Two relatively short drainages that flow to the Rio Yaqui in Mexico: Whitewater Draw and Black Draw.

It is a 7,015 square mile watershed is lightly populated with only 130,000 people (2000 census). Communities in the area include the rapidly growing Sierra Vista area and several historic towns, such as Tombstone, Douglas, and Bisbee. Grazing is widespread, with significant areas of irrigated agriculture located on the eastern side of the watershed. Historic copper, silver, and gold mining took place across the watershed; however, only a few mines are still active. Land ownership is divided approximately as: 40% private, 40% state, 20% federal (no tribal land). The Bureau of Land Management established a 50,000 acre San Pedro Riparian National Conservation Area in 1988 to protect this critical habitat.

Elevation varies from 4,000 feet (above sea level), with desert grassland and warmwater aquatic communities, to 10,700 feet at Mount Graham, with alpine forest. Areas above 5,000 feet typically support coldwater aquatic communities where perennial waters exist.

Water Resources


The area gets little precipitation, with 10-15 inches of rain and 0-5 inches of snow. Springs provide perennial flow to segments of the San Pedro River and other streams in this watershed. Concerns have been raised about ground water pumping and water demand in the rapidly growing Fort Huachuca Army Base -- Sierra Vista area and the potential impact on perennial flow in the San Pedro River. In 2003, a Fort Huachuca Preservation Legislation required the Secretary of Interior to develop water use management and conservation measures necessary to restore and maintain the sustainable yield of the aquifer.

An estimate of surface water resources in the Salt Watershed is provided in the following table.

Estimated Surface Water Resources in the San Pedro Watershed

	Perennial		Intermittent		Ephemeral	
Stream miles		195		665		6,610
	Perennial		Non-perennial			
Lake acres		1,319		29,471		

Estimated miles and acres are based on U.S. Geological Survey digitized hydrology at 1:100,000 and have been rounded to the nearest 5 miles or 5 acres. Ambient monitoring focuses on perennial waters; however, special investigations have identified water quality problems on intermittent and even ephemeral waters.



Watershed Partnerships

- Campomocho-Sacaton Watershed Group
 This 42,000 acre subwatershed is in the Willcox Playa basin, includes most of Hook Open A Ranch and Redtail
 Ranch near Willcox, Arizona. The group's primary objective is to implement conservation practices that will
 improve watershed health and water quality, and reduce downstream flood damages. Projects are specifically
 aimed at reducing soil erosion and water runoff, increasing ground cover, and improving wildlife habitat to reduce
 negative economic impacts. The group has quarterly meetings. Contact Donna Matthews at (520) 384-2229 or
 donna.matthews@az.usda.gov; or Dan Skinner, Chair, d.skinner@goldtechind.com.
- Upper San Pedro Partnership
 This 1,875 square mile basin extends along the San Pedro River from Mexico to "the narrows." This partnership coordinates the identification, development, and implementation of policies and projects to meet water needs in the Sierra Vista area. The group meets in Sierra Vista on the second Wednesday of the month. Contact Carol Sanger, Coordinating Manager, carolsang6@cox.net or lhendrickson@co.cochse.az.us; or Bob Strain, Chair, at (520) 459-4763
- Community Watershed Alliance (Middle San Pedro)
 The area of concerns extends further north along the San Pedro River, between "the narrows" near Charleston to the Gila River at Winkleman, AZ. This grassroots group works to effect change that will benefit water quantity and quality. It meets on the 4th Tuesday of the month in Benson, AZ. Contact Mary McCool at (520) 798-0229; Al Turk, (520) 586-7086, Anna Landis (520) 586-7310, Peter Moran (520) 586-4456 or watergroup@aol.com.

Special Studies and Water Quality Improvement Projects

Total Maximum Daily Load Analyses – The following TMDL analyses have been completed, are ongoing, or are scheduled to be completed in this watershed. Further information about the status of these investigations or a copy of the TMDL, if completed, can be obtained at ADEQ's website: www.azdeq.gov.

- Mule Gulch and several of its tributaries in the Bisbee area are impaired due to copper, cadmium, zinc, and low pH (acidic).
 Metal concentrations and acid mine conditions primarily pose a risk to aquatic life and wildlife. The TMDLs being developed by ADEQ are complex due to natural background levels of metals and because source loading data is difficult to collect due to slope, intermittent and ephemeral flows, and drought conditions. To account for natural conditions, ADEQ is developing site specific standards. Meanwhile, the mining operation in the area has continued to implement additional management measures to address contamination.
- San Pedro River between Babocomari Creek and Dragoon Wash is impaired due to *Escherichia coli* bacteria. Exceedances of *E. coli* standards may represent a significant public health concern if people are swimming or even wading in the water. This bacteria TMDL was initiated in 2006.
- San Pedro River, between Dragoon Wash and Tres Alamos Wash, is impaired due to nitrate. This stretch of river is contaminated by underground flow of groundwater contaminated by nitrates. Remediation activities are occurring as part of a Superfund cleanup site, and the facility is doing monthly ground and surface water monitoring to evaluate the effectiveness. Although water quality continues to improve, will take time for the surface water quality to meet standards as there is significant ground water contamination.
- San Pedro River, from Aravaipa Creek to the Gila River, is impaired by *Escherichia coli* bacteria and selenium. Exceedances of *E. coli* standards may represent a significant public health concern if people are swimming or even wading in the water. Selenium may negatively impact federally protected birds (bald eagle and Southwest willow flycatcher) found in this area. TMDL initiated in 2006.

Water Quality Improvement Grant Projects – ADEQ awarded the following Water Quality Improvement Grants (319 Grants) in this watershed. More information concerning these grants or projects can be obtained at: http://www.azdeq.gov/environ/water/watershed/fin.html.

• Turbidity Reduction in Aravaipa Creek Project

Coronado Resource Conservation and Development Area (2000)

Divide the area into smaller pastures with fencing and adjust grazing so that a higher concentration of cattle will be on each pasture for a shorter length of time. This should improve soil, allow seed germination, and encourage vegetative regrowth. Add fencing to exclude cattle form the creek to improve riparian condition.

• Borderlands Storm Water Runoff Control Project

Coronado Resource Conservation and Development Area (2001)

Revegetate using native plantings and provide water spreader dikes on 2,500 acres of severely eroded rangeland along the Mexican border to reduce sediment loading.

• Peppersauce Cave Water Restoration Project

Raymond C. Keeler (2001)

Remove litter and graffiti from the permanent pools in the cave, disinfect the pools to eliminate the *Escherichia* coli bacteria contamination, and distribute educational materials.

• Campomocho - Sacaton Storm Water Runoff Control Project

The Coronado Resource Conservation and Development Area (2001 and 2005)

Install sediment retention structures and contouring, and reseed to reestablish vegetation to reduce erosive water velocity and sediment transport during storm events in the Willcox Playa Drainage Area.

• San Pedro Wildlife Sanctuary Habitat Restoration Project

The Nature Conservancy (2001)

Restore agricultural fields by introducing native plants and improving riparian flood plain condition along the San Pedro River. Provide an outdoor riparian exhibit for education and outreach.

• Fort Huachuca East Range Road Closure and Stream Crossing Project

Engineering and Environmental Consultants, Inc (EEC) (2002)

Close 81 miles of roadways within the Fort Huachuca East Range and provide various degrees of rehabilitation to these areas. Develop an exhibit, talks, and articles to demonstrate practical and new technologies used in this project.

• Ramsey Canyon Preserve Parking Lot Runoff Reduction Project

The Nature Conservancy (2002)

Divert water from the roof of the Ramsey Canyon Visitors Center and from the nearby forest road to reduce sediment transport to Ramsey Creek. Install retention systems and recontour parking areas to direct runoff to planted areas.

• Wisconsin Mound Septic System at the Audubon Research Ranch Project

National Audubon Society Appleton-Whittell Research Ranch (2002)

Replace failed septic system with this alternative system and host workshops on alternative systems.

• St. David Community River Cleanup Project

The San Pedro National Resource Conservation District (2003)

Work with community partners and clean up heavy trash dumping along the San Pedro River in the north section of the National Riparian Conservation Area.

• Three Links Farm Riparian Habitat Restoration Project

The Nature Conservancy (2003)

Fence of and enhance riparian habitat along the San Pedro River.

Cottonwood Creek Restoration and Sediment Control Project

Coronado Resource Conservation and Development Area (2004)

Reduce stream bank erosion along Cottonwood Creek in the Whitewater Draw Drainage Area by using gabions to stabilize grade, fencing off livestock from riparian areas, and developing alternative water source for grazing.

• Erosion Control in the Babacomari Project

Coronado Resource Conservation and Development Area (2006)

Construct erosion control mats and waddles and revegetate the riparian area to stabilize two gullies in Lyle Canyon which are contributing sediment to Babacomari River.

Manzanita Erosion Control Project

Community Watershed Alliance (CWA) (2006)

Install rip rap, culverts, and gully plugs and revegetate using seedlings to reduce erosion in the San Pedro watershed.

Water Protection Fund Projects – The following Water Protection Fund Projects were awarded by the Arizona Department of Water Resources. More information about these funds or projects can be obtained from the ADWR web site at: http://www.azwater.gov.

Lower San Pedro Watershed Project

The Redington National Resources Conservation District (2000)

Provide a water resource assessment and provide a watershed alternatives plan for improving watershed conditions. The project also brought local communities together to address watershed issues and solicit public involvement.

• Cooperative Grazing Management for Riparian Improvements Project

The Double Check Ranch and the Nature Conservancy (2000)

Implement a cooperative grazing management plan. Fencing and alternative watering sources were developed to protect riparian areas along the San Pedro River.

Cottonwood Creek Restoration Project

The Coronado Resource Conservation and Development Area (2003)

Restore riparian conditions along Cottonwood Creek in Whitewater Drainage Area.

Other Water Quality Studies – The following additional water quality related studies were completed since 2000 in this watershed:

• Water Issues of the Arizona - Mexico Border: The Santa Cruz, San Pedro, and Colorado Rivers.

Terry W. Sprouse, University of Arizona, Water Resources Research Center (2005) Summary of water quality and water quantity issues facing this region.

 Water Quality Data for Selected National Park Units, Southern and Central Arizona and West-Central New Mexico, Water Years 2003 and 2004

U.S. Geological Survey in cooperation with the National Park Service (2005)

Field measurements and water samples were collected at springs, mine adits, streams, and wells at 30 sites in 9 park units in 2003-2004 to provide baseline (ambient) water quality information. Only 24 of the 30 sites were sampled three times due to drought conditions and lack of water during parts of the year. In the San Pedro Watershed, samples were collected in Coronado National Memorial. Analyses of data collected at these sites indicated:

Assessment of Selected Inorganic Constituents in Streams in the Central Arizona Basins Study Area, Arizona and Northern Mexico, through 1998

David Anning - U.S. Geological Survey, National Water Quality Assessment Program (2003)

Inorganic chemical data (dissolved solids, suspended sediment, and nutrients) and stream properties (temperature, pH, dissolved oxygen) were analyzed to assess water quality, determine natural and human factors affecting water quality, and compute stream loads.


Border Crossings – Water and Wastewater at the International Boundary
 R.G. Charles Graf and Craig Tinney (ADEQ) and Tom Konner (EPA Region IX)
 September/October 2005 Southwest Hydrology (2005)
 This article describes the problems and progress being made in addressing water quality and wastewater infrastructure along the Mexican border with California and Arizona for seven key populations centers: San Diego/Tijuana, Tecate, Calexico/Mexicali, San Luis/San Luis Rio Colorado (Yuma area), Nogales, Naco/Bisbee, and Douglas/Agua Prieta.

Assessments

The San Pedro Watershed can be separated into the following drainage areas (subwatersheds):

15050201	Willcox Playa
15050202	Upper San Pedro
15050203	Lower San Pedro
15080301	Whitewater Draw
15080302	San Bernardino Valley

These drainage areas and the surface waters assessed as "attaining" or "impaired" are illustrated on the following watershed map. Methods used to complete these assessments are described in the "Surface Water Assessment Methods and Technical Support" document (2006).



ARAVAIPA CREEK	USE SUPPORT	OVERALL ASSESSMENT	
Tronic Did Galanti to and or	A&Ww - Attaining FBC - Attaining FC - Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES	AGENCY	SAMPLING DATE: 02/28/2000 - 05/15/2002			
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES			
DATABASE #		Metals	Nutrients - Related	Other	
At east trail head SPARA019.41 100210	USGS Special study	5-8 dissolved and total metals: Antimony, arsenic, beryllium, barium, cadmium, chromium,	11 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus,	10 <i>E. coli</i> bacteria 11 Fluoride 10 Total dissolved solid	
Below Parsons Canyon SPARA017.25 100211	ADEQ Ambient USGS Special study	copper, lead, nickel, silver, thallium, and zinc 8 total and 0-1 dissolved: Boron,	nitrite/nitrate, total Kjeldahl nitrogen	11 Turbidity	
At Hells Half Acre Campground SPARA011.92 100716	ADEQ TMDL	manganese, mercury			

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limits for selenium and dissolved metals (lead, mercury, nickel) were higher than the A&W chronic criteria in at least 2 samples.
MONITORING RECOMMENDATIONS		Low Priority –Use lower lab detection limits for selenium and dissolve metals.	

ARAVAIPA CREEK	USE SUPPORT	OVERALL ASSESSMENT	2
15050203 - 004C	A&Ww - Attaining FBC - Attaining FC - Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 05/19/2000 – 04/06/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At Woods Ranch SPARA010.19 100212	USGS Special study	7-9 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, and zinc 3-9 total and 0-1 dissolved: Boron, lead, manganese, mercury, nickel 1 total and 1 dissolved: Barium, silver, thallium	9 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	8 E. coli bacteria 9 Fluoride 9 Total dissolved solids 8 Suspended sediment concentration 9 Turbidity	

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
No Exceedances					

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limits for selenium and dissolved metals (lead, mercury, and nickel) were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority –Use lower lab detection limits for selenium and dissolvemetals.	

BABOCOMARI RIVER	USE SUPPORT	OVERALL ASSESSMENT
From Banning Creek to San Pedro River 15050202 004 32.7 Miles	A&Ww - Attaining FBC - Attaining FC - Attaining AgL - Attaining	Category 1 Attaining all uses

SITE NAMES	AGENCY	SAMPLING DATE: 01/28/2000 – 02/01/2006			
ID#	PURPOSE	Included 02/01/2006 data to be able to assess designated uses			
DATABASE #		NUMBER AND TYPES OF SAM	NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other	
Near Huachuca City, AZ USGS #09471380 SPBBR018.97 101487	USGS Special study	3 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, lead, zinc 3 total metals only: Boron,	3-4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	3 E. coli bacteria 3 Fluoride 3 Total dissolved solids 3 Suspended sediment concentration	
Near Tombstone, AZ USGS #09471400 SPBBR003.49 101488	ADEQ Ambient USGS Special study	chromium, manganese 3 total and 1 dissolved: Mercury		4 Turbidity	
At mouth to San Pedro River SPBBR000.06 103548	ADEQ TMDL	1 total: Selenium			

EXCEEDANG			
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.	€	Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria in 2 samples.
MONITORING RECOMMEND	DATIONS	Low Priority –Use lower lab mercury.	detection limits for selenium and dissolved

BASS CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From unnamed tributary at 322606 / 1101318 to Hot Springs Canyon Creek 15050203 – 899B 7.9 Miles	A&Ww – Attaining FBC – Attaining FC – Attaining AgL – Attaining	Category 1 Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 03/01/2000 – 08/23/2000; 09/14/2004 – 04/19/2005 NUMBER AND TYPES OF SAMPLES			
DATABASE #					
		Metals	Nutrients - Related	Other	
Above Double R Canyon SPBASO01.64 100215	ADEQ Ambient	6-7 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, and zinc	8 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total	7 <i>E. coli</i> bacteria 8 Fluoride 8 Total dissolved solids 4 Suspended sediment	
Above Hot Springs Canyon Creek SPBAS000.62 100217	ADEQ Ambient	3-7 total and 0-2 dissolved: Barium, boron, chromium, lead, manganese, mercury, nickel, silver, thallium	Kjeldahl nitrogen	concentration 8 Turbidity	

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	6.0 mg/L A&WW	09/14/2004 – 2.66 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow. Flow was 0.1 cfs. Low levels of nitrogen (0.13 mg/L) and phosphorus (0.01 mg/L).

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limits for selenium and dissolved metals (copper, lead, mercury) were higher than the A&W chronic criteria in at least 3 samples.
MONITORING RECOMMEN	DATIONS	Low Priority – Use lower lab metals.	detection limits for selenium and dissolved

UNNAMED BASS CANYON TRIBUTARY	USE SUPPORT	OVERALL ASSESSMENT	
	A&Ww - Attaining FBC - Attaining FC - Attaining	Category 1 Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 09/16/2004 – 04/21/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
East of Bass Canyon SPUBS000.22 100224	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, and zinc 3-7 total and 0-2 dissolved: Boron, manganese, mercury	3-4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	4 E. coli bacteria 4 Fluoride 3 Total dissolved solid: 4 Suspended sediment concentration 4 Turbidity	

EXCEEDANG	-E3		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	All core parameters collected.		Lab detection limits for selenium and half of the dissolved mercury sample were higher than the A&W chronic criteria.	
MONITORING RECOMMENDATIONS		Low Priority – Use lower lab detection limits for selenium and dissolved mercury.		

BREWERY GULCH From headwaters to		USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Mule Gulch 15080301 337 1 Mile	ADEQ	A&We – Impaired PBC – Inconclusive	Category 5	Copper	ADEQ also assesses this reach as impaired by copper.
	E P A	A&We – Impaired	Category 5	Copper	EPA listed in 2004 due to copper

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters.

SITE NAMES	AGENCY PURPOSE	SAMPLING DATE: 03/07/2000 – 10/11/2000; 08/26/2003 – 09/27/200 NUMBER AND TYPES OF SAMPLES			
DATABASE #	TABASE #				
		Metals	Nutrients - Related	Other	
Above mineral zone SPBRG000.91 103439	ADEQ TMDL	6-7 dissolved metals: Cadmium, copper, lead, and zinc			
At old Bisbee storm drain SPBRG000.03 103441	ADEQ TMDL	3 total metals: Copper, zinc 2 total metals: Cadmium, lead			

EXCEEDANCE	S		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	6.3 µg/L at 20 mg/L hardness 10.2 µg/L at 41 mg/L hardness 8.5 µg/L at 35 mg/L hardness 31.3 µg/L at 88 mg/L hardness 20.6 µg/L at 137 mg/L hardness 10.5 µg/L at 43 mg/L hardness 18.4 µg/L at 78 mg/L hardness A&We acute	03/07/2000 – 81 μg/L 08/07/2000 – 150 μg/L 10/11/2000 – 26 μg/L 10/19/2000 – 52 μg/L 08/26/2003 – 65 μg/L 08/14/2004 – 25 μg/L 09/27/2004 – 30 μg/L	Impaired – Exceeded standard 3 times during a 3- year period (7 times during the assessment period).
Lead (dissolved)	51 µg/L at 41.5 mg/L hardness A&We acute	08/14/2004 – 380 μg/L	Inconclusive – 1 exceedance in the last 3 years of monitoring.
Lead (total)	15 μg/L PBC	08/14/2004 – 380 μg/L (d)	Inconclusive – 1 exceedance in 2 samples. (Binomial)
pH	>6.5 SU A&We, PBC	03/07/2000 - 6.2 SU	Inconclusive – Only 1 exceedance in 6 samples. (Binomial)

Pollutant: Assume "total" concentration, unless shown as dissolved.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	L DETECTION LIMITS NOT LOW ENOUGH
Lead and pH	Insufficient core parameters		
DISCUSSION OF EXCEEDANCE		EPA originally listed this reach as impaired by copper in 2004. current assessment ADEQ also lists it as impaired based on: 1. Seven exceedances during the assessment period; 2. Copper loadings from this tributary will be addresse Mule Gulch copper TMDL currently being develope 3. Three exceedances in the last 3-year period.	
MONITORING RECOMMENDATIONS		High Priority -Collect of development on Mule	copper, lead, and pH samples to support TMDL Gulch as needed.

BUEHMAN CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to end of designated unique water 15050203 – 010A 10.5 Miles	A&Ww - Attaining FBC - Attaining FC - Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 02/29/2000 - 05/01/2002; 11/08/2004 - 04/04/			
DATABASE #	NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other	
Below Bullock Canyon SPBHC004.66 100425	ADEQ Ambient	6-9 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper,	10 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus,	10 <i>E. coli</i> bacteria 10 Fluoride 10 Total dissolved solids	
Below unnamed dry wash SPBHC004.31 101175	ADEQ Ambient	lead, and zinc 3-4 dissolved and total metals: Barium, nickel, silver, thallium 9 total and 0-1 dissolved: Boron, manganese, mercury	nitrite/nitrate, total Kjeldahl nitrogen	3 Suspended sediment concentration 10 Turbidity	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	6.0 mg/L A&Ww	05/16/2000 – 4.4 mg/L 08/22/2000 – 2.4 mg/L	Attaining – Low dissolved oxygen due to natural conditions of ground water upwelling during very low flows.	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority –Use lower lab detection limits for selenium and dissolve mercury.	

COPPER CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Prospect Canyon 15050203 – 022A 6.6 Miles	A&Ww – Inconclusive FBC – Attaining FC – Attaining AgL – Attaining	Category 2 Attaining some uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 02/29/200	0 - 08/22/2000; 11/09/200	8/22/2000; 11/09/2004 – 09/21/2005	
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Above Bluebird Mine tributary SPCOP011.39 100433	ADEQ Ambient	4-7 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, and zinc	8 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total	8 <i>E. coli</i> bacteria 8 Fluoride 8 Total dissolved solids 3 Suspended sediment	
Below Dark Canyon \$PCOP008.37 100944	ADEQ Ambient	4-6 total 0-2 dissolved: Barium, boron, manganese, mercury, nickel, silver, thallium	Kjeldahl nitrogen	concentration 8 Turbidity	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Copper (dissolved)	28.0 µg/L at 380 mg/L hardness A&Ww chronic	03/09/2005 – 31.1 μg/L	Inconclusive – Only 1 exceedance during the assessment period.	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Dissolved copper	Core parameters collected.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Medium Priority -Collect additional dissolved copper due to the exceedance. Use lower lab detection limits for selenium and dissolved mercury.	

DOUBLE R CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT
From headwaters to Bass Canyon Creek 15050203 – 902 5.0 Miles	A&Ww - Attaining FBC - Attaining FC - Attaining	Category 1 Attaining all uses

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 05/22/2000 - 04/21/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Near Bass Canyon Creek SPDOU000.18 100223	ADEQ Ambient	5-9 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, and zinc 9 total and 0-2 dissolved: Boron, manganese, mercury 2 total and 1-2 dissolved: Barium, nickel, silver, thallium	8-9 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	8 E. coli bacteria 8 Fluoride 8 Total dissolved solids 3 Suspended sediment concentration 8 Turbidity	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	6.0 mg/L A&W/w	05/22/2000 – 4.7 mg/L 06/09/2003 – 4.6 mg/L 09/15/2004 – 5.5 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Flows between 0.02-0.06 cfs.	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limits for selenium and dissolved metals (copper, lead, mercury) were higher than the A&W chronic criteria in at least 4 samples.
MONITORING RECOMMENDATIONS		Low Priority –Use lower lab detection limits for selenium and dissolve metals.	

DUBACHER CANYON	USE SUPPORT	OVERALL ASSESSMENT	
	A&We – Inconclusive PBC – Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/12/200	00	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other
Above mine area SPDBC000.42 102923	ADEQ TMDL	1 dissolved only: Cadmium, copper, lead, and zinc		
Below Highway 80 at pit outfall SPDBC000.07 102924	ADEQ TMDL	1 pH		

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Copper (total)	1300 µg/L PBC	10/12/2000 - 36,000 µg/L (dissolved portion)	Inconclusive – Only 1 sample and it exceeded standards.	
Copper (dissolved)	53.2 µg/L At 242 mg/L hardness A&We	10/12/2000 – 36,000 μg/L	Inconclusive – Only 1 sample and it exceeded standards.	
рН	>6.5 SU A&We , PBC	10/12/2000 – 2.4 SU	Inconclusive – Only 1 sample and it exceeded standards.	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Copper and pH	Insufficient core parameters	Insufficient sampling events	
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Mule Gulch copper TMDL. Copper loadings from this tributary will be addressed in the Mule Gulch copper TMDL currently being developed.	
MONITORING RECOMMENDATIONS		High Priority – Collect additional copper and pH samples to support TMDL development on Mule Gulch as needed.	

GRANT CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to unnamed tributary at 323809 / 1095635 15050201 – 033A 6.8 Miles	A&Wc - Inconclusive FBC - Attaining FC - Attaining DWS - Attaining AgL - Attaining	Category 2 Attaining some uses	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 08/17/2004 - 06/14/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Below Post Creek SPGRA007.71 100561	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, beryllium. 4 total and 0-2 dissolved: Boron, cadmium, chromium, copper, lead, manganese, mercury, zinc	4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	4 E. coli bacteria 4 Fluoride 4 Total dissolved solids 4 Suspended sediment concentration 4 Turbidity	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	7.0 mg/L A&Wc	08/17/2004 – 4.56 mg/L	Attaining Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Low nutrient levels (nitrogen 0.21 mg/L) and low flow (0.09 cfs).	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient dissolved metals (cadmium, copper, zinc) to assess attainment of A&W.		Lab detection limits for dissolved metals (cadmium, copper, lead, mercury, and zinc) and total selenium were higher than the A&W chronic criteria in at least 2 samples.
MONITORING RECOMMENDATIONS		Low Priority –Collect missing core parameters to represent at least 3 seasons during an assessment period. Use lower lab detection limits for the dissolved metals and selenium.	

HENDRICKS GULCH	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Mule Gulch 15080301 335 0.5 Mile	A&We – Inconclusive PBC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 08/07/200	0 – 08/27/2003	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
At old Bisbee storm drain SPHNG000.01 102922	ADEQ TMDL	3-4 dissolved metals: Cadmium, copper, zinc 2 dissolved metals: Lead 1 total metals: Copper, zinc 4 pH	None	None

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Copper (dissolved)	16 μg/L at 68 mg/L hardness 8.4 μg/L at 44 mg/L hardness A&We	08/07/2000 – 76 μg/L 08/27/2003 – 44 μg/L	Inconclusive – Only 1 exceedance in a 3-year period.		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Copper	Insufficient core parameters	Insufficient sampling events	
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Mule Gulch copper TMDL. Copper loadings from this tributary will be addressed in the Mule Gulch copper TMDL currently being developed.	
MONITORING RECOMMENDATIONS		High Priority –Collect copper samples to support TMDL developmen on Mule Gulch as needed.	

HOT SPRINGS CANYON	USE SUPPORT	OVERALL ASSESSMENT
From headwaters to San Pedro River 15050203 – 013 25.9 Miles	A&Ww – Inconclusive FBC – Attaining FC – Attaining AgL – Attaining	Attaining some uses

SITE NAMES ID #	AGENCY PURPOSE	Sampling Periods: 03/01/2000 – 08/23/2000; 09/14/2004 – 04/19/2005 NUMBER AND TYPES OF SAMPLES		
DATABASE #				
		Metals	Nutrients – Related	Other
Below Wildcat Canyon SPHSC010.67 100574	ADEQ Ambient	6-7 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, and zinc 3-7 total and 0-2 dissolved metals: Barium, boron, chromium, lead, manganese, mercury, nickel, silver, and thallium.	8 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	7 E. coli bacteria 8 Fluoride 8 Total dissolved solids 4 Suspended sediment concentration 8 Turbidity

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Copper (dissolved)	9.6 μg/L at 108 mg/L hardness A&Ww acute	04/19/2005 – 15 μg/L	Inconclusive – 1 exceedance in last 3-years of monitoring.		

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Copper	All core parameters were collected		Lab detection limits for selenium and dissolved metals (lead, mercury) samples were higher than the A&W chronic criteria in at least 4 samples.
MONITORING RECOMMEND	DATIONS		per samples due to exceedance. for selenium and dissolved metals.

LESLIE CREEK	USE SUPPORT	OVERALL ASSESSMENT	
i i o i i i i o o o i i i i o i o i i i i o i	A&W2 - Inconclusive FBC - Inconclusive FC - Inconclusive AgL - Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE : 05/16/2002; 08/18/2004 (other dates no flow)			
DATABASE #		NUMBER AND TYPES OF SA	NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other	
At Leslie Canyon National Wilderness Area SPLES012.75 101500	ADEQ and USGS Ambient	1-2 dissolved and total metals: Antimony, arsenic, beryllium, boron, cadmium, chromium, copper, lead, manganese, and zinc 1 total metal only: Mercury 1 dissolved metal only: Selenium, uranium, barium	1-2 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	1 Fluoride 1 Total dissolved solids 1 Suspended sediment concentration 1 Turbidity	

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Dissolved oxygen	6.0 mg/L A&Ww	05/16/2002 – 4.5 mg/L 08/18/2004 – 2.6 mg/L	Inconclusive – Elevated nutrients on 05/26/2002 (nitrogen 6.2 mg/L, nitrate 26 mg/L) along with the low dissolved oxygen. Low dissolved oxygen on 08/18/2004 was due to natural conditions of low flow (flow 0.03 cfs) and ground water source of water. Low nutrients (nitrogen 1.03 mg/L, phosphorus 0.06 mg/L, nitrate 0.4 mg/L).		

DATA GAPS AND MONITORING NEEDS						
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH			
Low dissolved oxygen (with elevated nutrients)	Insufficient core parameters	Insufficient sampling events	Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.			
MONITORING RECOMMENDATIONS		Medium Priority -Collect dissolved oxygen data due to low dissolved oxygen measurement.				
		Collect core parameters to represent at least three seasons during an assessment period.				
		Use lower lab detection limits	for the selenium and dissolved mercury.			

MILLER CANYON	USE SUPPORT	OVERALL ASSESSMENT
From headwaters to Broken Arrow Ranch 15050202 – 409A 4.3 Miles	A&Wc – Inconclusive FBC – Inconclusive FC – Inconclusive DWS – Inconclusive AgL – Inconclusive	Category 3 Inconclusive

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATES: 02/23-2005; 03/30/2005			
DATABASE #		NUMBER AND TYPES OF SAM	NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other	
Near headquarters SPMLC012.43 100592	ADEQ Ambient	2 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, lead, and zinc	3-4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total	3 E. coli bacteria 3 Fluoride 3 Total dissolved solids 3 Suspended sediment	
		3 total and 1 dissolved: Mercury	Kjeldahl nitrogen	concentration 4 Turbidity	
		1-2 total metals only: Boron, chromium, manganese, selenium			

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	7.0 mg/L A&Wc	03/30/2005 – 5.2 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow (0.5 cfs) and groundwater upwelling.	

DATA GAPS AND MC	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters.	Insufficient monitoring events	Lab detection limits for selenium and dissolved metal (lead and mercury) samples were higher than the A&W chronic criteria in at least 1 sample.
MONITORING RECOMMENDATIONS		Low Priority -Collect core parameters to represent at least 3 seasons Use lower lab detection limits for selenium and dissolved metals.	

MORALES CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Mule Gulch 15080301 – 331 2 Miles	A&We – Inconclusive PBC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/11/2000			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At Highland Park Road SPMOR000.27 102937	ADEQ TMDL	1 dissolved: Cadmium, copper, lead, zinc			
		1 pH			

EXCEEDANCES			
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	10.7 µg/L at 44 mg/L hardness A&We acute	10/11/2000 – 18 μg/L	Inconclusive – Exceeded criterion in the single sample tested.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Copper	Insufficient core parameters	Insufficient sampling events		
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Mule Gulch copper TMDL. Copper loadings from this tributary will be addressed in the Mule Gulch copper TMDL currently being developed.		
MONITORING RECOMMENDATIONS		High Priority –Collect copper samples to support TMDL development on Mule Gulch as needed.		

MULE GULCH From headwaters to above	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Lavender Pit 15080301 – 090A 3 Miles	A&WW – Impaired PBC – Attaining FC – Attaining	Category 5	Copper	Listed due to copper since 1990. Ongoing TMDL. Establishing site-specific copper standards.

SITE NAMES AGENCY ID # PURPOSE		SAMPLING PERIOD: 03/07/2000 – 08/28/2003			
DATABASE #		NUMBER AND TYPES OF SAMPLE	NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other	
Below Spring Canyon SPMLG015.59 102773	ADEQ TMDL	12-19 dissolved and total metals: Copper, zinc 6-8 dissolved and 2 total: Cadmium,	1 sample: Ammonia, dissolved oxygen, total nitrogen, total	2 Fluoride 1 Turbidity	
At Inn at Castle Rock SPMLG014.59 100506	ADEQ TMDL	lead 1-2 dissolved and/or total metals: Antimony, arsenic, barium, beryllium,	phosphorus, nitrite/nitrate, total Kjeldahl nitrogen		
At MG - 100 SPMLG014.03 102489	ADEQ TMDL	boron, chromium, manganese, mercury, nickel, silver, thallium, zinc	15 pH		

EXCEEDANCES			
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Cadmium (dissolved)	3.7 µg/L at 198 mg/L hardness 1.9 µg/L at 80 mg/L hardness A&Ww chronic	03/07/2000 – 7.4 μg/L 10/12/2000 – 21 μg/L	Inconclusive – Two exceedances of chronic standards during the assessment period; however, samples may not be representative of a four day condition, as they were collected during rain events.
Cadmium (dissolved)	3.4 µg/L at 80 mg/L hardness A&Ww acute	10/12/2000 – 21 μg/L	Inconclusive – Exceeded the acute standard once.
Copper (dissolved)	14.0 µg/L at 104 mg/L hardness 25.2 µg/L at 195 mg/L hardness 19.7 µg/L at 150 mg/L hardness 17.3 µg/L at 131 mg/L hardness 17.3 µg/L at 131 mg/L hardness 25.7 µg/L at 199 mg/L hardness 36.5 µg/L at 289 mg/L hardness 25.3 µg/L at 196 mg/L hardness 14.5 µg/L at 108 mg/L hardness 13.6 µg/L at 100 mg/L hardness A&WW acute	03/07/2000 - 160 µg/L 08/08/2000 - 160 µg/L 08/18/2000 - 69 µg/L 10/12/2000 - 260 µg/L 10/07/2002 - 49 µg/L 12/01/2002 - 30 µg/L 01/08/2003 - 44 µg/L 07/20/2003 - 240 µg/L 08/13/2003 - 32 µg/L 08/26/2003 - 20 µg/L	Remains impaired – 6 exceedances during the last 3 years of monitoring (10 exceedances during the assessment period).

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Cadmium	Insufficient core parameters	Insufficient sampling events for core parameters	Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.	
MONITORING RECOMMENDATIONS		High Priority – Collect samples to support copper TMDL and site specific copper standards. Collect additional cadmium samples due to exceedances. Use lower lab detection limits for selenium and dissolved mercury. Collect core parameters to represent at least 3 seasons.		

MULE GULCH From above Lavender Pit to Bisbee WWTP discharge 15080301 – 090B 0.8 Miles	,	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
	ADEQ	A&We – Impaired PBC – Impaired	Category 5	Copper	Ongoing copper TMDL. Establishing site-specific copper standards.
	E P A	A&We – Impaired PBC – Impaired	Category 5	Low pH	EPA listed low pH in 2002. Ongoing copper TMDL will also address low pH.

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B and Appendix C).

SITE NAMES	AGENCY	SAMPLING DATE: 03/07/200	00 - 08/26/2003	
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES		
DATABASE #		Metals	Nutrients - Related	Other
Site MG 150 SPMLG012.79 102490	ADEQ TMDL	10 dissolved: Copper and zinc 6 total: Copper and zinc 2-3 dissolved: Cadmium, lead	5 pH	None

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (total)	1300 μg/L PBC	03/07/2000 – 4,000 μg/L 10/11/2000 – 4,000 μg/L 10/07/2002 – 39,000 μg/L 02/20/2003 – 16,725 μg/L 03/16/2003 – 21,000 μg/L 07/20/2003 – 19,200 μg/L 08/26/2003 – 13,000 μg/L	Remains impaired – Exceeded criterion during 7 of 7 sampling events (8 of 15 samples). (Binomial) (Note: dissolved copper results were compared to standards when total copper was not analyzed.)
Copper (dissolved)	41.0 μ g/L at 182 mg/L hardness 36.2 μ g/L at 161 mg/L hardness 40.5 μ g/L at 182 mg/L hardness 85.9 μ g/L at >400 mg/L hardness 41.5 μ g/L at 185 mg/L hardness 41.5 μ g/L at 185 mg/L hardness 63.0 μ g/L at 288 mg/L hardness 85.9 μ g/L at >400 mg/L hardness 61.3 μ g/L at 287 mg/L hardness 61.3 μ g/L at 287 mg/L hardness A&We acute	03/07/2000 – 4,000 μg/L 08/07/2000 – 42 μg/L 10/11/2000 – 4,000 μg/L 10/07/2002 – 40,000 μg/L 02/14/2003 – 67 μg/L 02/20/2003 – 28,000 μg/L 03/16/2003 – 21,000 μg/L 07/20/2003 – 34,000 μg/L 08/26/2003 – 15,000 μg/L	Remains impaired – Exceeded criteria 6 times in the last 3 years of monitoring (9 times during the assessment period).
Lead	15 μg/L PBC	10/11/2000 – 39 μg/L	Inconclusive – Exceeded in 1 of 2 samples. (Binomial)
рН	>6.5 SU A&We, PBC	03/07/2000 – 3.0 SU 08/07/2000 – 6.1 SU 10/11/2000 – 4.4 SU 02/20/2003 – 2.7 SU	Inconclusive – Did not meet criterion in 4 of 5 sampling events (4 of 9 samples); however, insufficient data to list as impaired. (Binomial)

Pollutant: Assume "total" concentration, unless shown as dissolved.

DATA GAPS AND MO	NITORING NEEDS			
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Lead	Insufficient core parameters	Insufficient sampling events for core parameters		
DISCUSSION OF LOW PH IMPAIRMENT		Evidence of potential pH impairment: 1. Very low pH during four of 5 sampling events; 2. Historic mining in the area is a probable source; and 3. ADEQ is currently developing a TMI) that should address low pH as well as copper loadings.		
MONITORING RECOMMENDATIONS			o support copper and pH TMDLs and	
		Collect core parameters to repre assessment period.	sent at least 3 seasons during an	

MULE GULCH From Bisbee WWTP discharge to	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Highway 80 bridge 15080301 – 090C 3.8 Miles	A&Wedw – Impaired PBC – Impaired	Category 5	Cadmium, copper, zinc, low pH	Ongoing TMDL. Establishing site- specific copper standards.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 03/06/2000 – 08/27/2003			
DATABASE #		NUMBER AND TYPES OF SAL	NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other	
At MG-200 B (new) SPMLG010.61 102491	ADEQ TMDL	7-21 dissolved only: Copper, lead, and zinc 7-12 total only: Copper,	1sample: Ammonia, dissolved oxygen, total nitrogen, total phosphorus,	2 Fluoride 2 Turbidity	
Below Elfrida cutoff SPMUG007.81 100225	ADEQ TMDL	cadmium, manganese, and zinc 1-2 total and 0-2 dissolved: Antimony, arsenic, barium, beryllium boron, chromium, lead, mercury, nickel, silver, thallium 16 pH	nitrite/nitrate, total Kjeldahl nitrogen		
		(2 sites on 8 dates)			

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Cadmium (dissolved)	11.7 µg/L at 254 mg/L hardness 17.1 µg/L at 363 mg/L hardness 8.5 µg/L at 193 mg/L hardness A&Wedw acute	03/07/2000 – 13 μg/L 10/11/2000 – 34 μg/L 12/19/2002 – 86 μg/L	Remains impaired – Exceeded three times during a 3-year period.
Copper (total)	1300 μg/L PBC	08/17/2000 – 3,490 μg/L (d) 10/11/2000 – 6,293 μg/L (d) 10/18/2000 – 1,400 μg/L 07/20/2003 – 8,538 μg/L 08/13/2003 – 2,254 μg/L 08/26/2003 – 2,218 μg/L	Remains impaired – Exceeded criteria 6 of 11 sampling events. (Binomial)
Copper (dissolved)	33.1 μg/L at 254 mg/L hardness 49.6 μg/L at >400 mg/L hardness 24.6 μg/L at 190 mg/L hardness 24.6 μg/L at >400 mg/L hardness 27.0 μg/L at 210 mg/L hardness 25.8 μg/L at 203 mg/L hardness 33.1 μg/L at 264 mg/L hardness 49.6 μg/L at >400 mg/L hardness 400 mg/L hardness	03/07/2000 – 70 μg/L 08/08/2000 – 160 μg/L 08/18/2000 – 12,000 μg/L 10/12/2000 – 8,400 μg/L 10/17/2002 – 490 μg/L 05/28/2002 – 25 μg/L 12/18/2002 – 87μg/L 02/08/2003 – 86 μg/L 02/21/2003 – 100 μg/L 03/06/2003 – 130 μg/L 07/20/2003 – 14,000 μg/L 08/13/2003 – 97 μg/L 08/26/2003 – 4,900 μg/L	Remains impaired – Exceeded criteria 9 times during the last 3 years of monitoring (13 times during the assessment period)
Lead (total)	15 µg/L FBC	10/12/2000 – 49.3 μg/L	Inconclusive – Exceeded during 1 of 3 sampling events (both sites). (Binomial)
Zinc (dissolved)	228 µg/L at 214 mg/L hardness	03/07/2000 – 310 μg/L	Remains impaired – Exceeded criteria 3 time

	379.3 µg/L at >400 mg/L hardness 379.3 µg/L at >400 mg/L hardness 286 µg/L at 287 mg/L hardness 379.3 µg/L at >400 mg/L hardness 379.3 µg/L at >400 mg/L hardness 379.3 µg/L at >400 mg/L hardness A&Wedw acute	08/08/2000 - 1,100 μg/L 08/18/2000 - 2,400 μg/L 10/12/2000 - 1,200 μg/L 10/17/2002 - 4,300 μg/L 07/20/2003 - 4,500 μg/L 08/26/2003 - 3,500 μg/L	during the last 3 years of monitoring (7 times during the assessment period).
pН	>6.5 SU A&Wedw, PBC	08/17/2000 – 2.8 SU 10/11/2000 – 2.8 SU 08/26/2003 – 5.8 SU	Remains impaired – Did not meet standards in 3 of 8 sampling events (at both sites). (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Lead	Insufficient core parameters	Insufficient sampling events	Lab detection limits for selenium, dissolved mercuiry were higher than the surface water quality criteria.
MONITORING RECOMMENDATIONS		High Priority – Collect samples to support TMDLs and site specific copper standards. Collect additional lead samples due to exceedances. Use lower lab detection limits for selenium and dissolved mercury.	
		Collect core parameters to rep assessment period.	resent at least 3 seasons during an

MULE GULCH	USE SUPPORT	OVERALL ASSESSMENT
From Highway 80 bridge to Whitewater Draw 15080301 – 090D 4.5 Miles	A&We - Inconclusive PBC - Inconclusive AgL Inconclusive	Category 3 Inconclusive

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 10/11/2000		
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
At Elfrida cutoff road SPMLG005.79 102873	ADEQ TMDL	1 dissolved: Cadmium, copper, lead		
		1 pH		

EXCEEDANCES			
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (total)	500 μg/L AgL	10/11/2000 - 5,500 (d)	Inconclusive – Exceeded criterion in the single sample tested. (Binomial)
Copper (total)	1300 μg/L PBC	10/11/2000 - 5,500 (d)	Inconclusive – Exceeded criterion in the single sample tested. (Binomial)
Copper (dissolved)	67 μg/L at 307 mg/L hardness A&We acute	10/11/2000 – 5,500	Inconclusive – Exceeded criterion in the single sample tested.
рН	>6.5 SU A&We, PBC, AgL	10/11/2000 – 4.2 SU	Inconclusive – Did not meet criteria in the single sample tested. (Binomial)

Frequency Exceed = Samples collected within a 7-day period are aggregated and counted as one sample per site.

(d) Indicates that the sample result was really the dissolved portion only. Total copper concentration was probably higher.

	NITORING NEEDS			
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Copper and pH	Insufficient core parameters	Insufficient sampling events for core parameters.		
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Mule Gulch copper TMDL. Copper loadings from this tributary will be addressed in the Mule Gulch copper TMDL currently being developed.		
MONITORING RECOMMENDATIONS		High Priority –Collect copper an development.	d pH samples to support TMDL	
		Collect core parameters to repre assessment period.	sent at least 3 seasons during an	

MURAL HILL CANYON	USE SUPPORT	OVERALL ASSESSMENT
From headwaters to Mule Gulch 15080301 – 344 2.2 Miles	A&We - Inconclusive PBC - Inconclusive	Category 3 Inconclusive

SITE NAMES AGENCY ID # PURPOSE DATABASE #		SAMPLING DATES: 10/11/2000; 08/14/2004 NUMBER AND TYPES OF SAMPLES		
Above Highway 80 SPMHC000.09 103440	ADEQ TMDL	2 dissolved: Cadmium, copper, lead and zinc 1 total: Copper, lead and zinc		

EXCEEDANCE	S		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (total)	1300 μg/L PBC	10/11/2000 – 1400 μg/L	Inconclusive – Did not meet criterion in the single sample tested. (Binomial)
Copper (dissolved)	8.4 µg/L at 34 mg/L hardness A&We acute	10/11/2000 – 15 μg/L	Inconclusive – Exceeded criterion in 1 of 2 samples (once in a 3-year period).
Lead (total)	15 μg/L PBC	08/14/2004 – 470 μg/L	Inconclusive – Exceeded criterion in the one sample tested. (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Copper and lead	Insufficient core parameters	Insufficient sampling events for core parameters.		
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Mule Gulch copper TMDL. Copper loadings from this tributary will be addressed in the Mule Gulch copper TMDL currently being developed.		
MONITORING RECOMMENDATIONS		High Priority -Collect copper samples to support TMDL development on Mule Gulch as needed		
		Collect lead samples due to the	exceedance.	

RAMSEY CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Forest Road 110 15050202 – 404A 4.4 Miles	A&Wc - Inconclusive FBC - Attaining FC - Attaining Agl - Attaining AgL - Attaining	Category 2 Attaining some uses	

MONITORING	USED IN TH	IS ASSESSMENT		
SITE NAMES ID #	AGENCY PURPOSE	Sampling Periods: 01/26/2000 - 7/12/2000; 12/16/2004 - 06/02/2005		
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other
Above Nature Conservancy buildings SPRMC011.48 100625	ADEQ Ambient	5-6 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, copper, lead, mercury, zinc	7 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total	7 E. coli bacteria 7 Fluoride 7 Total dissolved solids 4 Suspended sediment
At Box Canyon SPRMC011.11 101060	ADEQ Ambient	6 total 0-1 dissolved metals: Boron, chromium, manganese	Kjeldahl nitrogen	concentration 7 Turbidity
		2-1 dissolved and total: Barium, nickel, silver, thallium.		

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Mercury (dissolved)	0.01 µg/L A&Wc chronic	02/23/2005 – 0.055 μg/L	Inconclusive – Only 1 exceedance during the assessment period. Lab detection limit for other samples was higher than the standard so could not be used to assess attainment.	

DATA GAPS AND MO	NITORING NEEDS	5	
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Medium Priority – Collect additional dissolved mercury samples due exceedance. Use lower lab detection limits for selenium and dissolved mercury.	

REDFIELD CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT
From tributary at 323339 / 1101841 to San Pedro River 15050203 - 0148 32.5 Miles	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive AgL – Inconclusive	Category 3 Inconclusive

SITE NAMES AGENCY ID # PURPOSE DATABASE #		SAMPLING DATE: 04/20/2005 NUMBER AND TYPES OF SAMPLES		
Below Sycamore Canyon SPRDC012.76 100628	ADEQ Ambient	1 dissolved and total metals: Antimony, arsenic, barium, beryllium, chromium, zinc 1 total metal only: Boron, copper, lead, mercury, manganese	I samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	1 E. coli bacteria 1 Fluoride 1 Total dissolved solid: 1 Suspended sediment concentration 1 Turbidity

EXCEEDANG	- 43		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Insufficient core parameters	Insufficient sampling events	Lab detection limits for selenium and dissolved metals (copper, lead, mercury) were higher than the A&W chronic criteria.	
MONITORING RECOMMENDATIONS		Low Priority —Collect core parameters to represent at least three seasons during an assessment period. Use lower lab detection limits for the dissolved metals and selenium.		

RIGGS FLAT LAKE	USE SUPPORT	OVERALL ASSESSMENT	
15050201 - 1210 9.2 Acres	A&Wc – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3 Inconclusive	
	Agl – Inconclusive AgL – Inconclusive		

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 08/11/200	03		
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients – Related	Other	
At Dam SPRIG-A 100074	ADEQ Ambient	I dissolved and total metals: Antimony, arsenic, barium, beryllium, boron, chromium, manganese, mercury, zinc total metal only: Cadmium, copper, lead, mercury, silver	1 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	Fluoride Total dissolved solids Turbidity	

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Ww	08/11/03 - 6.4 mg/L	Attaining Low dissolved oxygen due to natural conditions of groundwater upwelling. Low nutrient levels.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limits for dissolved metals (cadmium, copper, lead, mercury, and silver) were higher than the A&W chronic criteria.
MONITORING RECOMMEND	DATIONS	Low Priority - Collect core parduring an assessment period. Use lower lab detection limits	ameters to represent at least 3 seasons for the dissolved metals.

RUCKER CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Whitewater Draw 15080301-288 10.4 Miles	A&Wc - Inconclusive FBC - Attaining FC - Attaining AgL - Attaining	Attaining some uses	

SITE NAMES	AGENCY	SAMPLING PERIOD: 01/25/2000 – 06/16/2005				
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES				
DATABASE #		Metals	Nutrients - Related	Other		
Above Campground SPRUC007.81 100938	ADEQ Ambient	5-6 dissolved and total metals: Antimony, arsenic, beryllium, copper, lead. 6 total and 0-2 dissolved: Boron, cadmium, chromium, manganese, mercury, zinc 1-2 total and dissolved: Barium, silver, thallium	7 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	5 E. coli bacteria 7 Fluoride 7 Total dissolved solids 4 Suspended sediment concentration 7 Turbidity		

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	7.0 mg/L A&Ww	06/01/2000 – 6.4 mg/L 06/16/2005 – 5.5 mg/L	Attaining Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Low nutrient levels. Flow 0.03-0.07 cfs. Very low nutrients (nitrogen 0.03-0.07 mg/L).

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient dissolved metals (cadmium, copper, zinc) to assess A&W.		Lab detection limits for dissolved metals (cadmium, copper, lead, mercury, zinc) and total selenium were higher than the A&W chronic criteria in at least 2 samples.
MONITORING RECOMMEND	DATIONS	seasons during an assessment	core parameters to represent at least 3 period. s for the dissolved metals and selenium.

SAIT LEDICO KIVEK	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
From Mexico border to Charleston 15050202 – 008 28.3 Miles	A&Ww – Attaining FBC – Inconclusive FC – Attaining Agl – Attaining AgL – Attaining	Category 2 Attaining some uses		Copper added in 2004. Remove from list — attaining standards.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 01/12/2000 – 03/30/2005				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients Related	Other		
At Palominas Transect USGS #09470490 SPSPR151.28 101485	USGS Ambient	8-18 dissolved and total metals: Antimony, arsenic, barium, beryllium, chromium, cadmium, copper, lead, manganese, nickel,	16-17 samples: Ammonia, 48-73 Dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate,	16 <i>E. coli</i> bacteria 15 Fluoride 16 Total dissolved solids		
At Palominas, AZ USGS 09470500 SPSPR150.09 100275	USGS Ambient	silver, thallium, and zinc 17 total metals 0-2 dissolved: Boron, mercury 2 Selenium	total Kjeldahl nitrogen	22 Turbidity		
Near Hereford Road SPSPR144.76 101497	USGS Special study					
Above Highway 90 SPSPR134.35 100288	ADEQ Ambient					
At Route 90, near Lewis Springs SPSPR134.32 101499	USGS Special study					
At Charleston, AZ USGS 09471000 SPSPR127.50 100291	USGS Ambient					

EXCEEDANCE	S		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Arsenic	50 μg/L FBC	07/17/2001 – 86 μg/L	Attaining – Only 1 exceedance in 17 samples. (Binomial)
Copper (dissolved)	6.8 µg/L at 49 mg/L hardness A&Ww acute	07/17/2001 – 21 μg/L	Attaining – 0 exceedance during the last 3- years of monitoring (last exceedance in 2001)
Copper (total)	500 μg/L AgL	07/17/2001 – 1200 μg/L 08/19/2004 – 953 μg/L	Attaining – 2 exceedances in 17 samples. (Binomial)
Dissolved oxygen	6.0 mg/L A&W/w	06/19/2000 – 5.2 mg/L 09/17/2002 – 4.1 mg/L	Attaining – Only 1 sample did not meet standard in 68 samples. (Binomial) Other sample (one on 09/17/2002) was due to natural conditions (flow 0.021 cfs).
E. coli bacteria	235 CFU/100 ml FBC	04/14/2004 – 2,320 CFU/100 ml 08/19/2004 – 35,000 CFU/100 ml	Inconclusive – 2 exceedances within the last 3 years of monitoring. One of these was during a flood flow – 201 cfs – when surface water bacterial contamination is naturally very high. (See discussion below)
Lead	15 μg/L FBC	07/17/2001 – 230 μg/L 08/19/2004 – 230 μg/L	Attaining – 2 exceedances in 17 samples. (Binomial)
Mercury (dissolved)	0.01 μg/L A&Ww chronic	07/17/2001 – 0.57 μg/L	Inconclusive – Only 1 exceedance during the assessment period.

Suspended sediment concentration (SSC)	Geometric mean 80 mg/L	06/19/2000 – 1250 mg/L – 10 cfs 07/12/2000 – 147 mg/L – 8.3 cfs 10/26/2000 – 430 mg/L – 283 cfs* 08/14/2002 – 240 mg/L – 13 cfs 07/30/2003 – 1880 mg/L – 14 cfs 07/15/2004 – 138 mg/L – 0.6 cfs 08/19/2004 – 6830 mg/L – 201 cfs*	Inconclusive – 7 of 54 samples exceeded the 80 mg/L criterion. Two of the exceedances (*) and 10 other samples were not included in the geometric mean calculation, because flows were above the 5() Percentile of recorded flow. Using the remaining samples, the geometric mean did not exceed 80 mg/L.
Selenium	2.0 µg/L A&Ww chronic	07/17/2001 – 5 μg/L	Inconclusive – Only one of exceedance in the last 3 years of monitoring.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
E. coli bacteria, mercury, selenium, and suspended sediment concentration	Core parameters collected.		Lab detection limits for selenium and dissolved mercury were higher than the A&W dironic criteria.	
BACTERIA CONTAMINATION DISCUSSION		One of the 2 E. coli bacteria exceedances occurred during flood flow (200 cfs). Further monitoring is needed to determine whether bacterial contamination is solely due to natural conditions associated with such runoff events.		
MONITORING RECOMMENDATIONS			er samples to support TMDL development.	
		Recommend using biocriteria assessments and bottom deposits implementation procedures in this reach, when they are adopted.		
		Use lower lab detection limits for selenium and dissolved mercury.		

SAN PEDRO RIVER	USE SUPPORT	OVERALL ASSESSMENT	
From Charleston to Walnut Gulch 15050202 – 006 8.9 Miles	A&Ww - Attaining FBC - Attaining FC - Attaining Agl Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES	AGENCY	SAMPLING DATE: 01/26/2000 - 06/10/2003				
ID#	PURPOSE	Included E. coli samples at 2 TMDL sites collected 02/01/2006 NUMBER AND TYPES OF SAMPLES				
DATABASE #						
		Metals	Nutrients - Related	Other		
Below Graveyard Gulch SPSPR126.35 100653	ADEQ Ambient	5-6 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, zinc	7-9 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus,			
Above Boquillas Ranch SPSPR120.47 104005	ADEQ TMDL	3-6 total and 0-2 dissolved: Barium, boron, lead, mercury,	nitrite/nitrate, total Kjeldahl nitrogen	4 Suspended sediment concentration 10 Turbidity		
At Fairbanks, AZ SPSPR117.97 100287	ADEQ TMDL	manganese, nickel, silver, thallium				

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Core parameters collected.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMEND	ATIONS	Low Priority –Use lower lab mercury.	detection limits for selenium and dissolved

SAN PEDRO RIVER From Babocomari Creek to	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Dragoon Wash 15050202 – 003 17.0 Miles	A&Ww – Attaining FBC – Impaired FC – Attaining Agl – Attaining AgL – Attaining	Category 5	E. coll bacteria	Listed in 2004 due to 2 E. coli bacteria exceedances.

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 01/26/2000 - 08/03/2005					
DATABASE #		NUMBER AND TYPES OF SA	NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients – Related	Other			
16 sites along this segment.	Hargis and Associates Effectiveness monitoring	4-5 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, lead, zinc 4-5 total and 0-1 dissolved:	6-9 samples: Ammonia, pH, dissolved oxygen, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	6 E. coli bacteria 6 Fluoride 8 Total dissolved solid 3 Suspended sediment concentration			
Near Tombstone, AZ SPSPR115.90 101490	USGS Ambient	Boron, chromium, manganese, mercury	59 Nitrate samples	4 Turbidity			
At Escalante Crossing SPSPR105.49 103674	ADEQ Ambient	1-2 dissolved and total metals: Barium, nickel, silver, thallium,					
0.8 miles south of Highway 80 SPSPR102.01 100281	ADEQ Ambient						

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
E. coli bacteria	235 CFU/100 ml FBC	04/26/2000 – 310 CFU/100 ml 07/13/2000 – 660 CFU/100 ml	Remains impaired – Two exceedances during this assessment period. (2 of 6 samples). Exceedances were during normal/low flows.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Core parameters were collected		Lab detection limit for selenium and dissolved mercury was higher than the A&W chronic criteria.	
MONITORING RECOMMENDATIONS		High Priority – Collect <i>E. coli</i> bacteria samples in support of TMDL development. Continue to collect nitrate samples to determine effectiveness of we quality improvement actions at the Apache Nitrogen Superfund cleanup site upstream.		
		Use a lower lab detection lin samples.	nit for selenium and dissolved mercury	

SAN PEDRO RIVER	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
From Dragoon Wash to Tres Alamos Wash 15050202 – 002 15.5 Miles	A&Ww – Impaired FBC – Inconclusive FC – Inconclusive Agl – Inconclusive AgL – Inconclusive	Category 5	Nitrate	Listed due to nitrate since 1990.

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 06/21/200	01 – 02/01/2006			
DATABASE #		NUMBER AND TYPES OF SA	NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other		
Mid Apache Nitrogen Contamination Area SPSPR102.18 103660	Hargis and Associates Effectiveness monitoring	2 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, copper, lead, mercury, zinc	3-4 samples: Ammonia, pH, dissolved oxygen 2 Total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	2 E. coli bacteria 2 Fluoride 2 Total dissolved solids 2 Suspended sediment		
North of Highway 80 SPSPR101.25 100276	ADEQ Ambient	I total metal only: Boron, chromium, manganese		2 Turbidity		
Below Dragoon Wash SPSPR101.10 102712	ADEQ Ambient					
Apache Nitrogen Contamination Area SPSPR100.16 103662	Hargis and Associates Effectiveness monitoring					

EXCEEDANCE	S		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
E. coli bacteria	235 CFU/100 ml FBC	02/01/2006 – 579 CFU/100 ml	Inconclusive – Only 1 exceedance during this assessment period.
Lead	15 μg/L FBC	02/15/2005 – 20 μg/L	Inconclusive – Only 1 exceedance (only 1 sample tested for total lead) (Binomial)
Mercury (dissolved)	0.01 μg/L A&Ww chronic	02/15/2005 – 0.0104 μg/L	Inconclusive – Only 1 exceedance during the assessment period.
Nitrate	Site specific standard of 10 mg/L A&Ww	10/15/2001 – 24 mg/L 06/21/2001 – 34 mg/L 05/02/2002 – 38 mg/L 08/21/2002 – 44 mg/L 11/21/2002 – 53 mg/L 02/12/2003 – 29 mg/L 05/22/2003 – 51 mg/L 08/06/2003 – 27 mg/L 05/26/2004 – 14 mg/L 05/09/2005 – 24 mg/L 02/01/2006 – 27 mg/L	Remains impaired Exceeded criteria in 11 of 16 samples.
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Ww	02/15/2005 – 482 mg/L	Inconclusive – Exceeded criterion of 80 mg/L in 1 of 2 samples, but flow (at 22 cfs) above 90% of flow (about 11 cfs), so value could not be used to calculate the geometric mean. Insufficient samples to calculate the geometric mean.

DATA GAPS AND MOI			
EXCEEDANCES NEEDING	MISSING CORE	MISSING SEASONAL	DETECTION LIMITS NOT LOW
MORE SAMPLES TO ASSESS	PARAMETERS	DISTRIBUTION	ENOUGH
E. coli bacteria, lead, suspended	Insufficient core parameters	Insufficient sampling events	Lab detection limit for selenium was
sediment concentration.			higher than the A&W chronic criteria.
		Nitrogen Superfund cleanup sit Collect additional <i>E. coli</i> bacte concentration samples due to t biocriteria assessments and bot in this reach, when they are ad	ria, lead, and suspended sediment the exceedances. Recommend using tom deposits implementation procedures lopted. The resent at least three seasons during an

SAN PEDRO RIVER	USE SUPPORT	OVERALL ASSESSMENT	
to Hot Springs Canyon Creek 15050203 012	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive AgI Inconclusive AgL – Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/20/2003 – 11/29/2004			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients – Related	Other	
3 Links – River camp SPSPR075.41 102391	319 Grant/ADEQ Effectiveness monitoring		7 samples: pH, dissolved oxygen 3 samples: total nitrogen,	1 <i>E. coli</i> bacteria 4 Total dissolved solids 5 Turbidity	
3 Links – North field SPSPR074.25 102390	319 Grant/ADEQ Effectiveness monitoring		total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen		
3 Links – Upstream crossing SPSPR072.40 102389	319 Grant/ADEQ Effectiveness monitoring				
3 Links – 5 Gap SPSPR071.62 102388	319 Grant/ADEQ Effectiveness monitoring				

EXCEEDANG	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Samples represent 3 seasons.	
MONITORING RECOMMEN	DATIONS	The old turbidity standard (50 04/12/2004 at 74 NTU. Susper should be collected to determin Recommend using biocriteria a	meters to represent at least 3 seasons. NTU) was exceeded in one sample on ided sediment concentration samples are if the new SSC criterion is being met. Seessments and bottom deposits this reach, when they are adopted.

SAIN FEDRO RIVER	USE SUPPORT	OVERALL ASSESSMENT
From Hot Springs Canyon Creek to Redfield Canyon	A&Ww – Inconclusive FBC – Inconclusive	Category 2
From Hot Springs Canyon Creek to Redfield Canyon 15050203 011 16.0 Miles	FC - Attaining Agl Attaining AgL - Attaining	Attaining some uses

SITE NAMES	AGENCY PURPOSE	SAMPLING DATE: 03/02/2000 – 04/05/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At Cascabel, AZ SPSPR059.21 100289	ADEQ Ambient	5-16 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, mercury, silver, thallium, and zinc 14-16 total metal 0-1 dissolved: Boron, manganese, mercury	16 samples: Ammonia, pH, dissolved oxygen, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	15 E. coli bacteria 17 Fluoride 18 Total dissolved solids 10 Suspended sediment concentration 18 Turbidity	

POLLUTANT	STANDARD	DATES	DESIGNATED USE SUPPORT
	UNIT DESIGNATED USES	EXCEEDANCES	SUPPORTING EVIDENCE AND COMMENTS
Chromium	100 μg/L FBC	08/19/2004 – 240 μg/L	Attaining – Exceeded criterion in 1 of 16 samples. (Binomial)
Copper	500 μg/L AgL	08/19/2004 – 900 μg/L	Attaining – Exceeded criterion in 1 of 16 samples. (Binomial)
Copper (dissolved)	22.9 µg/L At 300 mg/L hardness A&Ww Acute	04/05/2005 – 25 μg/L	Inconclusive – Only 1 exceedance in 3-year period. (1 of 4 samples.)
Dissolved oxygen	6.0 mg/L A&Ww	08/23/2000 – 5.6 mg/L	Attaining – Only 1 exceedance in 18 samples. (Binomial) Exceedance occurred during flood flow with extremely high total nitrogen (65 mg/L) and high phosphorus (22 mg/L) reported.
E. coli bacteria	235 CFU/100 ml FBC	08/23/2000 – 16,000 CFU/100 ml 08/19/2004 – 1,000 CFU/100 ml	Inconclusive – Two exceedances within the assessment period, but both occurred during extreme flood flows. (See further discussion below.)
Lead	15 μg/L FBC	08/19/2004 – 620 μg/L	Attaining – Only 1 exceedances in 15 samples. (Binomial)
Lead	100 μg/L AgL	08/19/2004 – 620 μg/L	Attaining – Only 1 exceedance in 15 samples. (Binomial)
Manganese	10,000 μg/L Agl	08/19/2004 – 15,000 μg/L	Attaining – Only 1 exceedance in 15 samples. (Binomial)
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Ww	08/17/2004 – 16,880 mg/L	Attaining – Exceeded criterion of 80 mg/L in 1 of 10 samples. Sample was collected during flood flow, so result was not included in geometric mean calculation. Therefore, geometric mean standard was not exceeded. The magnitude of the sediment concentration suggests that sediment may be an issue in this drainage.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Dissolved copper and E. coli bacteria.	All core parameters were collected		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
BACTERIA CONTAMINATION	N DISCUSSION	66 cfs). Further monitoring is	es occurred during flood flows (27 cfs and s needed to determine whether bacterial to natural conditions associated with such
MONITORING RECOMMENI	DATIONS	Use lower lab detection limit Recommend using biocriteria	ts for the selenium and dissolved mercury. a assessments and bottom deposits in this reach, when they are adopted, due

SAN PEDRO RIVER	USE SUPPORT	OVERALL ASSESSMENT
From Buehman Wash to	A&Ww – Inconclusive FBC – Inconclusive	Category 2
Peppersauce Wash 15050203 008 16.4 Miles	FC - Attaining AgL - Inconclusive	Attaining some uses

SITE NAMES	AGENCY PURPOSE	SAMPLING DATE: 01/15/2004 - 04/06/2005		
DATABASE #		NUMBER AND TYPES OF SAM		
		Metals	Nutrients - Related	Other
At Valley Road near San Manuel SPSPR035.01 100285	ADEQ Ambient	3-5 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, mercury, zinc	4 samples: Ammonia, pH, dissolved oxygen, total nitrogen, total phosphorus, nitrite/nitrate, total	4 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids 4 Suspended sediment
Near San Manuel SPSPR034.66 101843	ADEQ TMDL	5 total and 0-1 dissolved: Boron, manganese, mercury	Kjeldahl nitrogen	concentration 4 Turbidity

EXCEEDANCE	3		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Chromium	100 μg/L FBC	08/17/2004 – 210 μg/L	Inconclusive Exceeded criterion in 1 of 4 samples. (Binomial)
Copper	500 μg/L AgL	08/17/2004 – 1100 μg/L	Inconclusive – Exceeded criterion in 1 of 3 samples. (Binomial)
Copper (dissolved)	9.5 μg/L At 69 mg/L hardness A&Ww Acute	01/05/2005 – 11 μg/L	Inconclusive – Only 1 exceedance in 3-year period. (1 of 4 samples.)
E. coli bacteria	235 CFU/100 ml FBC	08/17/2005 - 4000 CFU/100 ml	Inconclusive – Only 1 exceedance during this assessment period. (Occurred during flood flow)
Lead	15 μg/L FBC	08/17/2004 – 620 μg/L 01/05/2005 – 53 μg/L	Inconclusive – Only 2 exceedances in 4 samples (Binomial requires a minimum of 5 exceedances and 20 samples to list as impaired).
Lead	100 μg/L AgL	08/17/2004 – 620 μg/L	Inconclusive – Only 1 exceedance in 4 samples. (Binomial)
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Ww	08/17/2004 – 46,400 mg/L	Inconclusive – Exceeded criterion of 80 mg/L in 1 of 4 samples. However, sample was collected during flood flow, so result was not used to calculate a geometric mean. Insufficient samples left to calculate the geometric mean. Magnitude of the sediment concentration suggests that sediment may be an issue in this drainage.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Chromium, copper, <i>E. coli</i> bacteria, lead, and suspended sediment concentration.	All core parameters were collected		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMEND	DATIONS	and suspended sediment sam Use lower lab detection limit Recommend using biocriteria	ditional chromium, copper, E. coli, lead, aples due to the exceedances. Its for the selenium and dissolved mercury. It assessments and bottom deposits in this reach, when they are adopted, due ediment during flood flows.

SAN PEDRO RIVER	USE SUPPORT	OVERALL ASSESSMENT	
From Peppersauce Wash to Arivaipa Creek 15050203 – 003 21.3 Miles	A&Ww - Inconclusive FBC - Inconclusive FC - Inconclusive Agl - Inconclusive AgL - Inconclusive	Category 3 Inconclusive	

SITE NAMES	AGENCY	SAMPLING DATE: 01/05/200			
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES			
DATABASE #		Metals	Nutrients - Related	Other	
At Mammoth SPSPR023.77 103481	ADEQ TMDL	1 dissolved and total metals: Antimony, arsenic, beryllium, boron, chromium, cadmium, copper, lead, manganese, and zinc 1 total metals only: Mercury	1 Ammonia, nitrite/nitrate,		

EXCEEDANCE	:5		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper (dissolved)	9.6 µg/L at 70 mg/L hardness A&Ww acute	01/05/2005 – 16 μg/L	Inconclusive – Only sample exceedance in 3 year period.
Lead	15 μg/L FBC	01/05/2005 – 84 μg/L	Inconclusive – Exceeded lead criterion in only sample analyzed for lead.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Dissolved copper and total lead.	Insufficient core parameters	Insufficient samples	Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMEND	ATIONS	due to exceedances.	ditional lead and dissolved copper samples epresent at least 3 seasons during an

SAN PEDRO RIVER From Aravaipa Creek to Gila River	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
15050203 – 001 14.8 Miles	A&Ww – Impaired FBC – Impaired FC – Attaining Agl – Attaining AgL – Attaining	Category 5	E. coli bacteria and selenium	E. coli bacteria and selenium added in 2004

SITE NAMES ID # DATABASE #	AGENCY PURPOSE	SAMPLING DATE: 02/28/2000 – 04/06/2005 NUMBER AND TYPES OF SAMPLES		
Below Eskiminzin Wash SPSPR005.28 100726	ADEQ Ambient	12-18 dissolved and total metals: Antimony, arsenic, beryllium, chromium, cadmium, copper,	17-19 samples: Ammonia, 48-73 Dissolved oxygen, pH, total nitrogen, total	18 <i>E. coli</i> bacteria 19 Fluoride 18 Total dissolved solids
Above Roach Wash SPSPR003.85 101348	ADEQ Ambient	lead, and zinc 16-17 total metals 0-2 dissolved: Boron, manganese, mercury, and selenium	phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	8 Suspended sediment concentration 18 Turbidity
		5-6 total and dissolved: Barium, silver, thallium, nickel		

EXCEEDANCE		I DAMES	
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Arsenic	50 μg/L FBC	01/10/2001 – 63 μg/L	Attaining – Only 1 exceedance in 17 samples. (Binomial)
Chromium	100 μg/L FBC	08/16/2004 – 350 μg/L	Attaining – Only 1 exceedance in 17 samples. (Binomial)
Copper (total)	500 μg/L AgL	08/16/2004 – 930 μg/L	Attaining – Only 1 exceedance in 16 total copper samples. (Binomial)
E. coli bacteria	235 CFU/100 ml FBC	08/21/2000 – 600 CFU/100 ml 01/10/2001 – 3636 CFU/100 ml 09/10/2003 – 740 CFU/100 ml 01/15/2004 – 740 CFU/100 ml 08/16/2004 – 4100 CFU/100 ml	Remains impaired – 4 exceedances within the last 3 years of monitoring. (5 exceedances within the assessment period)
Lead	15 μg/L – FBC 100 μg/L – AgL	01/10/2001 – 140 μg/L 09/10/2003 – 42 μg/L 08/16/2004 – 980 μg/L	Attaining – Only 3 exceedances in 16 samples. (Binomial method requires a minimum of 5 exceedances and 20 samples to assess as impaired.)
Mercury	0.6 μg/L FC	04/17/2001 – 0.67 μg/L	Attaining – Only 1 of 16 samples exceeded the standard (Binomial)
Mercury (dissolved)	0.01 µg/L A&Ww chronic	04/17/2001 – 0.46 μg/L	Inconclusive – One exceedance during the assessment period.
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L	09/10/2003 - 664 mg/L - 6.9 cfs 08/16/2004 - 29,000 mg/L - 54 cfs*	Inconclusive – 2 of 8 samples exceeded 80 mg/L criteria. One of those could not be included in the geometric mean calculation, because it occurred during high flow event (*). Using the remaining samples, the geometric mean standard was not exceeded.
Selenium	2.0 µg/L A&Ww chronic	01/10/2001 – 11 μg/L	Remains impaired – Because of lab detection limits, only 1 sample could be used for this assessment, and that one exceeded the selenium criterion by a high magnitude.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Suspended sediment concentration and dissolved mercury	Core parameters collected.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMEND	ATIONS	TMDL development. Collect additional SSC and di exceedances. Very high suspe excessive sediment transport biocriteria assessments and b in this reach, when they are NTU) was exceeded in 4 of 1	issolved mercury samples due to ended sediment concentrations indicate in this drainage. Recommend using ottom deposits implementation procedures adopted. (The old turbidity criterion (50 18 samples (1000 to 7267 NTU).)

SNOW FLAT LAKE	USE SUPPORT	OVERALL ASSESSMENT	
15050201 - 1420 0.5 Acres	A&Wc – Inconclusive FBC – Inconclusive FC – Inconclusive AgI – Inconclusive AgL – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 08/11/200	2003		
DATABASE #		NUMBER AND TYPES OF SA	MPLES		
		Metals	Nutrients – Related	Other	
At Dam SPSNO-A 100084	ADEQ Ambient	1 dissolved and total metals: Antimony, arsenic, barium, beryllium, boron, chromium, copper, lead, manganese, mercury, zinc 1 total metals only: Cadmium, copper, mercury, silver	1 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	Fluoride Total dissolved solids Turbidity	

POLLUTANT	STANDARD UNIT	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENT
No Exceedances	DESIGNATED USES		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limits for dissolved metals (cadmium, copper, lead, mercury and silver) were higher than the A&W chronic criteria.
MONITORING RECOMMEND	DATIONS	Low Priority -Collect core par- seasons during an assessment p Use lower lab detection limits	

SPRING CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Mule Gulch 15080301 – 333 1 Miles	A&We – Inconclusive PBC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATE: 10/11/2000)	
DATABASE #		NUMBER AND TYPES OF SA	OF SAMPLES	
		Metals	Nutrients - Related	Other
At Highway 80 SPSPC000.11	ADEQ TMDL	1 dissolved: Cadmium, copper, lead, zinc		
102921		1 pH		

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Copper (dissolved)	16 µg/L at 68 mg/L hardness 8.4 µg/L at 35 mg/L hardness A&We acute	08/07/2000 – 76 mg/L 08/27/2003 – 44 mg/L	Inconclusive – Exceeded twice during the assessment period, but only once in a 3-year period.	
pH	>6.5 SU A&We and PBC	08/07/2000 – 5.7 SU	Inconclusive – 1 of 4 samples did not meet standards. (Binomial)	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Copper and low pH	Insufficient core parameters	Insufficient sampling events for core parameters, as only 2 seasons were represented.	
DISCUSSION OF EXCEEDANCES		Samples were collected to support the Mule Gulch copper TMDL. Copper loadings from this tributary will be addressed in the Mule Gulch copper TMDL currently being developed.	
MONITORING RECOMMENDATIONS			onal copper and pH samples due to DL development on Mule Gulch as

TURKEY CREEK	USE SUPPORT	OVERALL ASSESSMENT	
13.1 Miles	A&Wc - Inconclusive FBC - Attaining FC - Attaining Agl - Attaining AgL - Attaining	Category 2 Attaining some uses	

SITE NAMES AGENCY ID # PURPOSE		SAMPLING PERIOD: 08/17/2004 – 06/16/2005		
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other
Above upper campground SPTUR028.53 102113	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, beryllium. 4 total and 0-2 dissolved: Boron, cadmium, chromium, copper, lead, manganese, mercury, zinc	4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	4 E. coli bacteria 4 Fluoride 4 Total dissolved solids 4 Suspended sediment concentration 4 Turbidity

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	7.0 mg/L A&W/w	06/15/2005 – 3.24 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Low nutrient levels (nitrogen – 0.5 mg/L, phosphorus = >0.02 mg/L). Low flow =0.1 cfs.	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient dissolved metals (cadmium, copper, zinc) to assess A&W.		Lab detection limits for dissolved metals (cadmium, copper, lead, mercury, zinc) and total selenium were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority - Collect missing core parameters to represent at least 3 seasons during an assessment period. Use lower lab detection limits for the dissolved metals and selenium.	

TWIN POND	USE SUPPORT	OVERALL ASSESSMENT	
In San Bernardino National Refuge 15080302 – 0001 1 Acre	A&Wc - Inconclusive FBC - Inconclusive FC - Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 05/16/2002	2	
DATABASE #		NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other
At Dam SPTWP-USGS 101581	USGS Ambient	1 dissolved metals only: Antimony, arsenic, barium, beryllium, boron, cadmium, chromium, copper, lead, manganese, lead, silver, uranium and zinc	1 sample: Dissolved oxygen and pH (Nutrients were dissolved portion only)	1 Total dissolved solid: 1 Turbidity

EXCEEDANG	- []		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances		4	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	
MONITORING RECOMMEND	DATIONS	Low Priority -Collect core para seasons during an assessment p	ameters to represent at least three eriod.

WARD CANYON	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Turkey Creek 15050201 – 433 3.0 Miles	A&Wc – Inconclusive FBC – Attaining FC – Attaining AgL – Attaining	Category 2 Attaining some uses	

SITE NAMES	AGENCY	SAMPLING PERIOD: 08/17/2004 – 06/15/2005			
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES			
DATABASE #		Metals	Nutrients – Related	Other	
Below Saulsbury Canyon SPWRC000.09 102892	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, beryllium. 4 total and 0-2 dissolved: Boron, cadmium, chromium, copper, lead, manganese, mercury, zinc	4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	4 E. coli bacteria 4 Fluoride 4 Total dissolved solids 4 Suspended sediment concentration 4 Turbidity	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	7.0 mg/L A&Ww	06/15/2005 – 6.0 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Low nutrient levels. Flow 0.01 cfs.	

olved metals	Lab detection limits for dissolved	
per, zinc) to	metals (cadmium, copper, lead, mercury, zinc) and total selenium were higher than the A&W chronic criteria in at least 2 samples.	
during an assessment period	Low Priority -Collect core parameters to represent at least 3 seasons during an assessment period.	
	Low Priority –Collect core	

WHITEWATER DRAW	USE SUPPORT	OVERALL ASSESSMENT	
Gadwell Canyon to unnamed reach # 15080301-003 15080301 004 22.2 Miles	A&Wc - Inconclusive FBC - Inconclusive FC - Inconclusive Agl - Inconclusive AgL - Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 10/11/2000			
DATABASE #		NUMBER AND TYPES OF SAI	ID TYPES OF SAMPLES		
		Metals	Nutrients - Related	Other	
At Double Adobe Bridge SPWHD015.66 100230	ADEQ TMDL	I dissolved and total metals: Antimony, arsenic, barium, beryllium, boron, cadmium, chromium, copper, manganese, mercury, nickel, silver, thallium, and zinc	1 samples pH	1 Fluoride 1 Turbidity	

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limits for lead, dissolved lead, and selenium were higher than the criteria.
MONITORING RECOMMENDATIONS		Low Priority -Collect core para seasons during an assessment p	ameters to represent at least three eriod.
		Use lower lab detection limits and selenium.	for the lead (including dissolved lead)

WHITEWATER DRAW	USE SUPPORT	OVERALL ASSESSMENT	
III I TOTTI GITTIG	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive AgL – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID # DATABASE #	AGENCY PURPOSE	SAMPLING DATE: 03/07/2000 NUMBER AND TYPES OF SAMPLES		
		Metals	Nutrients – Related	Other
Site WD-1A (at border) SPWHD000.04 100512	ADEQ TMDL	1 total and dissolved metals: Arsenic, beryllium		

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
No Exceedances					

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters.	Insufficient sampling events.	
MONITORING RECOMMENDATIONS		Low Priority – Collect core parameters to represent at least three seasons during an assessment period.	

WINWOOD CANYON	USE SUPPORT	OVERALL ASSESSMENT	
I I COM I I I COM I I COM I I I I I I I I I I I I I I I I I I I	A&We – Inconclusive PBC – Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	NUMBER AND TYPES OF SAMPLES			
DATABASE #					
		Metals	Nutrients - Related	Other	
Tributary from Mural Hill above mineralized zone SPWNC000.67 102926	ADEQ TMDL	2 dissolved metals: Cadmium, copper, lead, and zinc 1 total metals: Copper, lead, zinc			
Above old mill site SPWNC000.35 102927	ADEQ TMDL	2 pH			

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Copper (dissolved)	11.9 µg/L at 49 mg/L hardness A&We acute	09/28/2004 – 49 μg/L	Inconclusive – 1 exceedance in a 3-year period.		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Copper	Insufficient core parameters	Insufficient sampling events.	
DISCUSSION OF EXCEEDANG	CES	Samples were collected to support copper loadings from this tribucular Coulch copper TMDL currently	ort the Mule Gulch copper TMDL. utary will be addressed in the Mule being developed.
MONITORING RECOMMENDATIONS		Medium Priority –Collect copper samples as needed to support TMDI development.	

Santa Cruz

Santa Cruz Watershed

Watershed Description

This watershed is composed of two hydrological areas: 1) the Santa Cruz River which flows north to the Gila River, and 2) a series of streams that flow south and eventually into the Rio Magdalena and Rio Sonoyta in Mexico. Most of the population in this 11,100 square mile watershed is clustered around metropolitan Tucson (approximately 844,000 people in the 2000 census) and Nogales in Arizona and Sonora Mexico (370,000 people, mostly in Mexico). Land ownership is approximately: 40% Tribal, 25% federal, 20% private, and 15% state.

Grazing is the dominant land use, with irrigated crop production near streams. Active and abandoned mines are scattered throughout the watershed. There are eight wilderness areas along with national forest and national monuments with restricted land uses.

Elevations range from 9,156 feet (above sea level) at Mount Lemmon to about 1,100 feet at the Gila River. Expect for a string of high mountains in the east, most of the watershed is below 5,000 feet, with low Sonoran desert flora and fauna and warmwater aquatic communities where perennial waters exist.

Water Resources

This watershed obtains about 15 inches of rain and up to 1 inch of snow per year. Ground water pumping has eliminated natural perennial flow in most of the mainstem Santa Cruz River. Treated wastewater effluent provides perennial flow below discharges from the cities of Nogales and Tucson.

An estimate of surface water resources in the Santa Cruz Watershed is provided in the following table. Waters on Tribal lands are not assessed by ADEQ; therefore, those statistics are shown separately.


Estimated Surface Water Resources in the Santa Cruz Watershed

	Perennial	Intermittent	Ephemeral	
Stream miles	85	500	7,2	
	Perennial	Non-perennial		
Lake acres	1,366	0		

On Tribal Land - Not Assessed

	Perennial	Intermittent	Ephemeral
Stream miles	0	50	3,795
	Perennial	Non-perennial	
Lake acres	9,523	11,119	

Ambient monitoring focuses on perennial waters; however, special investigations may identify water quality problems on intermittent and even ephemeral waters. Estimated miles and acres are based on USGS digitized hydrology at 1:100,000 and have been rounded to the nearest 5 miles or 5 acres.



Watershed Partnerships

- The Friends of the Santa Cruz River (FOSCR)
 - FOSCR focuses on the upper Santa Cruz River near Nogales Arizona/Mexico. Its mission is to ensure continued flow in the river, promote the highest water quality achievable, and protect and restore the riparian ecosystem and diversity of live along the stream. It accomplished this goal through education, partnerships, and advocacy for the benefit of present and future generations. They meet monthly on the 3rd Thursday. Contact Sherry Sass (President) at (520) 398-9093 or admin@friendsofsantacruzriver.org, or sushis@aol.com.
- Pima County Association of Government's (PAG) Watershed Planning Subcommittee.

This group provides a forum for exchanging information among stakeholders, concerning projects that may affect water quality or quantity in Pima County (much of the Santa Cruz Watershed). Pubic participation is encouraged. No regularly scheduled meetings. Information concerning the group's activities can be obtained at their website: http://www.pagnet.org/WQ/participation.htm, at wq@pagnet.org; or (520) 792-1093.

Special Studies and Water Quality Improvement Projects

Total Maximum Daily Load Analyses - The following TMDL analyses have been completed, are ongoing, or are scheduled to be completed in this watershed. Further information about the status of these investigations or a copy of the TMDL, if completed, can be obtained at ADEQ's website: www.azdeq.gov.

- Alum Gulch and a tributary (Humboldt Canyon) are impaired by cadmium, copper, zinc, and low pH (acidity). Pollution by these metals and acid mine drainage pose a risk to aquatic life and wildlife. TMDL analyses were completed and approved in 2003. Based on this study, primarily loading originates from the World's Fair Mine area and Humboldt Canyon with relatively minor contributions from Trench Camp Mine and the January Adit. It appears that the remediation efforts at Trench Camp and the January Adit have been relatively successful. To achieve standards, ADEQ will be working with landowners and interested stakeholders to implement the following remediation actions and strategies recommended in the TMDL:
 - Remove mine residue dumps from the stream banks,
 - Remove mine-waste sediments from the streambeds, and
 - Isolate and treat mine-impacted ground water discharges (springs and adits).
- Arivaca Lake is impaired by mercury.

A fish consumption advisory concerning mercury in fish tissue has been issued at this lake because mercury poses a health problem to humans. Mercury also poses risks to other species that eat the fish. EPA collaborated with ADEQ and completed a mercury TMDL in 1999. The primary sources of mercury were identified as: atmospheric deposition (particulates in the air) and natural deposition from local substrates. Because atmospheric deposition is not readily controllable, and the primary land use is grazing, improvements in livestock management to reduce soil erosion were targeted in the TMDL implementation plan. ADEQ is working with interested landowners and stakeholders to implement these improvements.

Harshaw Creek is impaired by copper and low pH (acidity). Copper and acid mine drainage may negatively impact aquatic life and wildlife. TMDL loading analyses were completed in 2003. This report identified abandoned or inactive mines that were the primary sources of the copper

and acid mine waste. To achieve standards, ADEO will be working with landowners and interested stakeholders to implement the following remediation actions and strategies recommended in the TMDL:

- Remove mine residue dumps from the stream banks,
- Remove mine-waste sediments from the streambeds, and
- Isolate and treat mine-impacted ground water discharges (springs and adits).
- Lakeside Lake in Tucson is impaired by nutrients, ammonia, high pH, and low levels of dissolved oxygen. Excess nutrients (nitrogen) may result in low dissolved oxygen and high pH and potentially toxic algal blooms and fish kills. High levels of ammonia may also pose a risk to aquatic life. TMDL analyses were completed in 2005 and indicated that the water sources supplying the lake were the primary source of nutrients to the lake. Lakeside

Lake receives secondary-treated reclaimed effluent, ground water, Central Arizona Project (CAP) water from the Colorado River, and occasional storm water runoff from Atterbury Wash.

ADEQ has been working with the city of Tucson, Pima County Wastewater Management Department, and other interested stakeholders to mitigate these problems. The city of Tucson has been testing aerators that physically increase dissolved oxygen levels in the water column. However, increased agitation and vertical mixing stimulated greater algal productivity, high pH levels, and did not reduce the ammonia concentration. Tucson is also testing the use of alum to reduce phosphorus loading in the lake.

- Three R (3R) Canyon and Cox Gulch are impaired by beryllium, cadmium, copper, zinc, and low pH (acidity). These metals and acid mine drainage represent a risk to aquatic and wildlife. TMDLs were completed in 2003 and quantified contributions from 3R Mine and unnamed springs. However, a Phase II TMDL is needed to determine if there are other significant contributions in the basin. To achieve standards, ADEQ will be working with landowners and interested stakeholders to implement the following remediation actions and strategies recommended in the TMDL:
 - o Remove mine residue dumps from the stream banks,
 - o Remove mine-waste sediments from the streambeds, and
 - o Isolate and treat mine-impacted ground water discharges (springs and adits).
- Pena Blanca Lake is impaired by mercury.

A fish consumption advisory concerning mercury in fish tissue has been issued at this lake because mercury poses a health problem to humans. Mercury also poses risks to other species that eat the fish. EPA collaborated with ADEQ and completed a mercury TMDL in 1999. The study identified three sources of mercury: atmospheric deposition (particulates in the air), St. Patrick Mine ball mill site, and generalized natural deposition from local substrates. To meet standards, the TMDL analysis and implementation plan indicated that the tailings and sediment should be removed from the ball mill site. ADEQ is to conduct further monitoring on fish tissue to determine whether these measures were sufficient.

- Nogales Wash is impaired by ammonia, Escherichia coli, copper, and chlorine. Exceedances of the E. coli standard may represent a significant public health concern if people are swimming or even wading in the water. Ammonia, chlorine and copper pose a threat to aquatic life and wildlife. Wastewater infrastructure has deteriorated in Mexico and must be replaced. To protect the human health chlorine is added directly to the Wash continuously via drip systems and manual introduction of chlorine tables. Chlorine residuals are monitored daily in an attempt to keep chlorine residuals at or above 1 mg/L at the US and Mexico border (which is 100 times above the standard for aquatic life use). Although these conditions pose significant threats to human health and aquatic life, actions to correct the situation are dependent on ongoing international negotiations between several government officials (representing the United States, Arizona, Mexico, the cities of Nogales Arizona and Nogales Sonora, and the Mexican state of Sonora). The source loadings are known and the technical means to correct the problem have been determined. These TMDLs will be developed if needed after facility upgrades are completed.
- Santa Cruz River from Mexico to the Nogales International Wastewater Treatment Plant discharge is impaired by Escherichia coli bacteria.
 Exceedances of the E. coli standard may represent a significant public health concern if people are swimming or even wading in the water. Completing this TMDL may be complex due to probable sources in Mexico and intermittent stream flow. Drought conditions have slowed collection of adequate data to determine source loadings. A TMDL will be initiated when flow resumes.
- Sonoita Creek is impaired by zinc in the 14-mile segment just above its confluence with the Santa Cruz River.
 The federally protected Gila topminnow occurs in this reach and could be negatively impacted by dissolved zinc.
 Sources of the zinc have not been investigated but are likely related to transport of zinc during storm flows from its tributaries (e.g., Alum Gulch and 3R Canyon). Monitoring will be used to determine if strategies implemented on these tributaries reduce zinc transport sufficiently to eliminate exceedances on Sonoita Creek.

Parker Canyon Lake is impaired by mercury.
 A fish consumption advisory concerning mercury in fish tissue has been issued at this lake because mercury poses a health problem to humans. Mercury also poses risks to other species that eat the fish. A TMDL is scheduled to be initiated in 2006.

Water Quality Improvement Grant Projects – ADEQ awarded the following Water Quality Improvement Grants (319 Grants) in this watershed. More information concerning these grants or projects can be obtained at: http://www.azdeq.gov/environ/water/watershed/fin.html.

- BMPs to Control Sedimentation on the Santa Cruz River Project
 The Coronado Resource Conservation and Development Area (2000)
 Implement management practices to control sedimentation along a thousand feet of the Santa Cruz River.
- Riverfront Residence Green Roof Project
 A private consultant (2001)
 Install a 3400 square feet "green roof" (waterproofing, soil, and vegetative cover) to demonstrate how to mitigate impacts of urban runoff by slowing and absorbing runoff from the roof. The landscaping acts as a filter strip, minimizing pollutant transport. The reduction of runoff should also reduce soil erosion on-site and downstream.
- Best Management Practices: A Balancing Act Project
 Pima Natural Resource Conservation District (2001)
 Demonstrate agricultural practices that will minimize crop amendment (fertilizers, pesticides) loss. Losses frequently occur due to deep percolation, erosion, runoff, evaporation, and drift.
- Palo Alto Runoff Control Project
 Coronado Resource Conservation and Development Area (2002)
 Implement Best Management Practices on high priority areas in the Alter Valley subwatershed to control runoff that contributes sediment to the Santa Cruz River system. The objective is to reduce sediment production from gully erosion and headcutting on the Palo Alto Ranch along Alter Wash.
- Enhanced Implementation of Deferred Rotational Grazing on C6 Ranch Project
 Rancher in collaboration with the University of Arizona Extension Service (2002)
 Project will build fences to exclude livestock, develop alternative water sources for livestock, construct erosion control dams in gullies, and implement a comprehensive plan for monitoring effectiveness. Project is also a teaching opportunity.
- Santa Cruz River Riparian Re-vegetation Project
 Montessori De Santa Cruz Charter School (2003)
 Repair riparian habitat and provide community education and outreach. This is a collaborative project between the Montessori School, Tumacacori National Historical park Service, and the Friends of the Santa Cruz River.
- Santa Cruz River Sediment Control Project
 Coronado Resource Conservation and Development Area (2004)
 Install 800 feet Kellner jacks and revegetate with native species along the south river road bank of the Santa Cruz River to improve stream bank stability.
- Redrock Canyon and Upper Santa Cruz Watershed Improvement Project
 Coronado Resource Conservation and Development Area (2005 and 2006).
 Work with the five grazing allotments in the Red Rock Canyon (a tributary to Sonoita Creek) control erosion and sediment transport by implementing best grazing practices. Project excluded cattle from riparian areas using fencing, revegetation of riparian areas, and development of alternative sources of water.

Water Protection Fund Projects – The following Water Protection Fund Projects were awarded by the Arizona Department of Water Resources. More information about these funds or projects can be obtained from the ADWR web site at: http://www.azwater.gov.

• Riparian Restoration on the Santa Fe Ranch Project

The Coronado Resource Conservation and Development Area (2000)

Revegetate degraded riparian areas along the Santa Cruz River. The project would erect fencing to exclude cattle. The project would also develop a teacher's guide to riparian restoration, provide site tours, and a photo display of techniques used.

• Tucson Audubon Society's North Simpson Ranch Riparian Recovery Project

Tucson Audubon Society (2000 and 2004)

Increase vegetative diversity and increase stream bank stability along the Santa Cruz River. Management measures included rainwater harvesting, mulching, and fencing out cattle and unauthorized vehicles. The project would also provide a long-range strategy for habitat connectivity, human access, and a sustainable riparian habitat.

• Riparian Restoration on the San Xavier District Project

San Xavier District of the Tohono O'odham Indian Community (2002)

This was a cooperative riparian restoration and management project sponsored by the San X_{avier} District of the Tohono O'odham, Mark Briggs (an ecologist), the Sonoran Joint Venture, and the U.S. Fish and Wildlife Service.

• Esperanza Ranch Riparian Restoration Project

The Tucson Audubon Society (2005)

Restore the riparian area in a 300 acre ranch along the Santa Cruz River and Chivas Wash.

U.S. Army Corps of Engineers' Ecosystem Restoration Projects – Ecosystem restoration, environmental stewardship, and radioactive site cleanup projects are funded through the annual federal Energy and Water budget. The purpose of ecosystem restoration is to re-establish attributes of a natural functioning and self-regulating system.

• Ed Pastor Kino Environmental Restoration Project

The Tucson (Ajo) Detection Basin and Tucson Diversion Channel has been expanded to include 141 acres, including: 50 acres of wetlands, 12 acres of wildlife and open water areas, and 38 acres of mescluite bosque and ephemeral grassland. The project uses stormwater runoff and reclaimed water.

Agua Caliente Spring

The project has multiple objectives that will improve ecosystem function, restore the natural structure and function of the spring, improve habitat, and create education and recreational opportunities. The recommended plan would keep one pond and create a native cienaga-type wetland (eliminating pond 2 and 3).

• Rillito River Riparian Area (Swan Wetlands)

The plan is to restore riparian vegetative communities along the south bank of the Rillito River, between Craycroft Road and Columbus Boulevard (61 acres), to a more natural state. Improvements in the riparian condition will increase functional habitat and minimize sediment and organic accumulation.

Paseo de las Iglesias

The objective is to increase the functional riparian and floodplain habitat along the Santa Cruz River, the West Branch of the Santa Cruz River, and Los Reales Road. Increased riparian area will increase wildlife habitat, provide passive recreation opportunities, reduce flood damage, reduce bank erosion and sedimentation, and improve water quality. Irrigated planting of mesquite and riparian shrub will be placed on terraces above the low flow channel and in the historic floodplain, with small areas of emergent marsh and cottonwood-willow habitat. Water will be provided by water harvesting and reclaimed wastewater.

El Rio Antiguo

Restore riparian vegetative communities along the Rillito River, between Craycroft Road and Campbell Avenue. Cottonwood-willow, mesquite, shrub and grasses will be planted in the channel, in tributary mouths, and in water harvesting basins on the tributaries. A culvert and pipeline will allow water to flow behind the soil cement during 2-year and higher flood events to provide water to riparian pant communities along the north bank in the upstream study area.

Tres Rios del Norte

This project is located along the Santa Cruz River between Prince Road to Sanders Road, West Moore Road and West Avra Valley Road. It will restore 19 miles of wetland and riparian vegetative communities along the Santa Cruz River and its adjacent floodplains. The restoration would vastly improve mesquite, cottonwood-willow, and emergent wetland habitats to a condition supportive of wildlife, and for the benefit of residents and visitors to the area.

Other Water Quality Studies – The following additional water quality related studies were completed since 2000 in this watershed:

• The Water Quality of Priority Streams in Pima County

Pima Association of Governments (2002)

This report compiles the existing water quality data and other pertinent information for the streams that have been identified as priorities in Pima County.

- Water Issues of the Arizona Mexico Border: The Santa Cruz, San Pedro, and Colorado Rivers.
 Terry W. Sprouse, University of Arizona, Water Resources Research Center (2005)
 Summary of water quality and water quantity issues facing this region.
- Water Quality Data for Selected National Park Units, Southern and Central Arizona and West-Central New Mexico, Water Years 2003 and 2004

U.S. Geological Survey in cooperation with the National Park Service (2005)

Field measurements and water samples were collected at springs, mine adits, streams, and wells at 30 sites in 9 park units in 2003-2004 to provide baseline (ambient) water quality information. Only 24 of the 30 sites were sampled three times due to drought conditions and lack of water during parts of the year. Analyses of data collected at these sites indicated:

- Dissolved uranium was elevated at Williams Spring in Organ Pipe National Monument at 32 μg/L; and
- Concentrations of nitrate and nitrite (nutrients) were elevated at Dripping Springs in Organ Pipe Cactus National Monument, Fern Grotto on Coronado National Memorial, and Wild Horse Mine in the Tucson Mountain District of Saguaro National Park.
- Simulated Water Level Responses, Ground Water Fluxes, and Storage Changes for Recharge Scenarios along Rillito Creek, Tucson, Arizona

John P. Hoffmann and S.A. Leake, U.S. Geological Survey (2004)

The amount of water currently recharging the aquifers within the Tucson area is insufficient to meet current and projected demands. Ground water in this area has dropped more than 200 feet since the middle of the 20th Century (causing streams to become ephemeral). A local ground water flow model is used to simulate four recharge scenarios along Rillito Creek in northern Tucson to evaluate mitigating effects on ground water deficits and water level declines in Tucson's Central Well Field.

 Assessment of Selected Inorganic Constituents in Streams in the Central Arizona Basins Study Area, Arizona and Northern Mexico, through 1998

David Anning – U.S. Geological Survey, National Water Quality Assessment Program (2003) Inorganic chemical data (dissolved solids, suspended sediment, and nutrients) and stream properties (temperature, pH, dissolved oxygen) were analyzed to assess water quality, determine natural and human factors affecting water quality, and compute stream loads.

• Border Crossings - Water and Wastewater at the International Boundary

R.G. Charles Graf and Craig Tinney (ADEQ) and Tom Konner (EPA Region IX)

September/October 2005 Southwest Hydrology (2005)


This article describes the problems and progress being made in addressing water quality and wastewater infrastructure along the Mexican border with California and Arizona for seven key populations centers: San Diego/Tijuana, Tecate, Calexico/Mexicali, San Luis/San Luis Rio Colorado (Yuma area), Nogales, Naco/Bisbee, and Douglas/Agua Prieta.

Assessments

The Santa Cruz Watershed can be separated into the following drainage areas (subwatersheds):

15050202 D	
15050302 Pantano Wash	
15050302 Lower Santa Cruz	
15050304 Brawley Wash	
15050305 Aguirre Wash	
15050306 Santa Rosa Wash	
15080101 San Simon Wash (On Tribal Land – Not Assessed	(b:
15080102 Rio Sonoyta	
15080103 Tule Desert	
15080200 Rio Asuncion	

These drainage areas and the surface waters assessed as "attaining" or "impaired" are illustrated on the following watershed map. Methods used to complete these assessments are described in the "Surface Water Assessment Methods and Technical Support" document (2006).



ALUM GULCH From headwaters to 312820 /	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
1104351 (to beginning of intermittent flow) 15050301 - 561A 0.8 Miles	A&We – Impaired PBC – Impaired AgL – Impaired	Category 4A Not attaining	Cadmium, copper, zinc, and pH	TMDL completed in 2003. Need to implement improvements at mining sites.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATES: 01/11/2000; 06/08/2004				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
At January Mine Adit SCALG005.45 102952	USGS Ambient	1 total and 2 dissolved metals: Cadmium, copper, zinc 1 dissolved only: Barium,	2 samples: Dissolved oxygen and pH			
Below January Mine Adit, above Humboldt Canyon SCALG005.35 100838	ADEQ TMDL	beryllium, boron, chromium, lead, manganese, nickel, silver				

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Cadmium	50 μg/L AgL	01/11/2000 – 170 μg/L 06/08/2004 – 208 μg/L	Remains impaired Exceeded in 2 of 2 samples (Binomial)
Copper (dissolved)	85.8 µg/L at >400 mg/L hardness A&We acute	01/11/2000 – 400 μg/L	Remains impaired Exceeded once in the last 3 years of monitoring
Lead	15 μg/L PBC	06/08/2004 – 143 μg/L	Inconclusive – Exceeded in only sample tested for lead concentration. (Binomial)
Zinc (dissolved)	3,599 µg/L at >400 mg/L hardness A&We acute	01/11/2000 – 56,000 μg/L 06/08/2004 – 99,300 μg/L	Remains impaired Exceeded twice in the last 3 years of monitoring
Zinc (total)	25,000 μg/L AgL	01/11/2000 – 56,000 μg/L 06/08/2004 – 99,300 μg/L	Remains impaired Exceeded in 2 of 2 samples (Binomial)
pH	<6.5 SU A&We, PBC, AgL	01/11/2000 - 4.7 SU 06/08/2004 - 4.5 SU	Remains impaired Exceeded in 2 of 2 samples (Binomial)

DATA GAPS AND MO	NITORING NEEDS			
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Lead	Insufficient core parameters	Insufficient monitoring events		
MONITORING RECOMMENT	DATIONS	Medium Priority – Collect samples during crucial conditions to determine effectiveness of improvements at mine sites in this watersh once improvements are completed. Collect additional lead samples due to exceedance. Collect core parameters to represent at least 3 seasons during an assessment period.		

ALUM GULCH From 312820 / 1104351 to	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
	A&Ww – Impaired FBC – Impaired AgL – Impaired	Category 4A Not attaining	Cadmium, copper, zinc, and pH	TMDL completed in 2003. Need to implement improvements at mining sites.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATES: 01/11/2000)	
DATABASE #		NUMBER AND TYPES OF SAM	APLES	
		Metals	Nutrients - Related	Other
Below World's Fair Mine SCALG004.45 100870	ADEQ TMDL	1 total and dissolved metal samples: Cadmium, copper, zinc	1 sample: Dissolved oxygen and pH	

EXCEEDANCES			
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Cadmium	50 μg/L – AgL 84 μg/L – FBC	01/11/2000 – 290 μg/L	Remains impaired – Exceeded criterion in only sample collected. (Binomial)
Cadmium (dissolved)	19.1 µg/L at >400 mg/L hardness A&Ww acute	01/11/2000 – 220 μg/L	Remains impaired – Exceeded criterion in only sample collected.
Copper	500 μg/L – AgL 1300 μg/L – FBC	01/11/2000 – 2100 μg/L	Remains impaired – Exceeded criterion in only sample collected. (Binomial)
Copper (dissolved)	49.6 µg/L at >400 mg/L hardness A&Ww acute	01/11/2000 – 2000 μg/L	Remains impaired – Exceeded criterion in only sample collected.
Zinc	25,000 μg/L AgL	01/11/2000 – 53,000 μg/L	Remains impaired – Exceeded criterion in only sample collected. (Binomial)
Zinc (dissolved)	Calculated as 379.3 µg/L A&Ww acute	01/11/2000 – 54,000 μg/L	Remains impaired – Exceeded criterion in only sample collected.
pН	<6.5 SU A&Ww, FBC, AgL	01/11/2000 – 3.2 SU	Remains impaired – Exceeded criterion in only sample collected. (Binomial)

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient monitoring events	
MONITORING RECOMMEND	DATIONS	once improvements are comple	ovements at mine sites in this watershed
	,	assessment period.	sent at least 3 seasons daring an

ARIVACA CIENEGA	USE SUPPORT	OVERALL ASSESSMENT	
15050304 0001 3 Acres	A&Ww - Inconclusive FBC - Inconclusive FC - Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 05/15/20	02	
DATABASE #		NUMBER AND TYPES OF SA	AMPLES	
		Metals	Nutrients – Related	Other
Mid lake SCACL-USGS 101583	USGS Ambient	I dissolved metal only: Antimony, arsenic, barium, beryllium, boron, cadmium, chromium, copper, lead, manganese, nickel, selenium, silver, uranium, and zinc. (O total metals)	1 sample: Dissolved oxygen and pH	1 Total dissolved solids 1 Turbidity

EXCEEDANG	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Missing all core parameters	Insufficient sampling events.	
MONITORING RECOMMEND	PATIONS	Low Priority – Collect missing of seasons during an assessment pe	core parameters to represent at least 3 eriod.

ARIVACA LAKE 15050304 0080	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
118 Acres	A&Ww – Inconclusive FBC – Attaining FC – Impaired AgI – Attaining AgL – Attaining	Category 4A Not attaining	Mercury in fish tissue	Mercury TMDL completed in 1999

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 07/19/2	000 – 05/21/2001; 09/17/200	3; 04/06/2004
DATABASE #		NUMBER AND TYPES OF SA	MPLES	
		Metals	Nutrients – Related	Other
At Dam SCARI-A 100000 (main site sampled)	ADEQ, U of A, AGFD Ambient	6-7 total and 4 dissolved: Cadmium, chromium, lead, nickel, zinc	6-7 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl	3 E. coli bacteria 7 Fluoride 3 Total dissolved solids 7 Turbidity
Mid lake SCARI-B 101734	U of A Ambient	7 total and 1 dissolved metals: Antimony, arsenic, barium, beryllium, boron, copper,	nitrogen	
At boat ramp SCARI-C 102534	AGFD Ambient	manganese, mercury		
At Chimney Canyon SCARI-CHIM 102535	AGFD Ambient			

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	6.0 mg/L A&W/w	09/17/2003 – 4.2 mg/L	Attaining – Did not meet dissolved oxygen criteria in 2 of 10 samples (1 of 7 sampling events). (Binomial)
Selenium	2.0 µg/L A&Ww chronic	05/21/2001 – 4.0 μg/L	Inconclusive – Exceeded 1 time during the assessment period.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Selenium	Insufficient dissolved copper needed to assess A&W		Lab detection limits for selenium and dissolved metals (cadmium, copper, lead, and mercury) were higher than A&W chronic criteria.
MONITORING RECOMMENE	DATIONS	Medium Priority – Collect sa water quality improvement a Collect selenium samples due	
		Collect core parameters to reassessment period.	epresent at least 3 seasons during an
		Use lower lab detection limit	t for dissolved metals and selenium.

BIG CASA BLANCA CANYON	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Sonoita Creek 15050301 – 606 3 Miles	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 07/03/2004			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At long pool SCBCC006.33 103031	AGFD Ambient	2 total metal: Arsenic, barium, beryllium, cadmium, chromium, copper, manganese, nickel silver,			
At frog pool SCBCC006.74 103032	AGFD Ambient	and zinc. (Both sites sampled on same date)			

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limits for selenium, mercury, and lead were higher than the applicable water quality criteria.
MONITORING RECOMMENDATIONS		Low Priority – Collect missing core parameters to represent at least 3 seasons during an assessment period. Use lower lab detection limit for selenium, mercury, and lead.	

CARPENTER TANK	USE SUPPORT	OVERALL ASSESSMENT	
15050304 0002 3 Acres	A&Ww - Inconclusive FBC - Inconclusive	Category 3	
	FC – Inconclusive	Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 05/15/2002			
DATABASE #		NUMBER AND TYPES OF SA	AMPLES	·	
		Metals	Nutrients – Related	Other	
Mid lake SCCAR-USGS 101582	USGS Ambient	I dissolved metal only: Antimony, arsenic, barium, beryllium, boron, cadmium, chromium, copper, lead, manganese, nickel, selenium, silver, uranium, and zinc. (O total metals)	1 sample: Dissolved oxygen and pH	1 Total dissolved solids 1 Turbidity	

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

DATA GAPS AND MOI EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events.	21100011
MONITORING RECOMMEND	PATIONS	Low Priority – Collect missing of seasons during an assessment p	core parameters to represent at least 3 eriod.

CHIMENEA CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Rincon Creek 15050302 – 140 8 Miles	A&Ww – Attaining FBC – Inconclusive FC – Inconclusive	Category 2 Attaining some uses	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 05/14/20	- 11/16/2005			
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
At Saguaro National Park SCCHM004.75 101593	USGS Ambient	0-1 total metals and 4-5 dissolved: Antimony, beryllium, boron, cadmium, chromium, copper, lead, manganese, and	1 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen 3 samples: Dissolved oxygen	1 Fluoride 4 Total dissolved solids 1 Suspended sediment concentration		
Near Madrona Ranger Station	USGS	zinc.	4 samples: Total phosphorus 7 samples: pH	1 Turbidity		
SCCHM002.01 101584		0-1 total and 0-1 dissolved: Arsenic, barium, mercury, nickel, selenium, silver, uranium				

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances		(4)	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient total metals and E. coli bacteria to assess FBC and AgL.		Lab detection limit for selenium was higher than the A&W chronic criteria
MONITORING RECOMMENDATIONS		Low Priority – Collect missin seasons during an assessment	g core parameters to represent at least 3 period.
		Use lower lab detection limit	t for selenium.

CIENEGA CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Gardner Canyon 15050302 – 006A 18.08 Miles	A&Ww - Attaining FBC - Attaining FC - Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES ID # DATABASE #	AGENCY PURPOSE	SAMPLING PERIOD: 12/11/2000 – 03/20/2002; 09/27/2005 – 02/16/2006 (Included 02/16/2005 to have sufficient samples to assess designated uses) NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At Cedar Canyon SCCIE026.68 101176	ADEQ Special study	14-15 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium,	10-13 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus,	3 <i>E. coli</i> bacteria 14 Fluoride 14 Total dissolved solids	
At Stevenson Canyon SCCIE022.42 100266	ADEQ Ambient	copper, lead, nickel, silver, thallium, and zinc.	nitrite/nitrate, total Kjeldahl nitrogen	1 Suspended sediment concentration 14 Turbidity	
Below Pump Canyon SCCIE020.88 101177	ADEQ Special Study	15 total and 0-2 dissolved: Boron, manganese, mercury			

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Dissolved oxygen	6.0 mg/L A&W/w	09/27/2005 – 5.0 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Low nutrient levels. Flow 0.5 cfs.		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters.		Lab detection limits for selenium and dissolved mercury and nickel were higher than the A&W chronic criteria in at least 5 samples.
MONITORING RECOMMENDATIONS		Low Priority – Use lower lab mercury, and dissolved nicke	detection limits for selenium, dissolved l.

CIENEGA CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From Gardner Canyon to USGS gage station (Pantano Wash) 15050302 – 006B 28.8 Miles Unique Water	A&Ww - Attaining FBC - Attaining FC - Attaining AgL - Attaining	Category 1 Attaining all uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD : 12/12/2000 – 03/20/2002; 9/26/2005 – 2/14/2006 (Added in 2006 data to assess more uses)				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
SW of bench mark #3490 SCCIE006.69 101178	ADEQ Special study	10-14 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, silver,	13-14 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total	3 E. coli bacteria 14 Fluoride 14 Total dissolved solid: 2 Suspended sediment		
Above Davidson Canyon SCCIE0004.25 101179	ADEQ Ambient and Special study	thallium, and zinc. 14-15 total and 0-2 dissolved: Boron, manganese, mercury	Kjeldahl nitrogen	concentration 15 Turbidity		

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	6.0 mg/L A&Ww	09/18/2001 – 5.4 mg/L	Attaining – Low dissolved oxygen due to natural conditions of low flow and ground water upwelling. Low nutrient levels. Flow 0.7 cfs.	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority –Use lower lab mercury.	detection limits for selenium and dissolved

COX GULCH From headwaters to Three R	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Canyon 15050301 – 560	A&Ww – Impaired FBC – Impaired FC – Inconclusive AgL Impaired	Category 4A Not attaining	Cadmium, copper, zinc, and pH	Samples were collected on this reach in support of the Three R Creek TMDL TMDL completed in 2003

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 01/11/2000			
DATABASE #	_	NUMBER AND TYPES OF SA	MPLES		
		Metals	Nutrients - Related	Other	
Below tributary to European Mine SCCXG000.81 100869	ADEQ TMDL	1 total and dissolved metal sample: Beryllium, cadmium, copper, and zinc	pH – 1 sample		

EXCEEDANCES			
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Beryllium (total)	5.3 µg/L A&Ww chronic	01/10/2000 – 9.4 μg/L	Inconclusive – Exceeded in only sample collected.
Copper (total)	500 μg/L – AgL 1300 μg/L FBC	01/10/2000 – 18,000 μg/L	Remains impaired – Exceeded in only sample collected during this assessment period. (Binomial)
Copper (dissolved)	49.6 µg/L at >400 mg/L hardness A&Ww acute	01/10/2000 – 18,000 μg/L	Remains impaired – Exceeded in only sample collected during this assessment period.
Cadmium (dissolved)	19.1µg/L at >400 mg/L hardness A&Ww acute	01/10/2000 – 60 μg/L	Remains impaired – Exceeded in only sample collected during this assessment period.
Zinc (dissolved)	379 μg/L at >400 mg/L hardness A&Ww acute	01/10/2000 – 11000 μg/L	Remains impaired – Exceeded in only sample collected during this assessment period.
рН	<6.5 SU A&Ww, FBC, AgL	01/10/2000 – 3 SU	Remains impaired – Exceeded in only sample collected during this assessment period. (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient monitoring events	
MONITORING RECOMMENDATIONS		Medium Priority – Collect additional beryllium samples due to exceedance. Schedule follow up monitoring to determine effectiver of improvements at mine sites in this watershed once improvement are completed.	
		Collect missing core parameters an assessment period.	to represent at least 3 seasons during

UNNAMED TRIBUTARY TO COX GULCH	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
From headwaters to Cox Guich	A&We – Impaired PBC – Impaired	Category 4A Not attaining	Cadmium, copper, zinc, and pH	Samples were collected on this reach in support of the Three R Creek TMDL. TMDL completed in 2003

SITE NAMES	AGENCY	SAMPLING PERIOD				
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES				
DATABASE #		Metals	Nutrients – Related	Other		
No current data. Site file 100875	5					

DATA GAPS AND MO	NITORING NEEDS			
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Insufficient core parameters	Insufficient sampling events		
MONITORING RECOMMENDATIONS		Medium Priority – Need to implement corrective actions at mine sites along this tributary and its tributaries and then do effectiveness monitoring.		

HARSHAW CREEK From headwaters to Sonoita	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Creek	A&We – Impaired PBC – Impaired AgL – Impaired	Category 4A Not attaining	Copper and pH	TMDL completed in 2003 for copper, zinc and pH. Zinc delisted as a result.

SITE NAMES	AGENCY	SAMPLING PERIOD		
ID#	PURPOSE	NUMBER AND TY		
DATABASE #		Metals	Nutrients - Related	Other
No current data. Site files: 100318.				
100319, and 100848				

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	
MONITORING RECOMMENDATIONS		Medium Priority – Need to implement corrective actions at mine sites along Harshaw Creek and its tributaries and then do effectiveness monitoring.	

UNNAMED TRIBUTARY TO HARSHAW CREEK	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
(Endless Chain Mine tributary) 15050301 – 888 2 miles	A&We – Impaired PBC – Impaired	Category 4A Not attaining	Copper and pH	Samples were collected on this reach in support of the Harshaw Creek TMDL. TMDL completed in 2003 for copper, pH and zinc. Zinc was delisted as a result.

SITE NAMES	AGENCY	SAMPLING PERIOD NUMBER AND TYPES OF SAMPLES			
ID#	PURPOSE				
DATABASE #		Metals	Nutrients – Related	Other	
No current data Site files: 100850, 100851					

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Missing all core parameters	Insufficient sampling events	
MONITORING RECOMMEND	DATIONS		plement corrective actions at mine sites and then do effectiveness monitoring.

HUMBOLT CANYON From headwaters to Alum Gulch	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
	A&We – Impaired PBC – Inconclusive	Category 4A Not attaining	Copper	Copper loading was assigned to this reach during the Alum Gulch TMDL.

SITE NAMES	AGENCY	SAMPLING PERIOD		
ID#	PURPOSE	NUMBER AND TY	PES OF SAMPLES	
DATABASE #		Metals	Nutrients – Related	Other
No current data				
Site files:100840, 100841, and 100871				

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	
MONITORING RECOMMEND	DATIONS		plement corrective actions at mine sites its tributaries and then do effectiveness

KENNEDY LAKE	USE SUPPORT	OVERALL ASSESSMENT	The state of the s
15050301 - 0720 10 Acres	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING DATES: 07/18/20	02; 09/19/2002	
DATABASE #		NUMBER AND TYPES OF SA	MPLES	
		Metals	Nutrients – Related	Other
Mid Lake SCKEN-B 101052	AGFD Ambient	dissolved metals only: Cadmium, chromium, copper, lead, nickel, selenium and zinc. or mercury	2 samples: Ammonia, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	2 Total dissolved solids

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMEND	PATIONS	seasons during the assessment	rameters to represent at least three period. or selenium and dissolved mercury.

LAKESIDE LAKE 15050302 0760		USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
15 Acres	ADEQ	A&Ww – Impaired PBC – Impaired FC – Inconclusive	Category 4A Not attaining (Impaired)	Ammonia, dissolved oxygen, and pH	TMDL completed in 2005 for nutrient related pollutants.
	EPA	A&Ww – Impaired PBC – Impaired FC – Inconclusive	Category 4A Not attaining	Chlorophyll, nitrogen, and phosphorus	TMDL completed in 2005 for nutrient related pollutants.

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B & Appendix C).

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATES: 01/09/200	02 – 10/29/2003	
DATABASE #		NUMBER AND TYPES OF SAM	MPLES	
		Metals	Nutrients – Related	Other
At dam SCLAK-A 100034	ADEQ, U of A Ambient	1 dissolved and total metals: Cadmium, chromium, copper, lead, manganese, and zinc.	46-55 samples: Ammonia, total nitrogen, total phosphorus, nitrite/nitrate,	2 Fluoride 46 Total dissolved solids 46 Turbidity
Mid lake SCLAK-B 100035	ADEQ, U of A Ambient	1 total metals only: Antimony, arsenic, barium, boron, lead, mercury, nickel, selenium, silver	total Kjeldahl nitrogen, dissolved oxygen, pH	46 Algal samples 46 Chlorophyll samples
At boat ramp SCLAK-R 102294	U of A Ambient			

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Ammonia	0.21 mg/L at pH 8.9 and 31.9 C A&Ww chronic	08/18/2003 - 0.43 mg/L	Remains impaired – 1 exceedance in the last 3 years of monitoring
Dissolved oxygen	6.0 mg/L A&W/w	07/18/2002 - 3.8 mg/L 08/12/2002 - 4.6 mg/L* 09/10/2002 - 5.3 mg/L* 05/01/2003 - 4.6 mg/L 06/11/2003 - 3.9 mg/L 06/18/2003 - 3.1 mg/L 06/26/2003 - 5.0 mg/L 08/11/2003 - 4.9 mg/L* 09/08/2003 - 3.9 mg/L	Remains impaired – Samples in 9 of 23 sampling events had low dissolved oxygen concentration. (Binomial) Conditions were generally the same at both site A and B. * Indicates that on these dates the dissolved oxygen was too low at 1 meter, but meeting standards at 0.5 meters or surface. Proposing changing designated use to "effluent dependent water, which has lower dissolved oxygen requirements.
рН	<9.0 SU A&Ww, PBC	08/12/2002 - 9.3 SU 08/27/2002 - 9.3 SU 09/25/2002 - 9.5 SU 10/09/2002 - 9.4 SU 10/24/2002 - 9.3 SU 08/11/2003 - 9.4 SU	Remains impaired – 6 of 23 sampling events had high pH values. (Binomial)

Pollutant: Assume "total" concentration, unless shown as dissolved.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limit for selenium and dissolved mercury were higher than A&W chronic criteria.
DISCUSSION OF IMPAIRMENT		moved to Category 4A (from 5) Evidence of potential impairment 1. Nutrient TMDL comples should address these possible improve water quality 3. ADEQ has proposed in that indicates the follow Chlorophylla < 50. Total nitrogen <1.9 Total phosphorus <at chlorophylla="" complex="" lake:="" lakeside="" of="" phosphorus="" routing="" td="" th<="" the="" was=""><td>being taken by the City of Tucson to at the lake; and arrative nutrient implementation guidance wing limits for an urban lake: 9 µg/L 0 ng/L 0.160 mg/L above 50 µg/L on 12 dates. nely above 2.0 and as high as 5.9 mg/L. utinely above 0.16 ancl as high as 0.51 mg/L</td></at>	being taken by the City of Tucson to at the lake; and arrative nutrient implementation guidance wing limits for an urban lake: 9 µg/L 0 ng/L 0.160 mg/L above 50 µg/L on 12 dates. nely above 2.0 and as high as 5.9 mg/L. utinely above 0.16 ancl as high as 0.51 mg/L
MONITORING RECOMMEND	DATIONS	of water quality improvement ac Collect core parameters to repres assessment period.	p monitoring to determine the effectiveness tions taken at the lake. Sent at least three seasons during an relenium and dissolved mercury.

LOMA VERDE	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Tanque Verde Wash 15050302 – 268 4 Miles	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3 Inconclusive	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 05/14/20	002 – 10/15/2003	
DATABASE #		NUMBER AND TYPES OF SAM	APLES	
		Metals	Nutrients - Related	Other
In Saguaro National Park SCLMV003.51 101585	USGS Ambient	4 dissolved metals only: Antimony, barium, beryllium, boron, cadmium, chromium, copper, lead, manganese, nickel, silver, uranium, and zinc. 1 dissolved metals: Arsenic, selenium (0 total metals)	4 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen, total phosphorus, dissolved oxygen, and pH	4 Total dissolved solids 1 Turbidity

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	6.0 mg/L A&Ww	05/14/2002 – 2.2 mg/L	Inconclusive – Only 1 of 4 samples did not meet criterion; however, nutrients were extremely high (15.2 mg/L nitrogen, 1.8 mg/L phosphorus).

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Dissolved oxygen	Insufficient total metals and E. coli bacteria		
MONITORING RECOMMEND	DATIONS	exceedance.	dditional dissolved oxygen samples due to
		the assessment period.	ers to represent at least 3 seasons during

MADERA CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT
I I TOTTI HEAD WATERS TO DITIONING	A&Wc - Attaining FBC - Attaining	Category 2
15050301 - 322A	FC - Inconclusive Agl Inconclusive	Attaining some uses

AGENCY	SAMPLING PERIOD: 04/25/2001; 09/21/2005-01/09/2006				
PURPOSE	Included 01/09/2006 data to assess additional designated uses				
	NUMBER AND TYPES OF SAM	APLES			
	Metals	Nutrients - Related	Other		
ADEQ	3 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, copper, and zinc. 1-2 total and dissolved metals: barium, mercury, silver, thallium 3 total only: Boron, manganese	3 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	3 E. coli bacteria 3 Fluoride 3 Total dissolved solid: 2 Suspended sediment concentration 4 Turbidity		
	AGENCY PURPOSE	PURPOSE Included 01/09/2006 data to a NUMBER AND TYPES OF SAN Metals ADEQ 3 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, copper, and zinc. 1-2 total and dissolved metals: barium, mercury, silver, thallium	AGENCY PURPOSE SAMPLING PERIOD: 04/25/2001; 09/21/2005-01/09/200 Included 01/09/2006 data to assess additional designated NUMBER AND TYPES OF SAMPLES Metals Alissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, copper, and zinc. 1-2 total and dissolved metals: barium, mercury, silver, thallium		

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient total lead and mercury to assess FC and AgL.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria in at least 1 sample
MONITORING RECOMMEND	DATIONS	Low Priority – Collect mis seasons during an assessm	sing core parameters to represent at least 3 ent period.
		Use lower lab detection li	mit for selenium and dissolved mercury

MADRONA CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Rincon Creek 15050302 138 7 Miles	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 11/08/20			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
Near Madrona Ranger Station SCMDN001.51 101628	USGS Ambient	3-4 dissolved and 0-1 total metals: Antimony, barium, beryllium, boron, cadmium, chromium, copper, lead, manganese, and zinc. 0-1 total and 0-1 dissolved metals: Arsenic, mercury, selenium, nickel, silver, uranium	1 samples: Ammonia, total nitrogen, nitrite/nitrate, total Kjeldahl nitrogen 2 samples: Dissolved oxygen 4 samples: Total phosphorus 7 samples: pH	1 Fluoride 3 Total dissolved solids 2 Suspended sediment concentration	

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient total metals, <i>E. coli</i> bacteria, and dissolved oxygen to assess designated uses.		
MONITORING RECOMMEND	DATIONS	Low Priority – Collect missin seasons during the assessmen	g core parameters to represent at least 3 t period.

NOGALES WASH From Mexico border to	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Potrero Creek 15050301 – 011 6.2 Miles	A&WW – Impaired PBC – Impaired	Category 5	E. coli bacteria, chlorine, ammonia, copper	On the 303(d) list due to <i>E. coli</i> bacteria, chlorine, ammonia, copper.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 03/07/200	0 – 11/16/2005		
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At Morley Street Tunnel SCNGW004.87 100251	ADEQ Ambient	17-25 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, mercury, and zinc. 10-11 dissolved and total metals: Barium, nickel, silver, thallium 8 total only: Boron, manganese 1 Selenium	23-24 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	19 <i>E coli</i> bacteria 23 Fluoride 23 Total dissolved solids 12 Suspended sediment concentration 24 Turbidity 3 Solvents and petroleum products	

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Ammonia	Varies based on pH and water temperature A&Ww chronic	08/09/2000 – 6.1 mg/L 04/23/2001 – 3.3 mg/L 01/15/03 – 13 mg/L 09/09/03 – 6.2 mg/L 01/14/04 – 3.6 mg/L 09/15/04 – 1.2 mg/L	Remains impaired – 4 exceedances in last 3 years of monitoring (6 in the assessment period).
Chlorine	11 µg/L A&Ww acute	03/07/2000 – 210 μg/L 05/24/2000 – 130 μg/L 08/09/2000 – 130 μg/L 04/24/2001 – 480 μg/L	Remains impaired Chlorine exceeded criterion all 4 times measured (4 times within a 3 year period). Chlorine is being added to the stream flow to reduce risks due to high bacterial contamination.
Copper (dissolved)	22.2 µg/L at 180 mg/L hardness A&Ww acute	01/15/2003- 24 μg/L	Remains impaired – One exceedance in last 3 years of monitoring.
Dissolved oxygen	6.0 mg/L A&Ww	12/19/2001 – 5.0 mg/L 09/09/2003 – 3.1 mg/L 12/01/2003 – 4.6 mg/L 01/14/2004 – 4.7 mg/L	Inconclusive – 4 of 22 samples did not meet the dissolved oxygen standards. Binomial method requires at least 5 exceedances to be listed as impaired with 22 samples.
E. coli bacteria	235 CFU/100 ml PBC	Too many exceedances to list here. Maximum was 4,810,000 CFU/100 ml	Remains impaired – 11 exceedances during the assessment period. (Noted fewer exceedances in 2004 and 2005.)
Lead	15 μg/L PBC	03/07/2000 – 190 μg/L 09/09/03 – 100 μg/L	Attaining – Only 2 exceedances in 22 samples. (Binomial)
Selenium	2 μg/L A&Ww chronic	09/09/2003 – 5.2 μg/L	Attaining – Only 1 exceedance in 23 samples. (Binomial)
Suspended sediment concentration (SSC)	Geometric mean 80 mg/L A&Ww	09/09/2003 – 972 mg/L	Attaining – Criterion was exceeded once in 1 sample, but geometric mean was not exceeded. (The old turbidity standard (50) was exceeded in 5 of 24 samples.)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Dissolved oxygen Collected all core parameters			Lab detection limits for selenium ar dissolved metals (lead, mercury, an nickel) were higher than the A&W chronic criteria in at least 3 samples	
COMMENTS CONCERNIN	G EXCEEDANCES	wastewater infrastructure in	high ammonia levels are due to insufficient Mexico. The chlorine tablets are added to a; however, the chlorine is toxic to aquatic	
MONITORING RECOMMENDATIONS		High Priority – Collect samp coli bacteria, ammonia, chlo Collect dissolved oxygen san		
		Use lower lab detection limit	t for selenium and dissolved metals.	

PARKER CANYON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
	A&Ww – Inconclusive FBC – Inconclusive FC – Inconclusive	Category 3	

SITE NAMES ID#	AGENCY PURPOSE ADEQ Ambient	SAMPLING PERIOD: 09/27/2005 – 12/07/2005				
Below Parker Canyon Lake Dam SCPRK010.26 103524		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
		I total and dissolved metal samples: Antimony, arsenic, beryllium, boron, cadmium, chromium, copper, lead, manganese, mercury, and zinc	2 samples: Dissolved oxygen and pH 1 sample: Ammonia, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	2 E. coli bacteria 1 Fluoride 2 Total dissolved solids 2 Turbidity 2 Suspended sediment		

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	6.0 mg/L A&W/w	09/27/05 - 2.6 mg/L 12/07/2005 - 5.8 mg/L	Attaining – Low dissolved oxygen due to low flow conditions and groundwater upwelling. Flow around 0.2 cfs. Low nutrient levels.

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limit for selenium was higher than the A&W chronic criteria
MONITORING RECOMMENDATIONS		Low Priority – Collect missing core parameters to represent at least 3 seasons during the assessment period. Use lower lab detection limit for selenium.	

PARKER CANYON LAKE	USE SUPPORT		SSMENT CAU	ITANTS IMPAIRMENT ISING STATUS RMENT
15050301 1040 130 Acres	A A&Wc-I D FBC-Att FC-Inco Q AgI-Att AgL-Att	nclusive Attaini	ory 2 ng Some	
	E P A FC-Imp	aired Catego Impair	tissue	in fish EPA listed mercury In 2004 due to fish consumption advisory

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B & Appendix C).

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 11/29/2000 – 11/22/2005 NUMBER AND TYPES OF SAMPLES			
At Dam SCPAK-A 100057	ADEQ Ambient	6-7 total and 4 dissolved: Cadmium, chromium, lead, nickel, zinc	6-7 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus,	3 <i>E. coli</i> bacteria 7 Fluoride 3 Total dissolved solids	
At boat ramp SCPAK-D	ADEQ Ambient	7 and 1 dissolved metals: Antimony, arsenic, barium, beryllium, boron, copper, manganese, mercury	nitrite/nitrate, total Kjeldahl nitrogen	7 Turbidity	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	<7.0 mg/L A&Wc	11/29/2000 – 6.5 mg/L 10/09/2003 – 5.1 mg/L 11/22/2005 – 6.2 mg/L	Inconclusive – Did not meet dissolved oxygen criteria in 3 of 6 sampling events. (Binomial requires a minimum of 5 exceedances and 20 samples to be listed as impaired.)	

Pollutant: Assume "total" concentration, unless shown as dissolved.

DATA GAPS AND MO	NITORING NEEDS	S		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Dissolved oxygen, mercury	Insufficient dissolved copper to assess A&W.		Lab detection limits for dissolved metals (cadmium, copper, lead, mercury, and silver) and selenium were higher than the A&W chronic criteria in at least 1 sample.	
DISCUSSION OF MERCURY IMPAIRMENT		Evidence of potential mercury impairment: 1. Mercury fish consumption advisory issued in 2002 still exists; and 2. Two other lakes in this watershed are impaired by mercury (Pena Blanca and Arivaca lakes) which may indicate common source contributions.		
MONITORING RECOMMENDATIONS		High Priority – Collect mercury samples to support TMDL development. Collect dissolved oxygen samples due low levels. Elevated turbidity and low dissolved oxygen may be symptoms of excess nutrient loading. New methods for implementing the narrative nutrient standard should be applied to this lake once adopted, to determine whether narrative nutrient violations are occurring. Use lower lab detection limit for selenium and dissolved metals.		

PATAGONIA LAKE	USE SUPPORT	OVERALL ASSESSMENT	
15050301 - 1050 230 Acres	A&Wc - Inconclusive FBC - Inconclusive FC - Attaining DWS Attaining AgI Attaining AgL Attaining	Category 2 Attaining some uses	

SITE NAMES AGENCY ID # PURPOSE DATABASE #		SAMPLING PERIOD: 11/28/2000 – 08/30/2001			
		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At Dam SCPAT-A 100060	ADEQ Ambient	4 total and 0-1 dissolved: Antimony, arsenic, barium, beryllium, boron, cadmium, chromium, copper, lead, manganese, mercury, nickel, selenium, silver, and zinc	3-4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	1 <i>E. coli</i> bacteria 3 Fluoride 1 Total dissolved solid: 2 Turbidity	

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	<7.0 mg/L A&Wc	08/30/2001 – 6.2 mg/L	Inconclusive – Did not meet dissolved oxygen criterion in of 4 sampling events. (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Dissolved oxygen	Insufficient metals (dissolved cadmium, copper, and zinc) and <i>E. coli</i> bacteria to assess A&W and FBC.		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMEN	DATIONS	exceedance. Low dissolved of nutrient loading. New methor standard should be applied to whether narrative nutrient v	ore total dissolved oxygen samples due to oxygen may be a symptom of excess ods for implementing the narrative nutrient to this lake once adopted, to determine iolations are occurring.

PENA BLANCA LAKE 15050301 – 1070	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
50 Acres	A&Wc – Inconclusive FBC – Inconclusive FC – Impaired AgI – Inconclusive	Category 4A Not attaining	Mercury in fish tissue	TMDL for mercury was completed in 1999.

SITE NAMES ID # DATABASE #	AGENCY PURPOSE	SAMPLING PERIODS: 11/28/2000 – 08/28/2001; 09/18/2003; 01/08/2004 – 09/28/2005				
		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients – Related	Other		
At Dam SCPEN-A 100064	ADEQ and U of A Ambient	7-11 total and 3-5 dissolved: Cadmium, chromium, lead, nickel, silver, thallium, zinc	12 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus,	2 E. coli bacteria 10 Fluoride 4 Total dissolved solid:		
At boat ramp SCPEN-FR 102761	AGFD Ambient	7-11 total and 0-1 dissolved metals: Antimony, arsenic,	nitrite/nitrate, total Kjeldahl nitrogen	10 Turbidity		
Mid Lake SCPEN-B 100065	ADEQ and U of A Ambient	barium, beryllium, boron, copper, manganese, mercury, selenium				

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Dissolved oxygen	<7.0 mg/L A&Wc	09/12/03-09/18/03 – 2.5 mg/L	Inconclusive – Did not meet dissolved oxygen criterion in 1 of 8 sampling events (multiple sites). (Binomial)	
рН	<9.0 SU A&Wc, FBC, Agl, AgL	09/28/2005 – 12.5 SU	Inconclusive – Did not meet pH criteria in 1of 6 sampling events (multiple sites). (Binomial)	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Dissolved oxygen, pH	Insufficient dissolved copper		Lab detection limits for dissolved metals (cadmium, copper, lead, mercury, and silver) and selenium were higher than the A&W chronic criteria in at least 1 sample.
MONITORING RECOMMENE	DATIONS	TMDL load reduction strategy Collect more total dissolved exceedances. The old turbidit exceeded on 2 dates. Low disturbidity may be symptoms of for implementing the narratithis lake once adopted, to deviolations are occurring.	mples to determine the effectiveness of ies for mercury. oxygen and pH samples due to ty standard (10 NTU) was slightly ssolved oxygen, high pH, and elevated of excess nutrient loadings. New methods we nutrient standard should be applied to etermine whether narrative nutrient the for selenium and dissolved metals.

POTRERO CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From Interstate 19 to Santa Cruz River 15050301 – 500B 4.9 Miles	A&Ww - Inconclusive FBC - Inconclusive FC - Inconclusive AgL - Inconclusive	Category 3	

SITE NAMES AGENCY ID # PURPOSE DATABASE #		SAMPLING PERIOD: 01/25/2000 – 01/11/2006 Included 01/11/2005 data to be able to assess more designated uses.		
		NUMBER AND TYPES OF SAM	APLES	
		Metals	Nutrients - Related	Other
At Ruby Road SCPOT001.62 100571	ADEQ and Friends of the Santa Cruz River	3 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, and zinc. 3 total only: Boron, manganese 2 total and 3 dissolved: Mercury 1 total and 3 dissolved: Lead, copper	17-23 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	3 E. coli bacteria 2 Fluoride 3 Total dissolved solid: 2 Suspended sediment concentration 19 Turbidity

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
E. coli bacteria	235 CFU/100 ml FBC	11/16/2005 – 648 CFU/100 ml	Inconclusive – Only 1 exceedance within the assessment period (3 samples).

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
E. coli bacteria	Insufficient dissolved and total copper, total lead, and total mercury to assess A&W, FC and AgL		Lab detection limits for selenium were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Medium Priority – Collect ac exceedance.	dditional <i>E. coli</i> bacteria due to the
		Collect missing core paramet an assessment period.	ers to represent at least 3 seasons during
		Use lower lab detection limit	t for selenium.

REDROCK CANYON	USE SUPPORT	OVERALL ASSESSMENT	
I I TOTT TICAGOVALETS TO TIGISTICAT	A&Ww - Attaining FBC - Attaining FC - Attaining	Category 1 Attaining all uses	

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 12/13/2000 – 09/19/2001 NUMBER AND TYPES OF SAMPLES			
DATABASE #					
		Metals	Nutrients - Related	Other	
Near Patagonia, AZ SCRED005.58 101080	ADEQ Ambient	4-5 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, silver, thallium, and zinc. 4 total only: Boron, manganese 4 total metals only: Mercury	4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	4 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids 4 Turbidity	

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Dissolved oxygen	<6.0 mg/L A&Ww	09/19/2001 – 5.2 mg/L	Attaining Low dissolved oxygen is naturally occurring due to low flows and ground water upwelling. Very low nutrients.		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority – Use lower lab mercury.	detection limit for selenium and dissolved

RINCON CREEK	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Pantano Wash 15050302 – 008 16.2 Miles	A&We - Inconclusive PBC - Inconclusive AgL - Inconclusive	Category 3 Inconclusive	

SITE NAMES ID # DATABASE #	AGENCY PURPOSE	SAMPLING PERIOD: 04/25/2001; 09/21/2005-01/09/2006 Included 01/09/2006 data to assess additional designated uses				
		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
Near Tucson, AZ SCRIN008.97 102170	AGFD Ambient	1 dissolved metal: Antimony, barium, beryllium, boron, cadmium, chromium, copper, lead, manganese, nickel, silver, and uranium. (0 total metals)	1 sample: Dissolved oxygen, pH	1 Suspended sediment		

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
No Exceedances					

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	
MONITORING RECOMMENDATIONS		Low Priority – Collect missing seasons during an assessment p	core parameters to represent at least 3 period.

ROSE CANYON LAKE	USE SUPPORT		OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
15050302 - 1260 7 Acres	A D E Q	A&Wc - Inconclusive FBC - Inconclusive FC - Attaining	Category 2 Attaining some uses		
	E P A	A&Wc – Impaired FBC – Impaired	Category 5 Impaired	рH	EPA added pH to 303(d) List in 2004 (Older data included in original listing)

Light blue highlights indicate EPA impairments based on EPA assessment and listing criteria. This listing may change when EPA reviews and approves the 2006/2008 impaired waters list. Such listings do not satisfy requirements established in ADEQ's Impaired Water Identification Rule; therefore, they are not included in the list of ADEQ's Impaired waters (Appendix B and Appendix C).

MONITORING	USED IN TH	IS ASSESSMENT			
SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 10/04/2000 – 08/14/2001			
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At Dam SCROS-A 100183	ADEQ Ambient	4 total metal samples: Antimony, arsenic, barium, beryllium, boron, cadmium,	4 samples: Ammonia, total nitrogen, nitrate/nitrate, total phosphorus, total	1 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids	
At top of lake inlet SCROS-IN 101266	ADEQ Ambient	chromium, copper, lead, manganese, mercury, nickel, selenium, silver, and zinc.	Kjeldahl nitrogen. 3 samples: Dissolved oxygen 5 samples: pH	4 Turbidity	

POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
рН	<6.5 SU A&Wc, FBC	06/27/2001 – 6.1-6.3 SU 08/14/2001 – 6.0-6.3 SU	Inconclusive – 2 low pH values in 3 sampling events (4 samples).

Pollutant: Assume "total" concentration, unless shown as dissolved.

DATA GAPS AND MO	NITORING NEEDS			
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
	Insufficient dissolved metals and <i>E. coli</i> bacteria to assess A&W and FBC			
PH IMPAIRMENT DISCUSSION		Evidence of potential pH impairment: 1. All low pH values occurred below 4 meters deep in this seven acre lake, which may be associated with natural conditions; 2. No newer data since the original listing; and 3. A major wildfire occurred in this area in 2003 that may hav further impacted water quality.		
MONITORING RECOMMENDATIONS		Low pH and turbidity ma New methods for implem be applied to this lake on	ditional pH to support TMDL ay be symptoms of excess nutrient loading, nenting the narrative nutrient standard should not adopted, to determine whether narrative courring. Collect missing core parameters.	

SABINO CANYON	USE SUPPORT	OVERALL ASSESSMENT	
From unnamed tributary at 322328 / 1104700 to Tanque Verde Wash 15050302 - 014B 14.1 Miles	A&Ww – Inconclusive FBC – Inconclusive FC – Attaining DWS – Inconclusive AgI – Attaining	Category 2 Attaining some uses	

MONITORING	G USED IN THIS	ASSESSMENT			
SITE NAMES	AGENCY	SAMPLING PERIOD: 12/14/2000 - 09/13/2005			
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES			
DATABASE #		Metals	Nutrients - Related	Other	
Above East Fork Sabino Canyon SCSAB009.77 100635	ADEQ Ambient	6-9 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, silver,	8-9 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total	4 <i>E. coli</i> bacteria 8 Fluoride 7 Total dissolved solids 1 Suspended sediment	
Above bridge 9 SCSAB007.15 102835	AGFD Ambient	thallium, and zinc. 7 total and 0-1 dissolved: Boron,	Kjeldahl nitrogen	concentration 8 Turbidity 1 Cyanide	
Near Tucson SCSAB005.40 101152	ADEQ Ambient	manganese, mercury 1 Selenium			
Above bridge 1 SCSAB005.21 102834	ADEQ and AGFD Ambient				
At USGS gage SCSAB004.49 100260	USGS Ambient				

EXCEEDANCE	EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS			
Cyanide	41 μg/L A&Ww acute	07/23/2003 – 120 μg/L	Inconclusive Exceeded in the only sample that was tested for cyanide. See "Aspen Fire" discussion below.			
Dissolved oxygen	<6.0 mg/L A&Ww	09/20/2001 – 5.7 mg/L	Attaining – Low dissolved oxygen due to natural conditions. Very low flow (0.01 cfs) and ground water upwelling.			
Lead	15 µg/L FBC and DWS	07/23/2003 – 202 μg/L 02/19/2004 – 1250 μg/L	Inconclusive – 2 exceedances in 8 samples. (Binomial method requires a minimum of 5 exceedances and 20 samples.) See "Aspen Fire" discussion below.			
Manganese	980 μg/L DWS	07/23/2003 – 7820 μg/L	Attaining – Exceeded criteria in 1 of 7 samples (Binomial) Exceedance occurred immediately after "Aspen Fire" – see below.			
Selenium	2.0 µg/L A&Ww chronic	07/23/2003 – 4.0 μg/L	Inconclusive – Exceeded in 1 sample during the last 3 years of monitoring. The lab detection limit on 6 other samples was above the criteria so could not be used to determine attainment. See "Aspen Fire" discussion below.			

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH	
Cyanide Collected all core parameters			Lab detection limits for dissolved mercury and selenium were above the A&Ww chronic criteria.	
ASPEN FIRE of 2003		A major wildfire burned 84,750 acres in the Coronado National Forest, including a major portion of Sabino Canyon's watershed. The fire started on 06/17/2003. Samples collected on 07/23/2003 reflect the impact of this fire on water quality with exceedances of cyanide, lead, manganese, and selenium criteria. The old turbidity criterion (50 NTU) was also exceeded on 07/23/2003 at 2800 NTU. Subsequent monitoring on 02/19/2004 and 09/13/2005 contained only a lead		
MONITORING RECOMMENDATIONS		exceedance. Medium Priority – Collect additional cyanide, lead, manganese, and selenium samples due to exceedances to determine any long term impacts of the fire. Use lower lab detection limits for dissolved mercury and selenium. Longer term impacts of erosion and sedimentation should be studied. Collect suspended sediment concentration (SSC) samples. Recommend using biocriteria assessments and bottom deposits implementation		

SANTA CRUZ RIVER	USE SUPPORT	OVERALL ASSESSMENT
From headwaters to Mexico border 15050301 – 268 13.9 Miles	A&Ww – Attaining FBC – Attaining FC – Attaining DWS – Attaining AgI – Attaining AgL – Attaining	Category 1 Attaining all uses

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 12/13/2000 – 09/19/2001				
DATABASE #		NUMBER AND TYPES OF SAMPLES				
		Metals	Nutrients - Related	Other		
Near Lochiel SCSCR169.35 100242	ADEQ Ambient	4 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, silver, thallium, and zinc. 4 total metals only: Boron, manganese, mercury	4 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	3 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids 4 Turbidity		

EXCEEDANG	CES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
No Exceedances			

DATA GAPS AND MO	NITORING NEEDS	5	
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority – Use lower lab mercury.	detection limit for selenium and dissolved

SANTA CRUZ RIVER From Mexico border to Nogales	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Intl WWTP discharge 15050301 – 010 17.0 Miles	A&Ww – Attaining FBC – Impaired FC – Inconclusive AgI – Attaining AgL – Attaining	Category 5	E. coli bacteria	Listed due to E. coli bacteria since 2002. TMDL has been delayed because drought has resulted in no stream flow.

SITE NAMES ID#	AGENCY PURPOSE	SAMPLING PERIOD: 01/25/20	000 – 12/09/2001		
DATABASE #		NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients - Related	Other	
At International boundary with Mexico SCSCR128.27 100239	ADEQ Ambient	7-8 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, silver,	15-17 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total	8 <i>E. coli</i> bacteria 8 Fluoride 8 Total dissolved solid: 18 Turbidity	
At Guavai Ranch SCSCR119.01	ADEQ and Friends of the	thallium, and zinc.	Kjeldahl nitrogen		
100246	Santa Cruz River Ambient	8 total metals only: Boron, manganese, mercury			

EXCEEDANC	ES		
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Dissolved oxygen	<6.0 mg/L A&W/w	02/29/2000 – 5.5 mg/L 05/24/2000 – 5.4 mg/L 08/09/2000 – 4.3 mg/L	Attaining Low dissolved oxygen levels are naturally occurring due to ground water upwelling and low flows was less than 0.5 cfs.
E. coli bacteria	235 CFU/100 ml FBC	08/09/2000 - 10,000 CFU/100 ml	Remains impaired – One exceedance last 3 years monitored.
Mercury	0.6 μg/L FC	09/18/2000 – 0.8 μg/L	Inconclusive 1 exceedance in 8 samples. (Binomial)

DATA GAPS AND MO	NITORING NEED	5	
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Mercury	Collected all core parameters		Lab detection limits for selenium and dissolved metals (lead, mercury, and nickel) were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		development. Collect mercury samples due limit for selenium and dissolv The old turbidity standard (5 11 (53 and 100 NTU). Collect suspended sediment is occur.	to exceedance. Use lower lab detection ved metals. O NTU) was exceeded in 2 samples out of t SSC samples to determine if excessive ring. Recommend using biocriteria osits implementation procedures in this

SANTA CRUZ RIVER	USE SUPPORT	OVERALL ASSESSMENT	
discharge to Josephine Canyon	A&Wedw - Inconclusive PBC - Attaining AgL Inconclusive	Category 2 Attaining some uses	

SITE NAMES AGENCY 1D # PURPOSE		SAMPLING PERIOD: 01/25/2000 – 11/15/2005 (Full suite only on 09/21/2005)		
DATABASE #	NUMBER AND TYPES OF SAMPLES			
		Metals	Nutrients – Related	Other
At Rio Rico SCSCR111.66 100238	ADEQ and Friends of the Santa Cruz River Ambient	1 dissolved and total metals: Antimony, arsenic, cadmium, and zinc. 1 total only: Beryllium, boron, manganese 1 dissolved only: Chromium, copper, lead 4 total metals only: Mercury	17-32 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	3 E. coli bacteria 1 Fluoride 1 Total dissolved solid: 1 Suspended sediment concentration 34 Turbidity

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
No Exceedances				

EXCEEDANCES NEEDING	MISSING CORE	MISSING SEASONAL	DETECTION LIMITS NOT LOW
MORE SAMPLES TO ASSESS	PARAMETERS	DISTRIBUTION	ENOUGH
	Insufficient dissolved and total metals.	Insufficient sampling events.	Lab detection limits for selenium were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Low Priority – Collect missing core parameters to represent at least 3 seasons during an assessment period. Use a lower lab detection limit for selenium.	

SANTA CRUZ RIVER	USE SUPPORT	OVERALL ASSESSMENT	
From Josephine Canyon to Tubac Bridge 15050301 – 008A 4.8 Miles	A&Wedw - Inconclusive PBC - Attaining AgL Attaining	Category 2 Attaining some uses	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 01/25/2000 – 10/01/2001; 09/29/2004			
DATABASE #		NUMBER AND TYPES OF SAM	MPLES		
		Metals	Nutrients - Related	Other	
At Santa Gertrudis Lane SCSCR103.45 100247	ADEQ and Friends of the Santa Cruz River Ambient	4 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, silver,	20-24 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl	3 <i>E. coli</i> bacteria 4 Fluoride 4 Total dissolved solids 35 Turbidity	
At Tubac, AZ SCSCR103.39 USGS #09481740 101002	ADEQ Special Inv	thallium, and zinc. 4 total metals only: Boron, manganese, mercury	nitrogen	2 Chlorine (free residual)	

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
Chlorine	11 μg/L – A&Wedw acute	02/27/2001 – 90 μg/L	Inconclusive – One of 2 chlorine residual samples exceeded water quality criterion.	

DETECTION LIMITS NOT LOW ENOUGH Lab detection limits for selenium and dissolved mercury were higher than	
dissolved mercury were higher than	
the A&W chronic criteria.	
Medium Priority – Collect more total chlorine residual samples due to exceedance. Use lower lab detection limit for selenium and dissolved mercury.	
1	

SANTA CRUZ RIVER	USE SUPPORT	OVERALL ASSESSMENT	
From Tubac Bridge to Sopori Wash 15050301 – 008B 8.9 Miles	A&We - Inconclusive PBC - Inconclusive AgL Inconclusive	Category 3 Inconclusive	

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING PERIOD: 01/25/2000 – 09/29/04; 09/21/2005		
DATABASE #		NUMBER AND TYPES OF SAM		
		Metals	Nutrients - Related	Other
At Tubac Bridge SCSCR099.40 100243	ADEQ and Friends of the Santa Cruz Ambient	1 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, mercury, and zinc.	18-46 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl	1 E. coli bacteria 1 Fluoride 1 Total dissolved solid: 1 Suspended sediment
North of Chaves Siding Road SCSCR096.72 100244	ADEQ and Friends of the Santa Cruz Ambient	1 total only: Boron, manganese, selenium	nitrogen	concentration 44 Turbidity

EXCEEDANCES				
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS	
E. coli bacteria	235 CFU/100 ml FBC	09/21/2005 – 650 CFU/100 ml	Inconclusive – Criterion exceeded in the only sample tested. Sample had very high nutrient levels, and site is just downstream of where the Effluent Dependent Water classification ends.	
рН	<6.5 SU A&We, PBC, AgL	02/29/2000 – 2.6 SU	Attaining – Only 1 exceedance in 46 samples. (Binomial)	

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
E. coli bacteria	Insufficient core parameters	Insufficient sampling events.	
MONITORING RECOMMENDATIONS		Medium Priority – Collect more <i>E. coli</i> bacteria samples due to exceedance.	
		Collect missing core parameter an assessment period.	s to represent at least 3 seasons during

SANTA CRUZ RIVER	USE SUPPORT	OVERALL ASSESSMENT	
I TOTTI CUITAGA GET OTO TO TIO	A&Wedw - Inconclusive PBC - Attaining	Category 2 Attaining some uses	

SITE NAMES	AGENCY	SAMPLING PERIODS: 01/03/2001 – 10/02/2001; 09/12/2005 – 11/15/2005 NUMBER AND TYPES OF SAMPLES			
ID#	PURPOSE				
DATABASE #		Metals	Nutrients - Related	Other	
Near Marana SCSCR034.56 101081	ADEQ Ambient	4-5 dissolved and total metals: Antimony, arsenic, beryllium, cadmium, chromium, copper, lead, nickel, silver, thallium, and zinc. 5 total only: Boron, manganese 5 total metals only: Mercury	5 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	4 E. coli bacteria 5 Fluoride 5 Total dissolved solids 1 Suspended sediment concentration 4 Turbidity 3 Chlorine (free residual)	

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Chlorine	11 μg/L A&Wedw acute	02/26/2001 -480 μg/L 10/02/2001 -70 μg/L	Inconclusive – 2 exceedances in a 3-year period; however, wastewater treatment facility had a permit variance at the time.		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
Chlorine	Collected all core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
MONITORING RECOMMENDATIONS		Medium Priority – Collect more total chlorine residual samples due t the exceedance. Use lower lab detection limit for selenium and dissolved mercury.	

SONOITA CREEK	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
From 750 feet below Patagonia WWTP discharge to Patagonia Lake 15050301 – 013C 9.03 Miles	A&WW - Impaired FBC - Attaining FC - Attaining Agl Attaining AgL Attaining	Category 5	Zinc and low dissolved oxygen	Added zinc to 303(d) list in 2004. Moved low DO from 4B back to 5

SITE NAMES	AGENCY	SAMPLING PERIOD 12/12/2000 – 09/19/2001; 09/28/2005 – 12/08/20				
ID#	PURPOSE	NUMBER AND TYPES OF SAMPLES				
DATABASE #		Metals	Nutrients - Related	Other		
At Circle Z Ranch SCSON014.52 101154	ADEQ Ambient	4-5 dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, silver, thallium, and zinc. 4 total and 0-1 dissolved: Boron, manganese, mercury	5 samples: Ammonia, dissolved oxygen, pH, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen	6 E. coli bacteria 5 Fluoride 6 Total dissolved solids 1 Suspended sediment concentration 6 Turbidity		

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
Zinc	379 μg/L at >400 hardness A&W/w acute	12/12/2000 – 800 µg/L 04/13/2001 – 860 µg/L 09/28/2005 – 760 µg/L	Remains impaired Two exceedances in a 3 year period (2000-2001) Site is downstream of a WWTP discharge and downstream of several historic mining sites.		

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Collected all core parameters		Lab detection limits for selenium and dissolved mercury were higher than the A&W chronic criteria.
LOW DISSOLVED OXYGEN IN	MPAIRMENT	receiving Patagonia's WWTI goes subsurface. ADEQ is ler	urring in the reach just below the reach Peffluent discharge. The discharge rapidly agthening the reach designated as A&Wedw v dissolved oxygen was measured.
MONITORING RECOMMENDATIONS		High Priority – Collect zinc samples to support TMDL development. Collect dissolved oxygen samples in the reach below the proposed EDW.	
		Use lower lab detection limi	t for selenium and dissolved mercury.

SYCAMORE CANYON	USE SUPPORT	OVERALL ASSESSMENT	
From headwaters to Mexico border 15080200 002 9.9 miles	A&WW – Inconclusive FBC – Inconclusive FC – Inconclusive AgL Inconclusive	Category 3	

SITE NAMES ID #	AGENCY PURPOSE	NUMBER AND TYPES OF SAMPLES		
DATABASE #				
		Metals	Nutrients - Related	Other
Above Penasco Canyon SCSYR004.21 100660	ADEQ Ambient	I dissolved and total metals: Antimony, arsenic, barium, beryllium, cadmium, chromium, copper, lead, nickel, silver, thallium, and zinc. I total metals only: Boron, manganese, mercury,	I sample: Ammonia, total nitrogen, total phosphorus, nitrite/nitrate, total Kjeldahl nitrogen, dissolved oxygen, pH	1 Fluoride 1 Total dissolved solid: 1 Turbidity

EXCEEDANCES					
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS		
No Exceedances					

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient sampling events	Lab detection limits for selenium and dissolved mercury are higher than the A&Ww criteria.
MONITORING RECOMMENDATIONS		Low Priority -Collect core parameters to represent at least three seasons during an assessment period. Use lower lab detection limits for selenium and dissolved mercury.	

THREE R CANYON From headwaters to 312835 / 110	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
4619 (latitude/longitude where intermittent flow begins) 15050301 – 558A 2.3 Miles	A&We – Impaired PBC – Impaired AgL – Impaired	Category 4A Not attaining	Cadmium, copper, zinc, and pH	TMDL completed in 2003. Need to implement improvements at mining sites.

DATABASE # NUMBER AND TYPES OF SAMPLES			
	NUMBER AND TYPES OF SAMPLES		
Metals Nutrients – Related	Other		
No current data			

DATA GAPS AND MOS	MISSING CORE	MISSING SEASONAL	DETECTION LIMITS NOT LOW
MORE SAMPLES TO ASSESS	PARAMETERS	DISTRIBUTION	ENOUGH
	Insufficient core parameters		
MONITORING RECOMMEND	DATIONS	Low Priority – Additional ma effectiveness of improvemen improvements are completed	onitoring should be scheduled to determin ts at mine sites in this watershed once

UNNAMED TRIBUTARY TO THREE R CANYON	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
III brom headwaters to I breek	A&We – Impaired PBC – Impaired	Category 4A Not attaining	Cadmium, copper, zinc, and pH	TMDL completed in 2003. Need to implement improvements at mining sites.

SITE NAMES	AGENCY	SAMPLING DATE:		
ID#	PURPOSE	NUMBER AND TY	PES OF SAMPLES	
DATABASE #	Metals	Nutrients – Related	Other	
No current data Data file: 100874				

DATA GAPS AND MO	NITORING NEEDS		
EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters		
MONITORING RECOMMENT	PATIONS		onitoring should be scheduled to determine its at mine sites in this watershed once d.

THREE R CANYON From 312835 / 110 4619 to	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
312827 / 1104712 (intermittent flow)	A&We – Impaired PBC – Impaired FC Inconclusive AgL Impaired	Category 4A Not attaining	Cadmium, copper, zinc, and pH	TMDL completed in 2003. Need to implement improvements at mining sites.

SITE NAMES ID #	AGENCY PURPOSE	SAMPLING DATE: 01/11/200	0	
DATABASE #		NUMBER AND TYPES OF SA	MPLES	
		Metals	Nutrients - Related	Other
Below uppermost spring SCTHC003.83 100872	ADEQ TMDL	1 total and dissolved metal sample: Beryllium, cadmium, copper, and zinc	pH – 1 sample	

EXCEEDANCES			
POLLUTANT	STANDARD UNIT DESIGNATED USES	DATES EXCEEDANCES	DESIGNATED USE SUPPORT SUPPORTING EVIDENCE AND COMMENTS
Copper	500 μg/L – AgL 1300 μg/L – FBC	01/11/2000 – 50,000 μg/L	Remains impaired – Exceeded in only sample collected during this assessment period. (Binomial)
Copper (dissolved)	8.7 µg/L at 63 mg/L hardness A&W acute	01/11/2000 – 49,000 μg/L	Remains impaired – Exceeded in only sample collected during this assessment period.
Cadmium (dissolved)	2.6 µg/L at 63 mg/L hardness A&W acute	01/11/2000 – 47 μg/L	Remains impaired – Exceeded in only sample collected during this assessment period.
Zinc (dissolved)	79 μg/L at 63 mg/L hardness A&W acute	01/11/2000 – 1400 μg/L	Remains impaired – Exceeded in only sample collected during this assessment period.
рН	<6.5 SU A&Ww, FBC, AgL	01/11/2000 – 2.9 SU	Remains impaired – Exceeded in only sample collected during this assessment period. (Binomial)

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters	Insufficient monitoring events	
MONITORING RECOMMENI	DATIONS	once improvements are comple	ovements at mine sites in this watershed

THREE R CANYON From 312827 / 1104712 to	USE SUPPORT	OVERALL ASSESSMENT	POLLUTANTS CAUSING IMPAIRMENT	IMPAIRMENT STATUS
Sonoita Creek (ephemeral segment)	A&We – Impaired PBC – Impaired AgL – Impaired	Category 4A Not attaining	Cadmium, copper, zinc, and pH	TMDL completed in 2003. Need to implement improvements at mining sites.

SITE NAMES	AGENCY	SAMPLING DATE:			
ID # PURPOSE DATABASE #	NUMBER AND TY	PES OF SAMPLES			
	Metals	Nutrients – Related	Other		
No current data					

EXCEEDANCES NEEDING MORE SAMPLES TO ASSESS	MISSING CORE PARAMETERS	MISSING SEASONAL DISTRIBUTION	DETECTION LIMITS NOT LOW ENOUGH
	Insufficient core parameters		
MONITORING RECOMMENDATIONS		Low Priority – Collect samples during critical conditions determine effectiveness of improvements at mine sites in this watershed once improvements are completed.	
		Collect missing core parameters to represent at least 3 seasons during an assessment period.	